



ITEM FOR ZONING AND PLATTING COMMISSION

BOARD MEETING

DATE REQUESTED:

September 21, 2010

ADDRESS

OF PROPERTY:

4709 Highland Terrace

NAME OF APPLICANT:

Jim Einhaus, 784-7277

David Weekley Homes

PDR/CITY ARBORIST

STAFF:

Keith Mars, 974-2755

keith.mars@ci.austin.tx.us

ORDINANCE:

Comprehensive Watershed Ordinance (current Code)

REQUEST:

Retroactive variance request from Land Development Code 25-8-

641 to remove/impact a Heritage Tree

STAFF RECOMMENDATION: No recommendation

REASONS FOR

Variance is being requested retroactively

RECOMMENDATION:





MEMORANDUM

TO:

Betty Baker, Chair

Commissioners of the Zoning and Platting Commission

FROM:

Keith Mars, City Arborist Program

Planning and Development Review

DATE:

September 21, 2010

SUBJECT:

4709 Highland Terrace

REQUEST:

Retroactive variance from LDC 25-8-641 - Impacts to three Heritage

Trees.

Area Description

4709 Highland Terrace is a residential lot located near 45th street and Mopac. A single-family residence, driveway, and access pathway is currently being constructed.

Account of Events

On November 13, 2009, a Tree Ordinance Review Application (TORA) was approved with conditions for 4709 Highland Terrace (Exhibit 1). The tree permit contained the the following conditions: (1) the driveway near the neighboring 36" and 26" diameter at breast height (dbh) Live Oaks (Quercus fusiformis) was to be established above grade and in the location of the existing driveway; (2) water and wastewater lines were to be established at the center point of the lot to avoid critical root zones; (3) ten inches of trees to be planted on site; (4) an 8" mulch layer over the root zone was to be applied and tree fencing was to be established and maintained; (5) provide a receipt for remedial tree care from a certified arborist; and (6) no impacts are permitted within the ½ critical root zone of all trees.

On August 3, 2010, City Arborist staff performed a site assessment after being contacted by the residential tree inspector regarding impacts to protected trees at 4709 Highland Terrace. Upon assessment of the site, staff observed impacts to four trees on site and two on the neighboring property at 4711 Highland Terrace. As a result of excavation and forming up a sidewalk, non-code compliant impacts to a 40" Live Oak (Tree #1) resulted in extensive damage to root structure and removal of root mass (Exhibit 2). Additional damage to root structure and loss of root mass resulted from preliminary grading work done for the driveway. The driveway was not being installed in the location dictated by



the TORA and, thus, was closer to the 40" Live Oak (Tree #1) than what had been approved (Exhibit 3). The noncompliant shifting of the driveway also resulted in further encroachment into the critical root zones of the neighboring 26" (Tree #2) and 36" (Tree #3) Live Oak trees at 4711 Highland Terrace (Exhibit 4). Further violation occurred with temporary fill material, debris, and a temporary bathroom facility were all located within the ½ critical root zones of two 19" Cedar Elms (Trees #4 and 5) (Ulmus crassifolia) and a two stem 30"x19" Live Oak (Tree #6). An additional violation was the absence of tree protection fencing for the 40" (Tree #1) Live Oak. Of the six trees impacted by construction activities, the 40" Live Oak (Tree #1) on the subject site and the 26" (Tree #2) and 36" (Tree #3) on the neighboring property were impacted beyond what code allows. The 40" Live Oak (Tree #1) sustained extensive root damage and removal of root mass while the 26" (Tree #2) and 36" Live Oaks (Tree #3) sustained minimal impact from approximately 2.5" of cut into the critical root in preparation for forming the driveway.

Staff contacted the representative for David Weekly Homes to inform them of the violations and communicated that a certified arborist was needed immediately to (1) assess the impact to the trees, (2) develop and implement a remediation plan for the four trees onsite that were impacted and the two trees on 4711 Highland Terrace, and (3) remove the fill material, debris, and other objects from the critical root zone of all trees. By August 6, 2010, the fill material and sidewalk forms had been removed from the site, albeit using machinery rather than by hand. On August 8, 2010, the certified arborist sent an invoice detailing the remediation work that had been performed, including root pruning, subsurface injections for root fertilization, and soil treatment via soil aeration and adding organic material to the upper soil layer (Exhibit 5). The sidewalk has been abandoned and the applicant has filled in the sidewalk area with a topsoil and compost mixture (Exhibits 6 and 7).

Since this time City Arborist staff informed the applicant that a retroactive variance must be requested and have worked with the applicant to bring the driveway location and sidewalk excavation into compliance. The driveway location has been shifted to avoid the ½ critical root zone (20' from cross-sectional center point of 40" Live Oak (Tree #1)) (Exhibit 8). The applicant is also proposing to use decomposed granite as the driveway material for the surface area that occurs within the ½ critical root zone of the neighboring 26" (Tree #2) and 36" (Tree #3) Live Oaks. Decomposed granite will assist with porosity over the root zone allowing for additional water uptake. The current proposal locates the driveway approximately 10' further away from the 40" Live Oak (Tree #1) than the driveway location permitted on November 13, 2009. The current proposed driveway encroaches no further into the critical root zones of the neighboring 26" (Tree #2) and 36" Live Oaks (Tree #3) than what was permitted in November 13, 2009, regarding reuse of the existing driveway footprint.

Tree Evaluation

40" Live Oak (Quercus fusiformis) (Tree #1)-

The initial site assessment after the impacts occurred revealed extensive damage to root structure and reduction of root mass (Exhibit 9). Cutting and forming-up the sidewalk



had resulted in encroachments within three feet of the subject tree. Further, approximately 2.5' of fill material had been placed around the root collar of the subject tree. It was also apparent that machinery had severed 3-6" diameter anchoring roots (Exhibit 10). The severed roots had also been ripped rather than cut resulting in further subsurface damage. Additional damage and removal to root structure resulted from shifting the driveway closer to the subject tree in violation of the approved tree permit that stated that only the existing driveway location could be reused. Regarding the aerial parts of the subject tree, there appeared to be no bark or vascular tissue damage and the crown appeared to have not been impacted. Extensive root damage has occurred to the subject tree resulting in a high degree of uncertainty if the subject tree can recover.

26" and 36" Live Oaks (Quercus fusiformis) (Trees #2 and 3, respectively) on neighboring property-

The subject trees sustained ½ critical root zone impacts from the shifting of the driveway location to the property line (Exhibits 11 and 12). It appears the existing turf grass had been scraped approximately 2.5" in preparation for shifting the driveway to a location that was in violation of the November 13, 2009, tree permit. Root damage to the subject trees was minimal. Only small diameter (0.125"-0.250") roots were disturbed. Regarding the aerial parts of the subject tree, there appeared to be no bark or vascular tissue damage and the crown appeared to have not been impacted. Minimal root impacts occurred to the subject trees. Thus, there is a high degree of certainty the trees can recover from the impacts.

Variance Request

The applicant is requesting a retroactive variance for encroachments that occurred in the ½ critical root zones of three Heritage Trees (LDC 25-8-641). The variance is being brought forward as means of enforcing the Heritage Tree Ordinance.

Recommendations

No recommendation is provided by staff. The reasons are two-fold. One, since the impacts have already occurred findings of fact cannot be met for staff to recommend approval for the variance request. Second and conversely, staff does not wish to recommend denial of the variance since doing so would not resolve the variance if it is denied. If the variance was denied by the Environmental Board and Land Use Commission staff would take the case to municipal court to seek restitution, though this is outside of staff control and is at the discretion of the judge. Given the impacts have already occurred and the variance is being brought forward as means of enforcement, staff has prepared the following list of conditions for the Environmental Board and/or Zoning and Platting Commission to consider if the variance request is granted. The applicant has agreed to all of the conditions.

1. For the 40" Live Oak (Tree #1), 100% diameter (i.e., 40") of mitigation is required at the time of permitting in the form of payment into the Urban Forest Replenishment Fund for a total of \$3,000. 200% mitigation (i.e., 80") of mitigation is required to be held in a bond plus 15% administrative costs for a



- total of \$6,000 for the bond and \$900 for administrative costs. The bond will be retuned after five years if the tree has sustained the impacts as determined by the City Arborist.
- 2. A five-year tree maintenance plan prepared and implemented by a certified arborist for the 40" Live Oak (Tree #1) prepaid by the builder and transferred to the owner. The plan is to be administered semi-annually and reported to the City Arborist
- 3. A three-year maintenance plan prepared and implemented by a certified arborist for the 26" and 36" Live Oaks (Trees #2 and 3, respectively) prepaid by the builder and transferred to the owner. The plan is to be administered semi-annually and reported to the City Arborist.

If you need further details, please feel free to contact me at 974-2755.

Keith Mars, City Arborist Program Planning and Development Review

City Arborist:

Environmental Officer:

Michael Embes

Patrick Mumby



Planning and Development Review Department Staff Recommendations Concerning Heritage Tree Variances

Application Address

4709 Highland Terrace

Size and Species of Tree(s): 40" Live Oak, 26" Live Oak, and a 36" Live Oak (Quercus

fusiformis)

Reason for Request:

Retroactive variance request for non-code compliant impacts to

three Heritage Trees

Land Use Commission variance determinations for a requirement of Section 25-8, Subchapter B, Article 1 of the City Code relating to tree and natural area protection.

Section 1 - Approval Criteria

1) The requirement for which a variance is requested prevents a reasonable access to the property.

No.

- 2) The requirement for which a variance is requested prevents a reasonable use of the property. No.
- 3) The tree presents an imminent hazard to life or property and the hazard cannot be reasonably mitigated without removing the tree.

No.

4) Is the tree dead?

No.

5) Is the tree diseased? If so, is restoration to a sound condition practicable or can the disease by transmitted?


No.

- 6) For a tree located on public property or a public street or easement, the requirement for which a variance is requested prevents:
 - a) the opening of necessary vehicular traffic lanes in a street or ally, or
 - b) the construction of utility or drainage facilities that may not feasibly be rerouted.

NA.

7) The applicant has applied for and been denied a variance, waiver, exemption, modification, or alternative compliance from another City Code provision which would eliminate the need to remove the heritage tree, as required in Section 25-8-646 (Variance Prerequisite).

No.



No. The variance request is a means of enforcement for non-code compliant impacts that have already occurred to three Heritage Trees. Therefore, findings of fact cannot be met since the impacts have already occurred.

Reviewer Name: Keith Mars, City Arborist Program

Reviewer Signature: Neth Mars

Date: 09/02/2010

Findings of Fact: 4709 Highland Terrace Tree Permit #2009-112903 TP

Applicant's Findings

10/1/09	David Weekley Homes applied for Building Permit through City of Austin prior to submittal of Tree Permit application. Property Owner, Zahi Kaskas and/or their real estate agent, Dana Twombly, communicated to David Weekley Homes that they were In the process of making application for Tree Permit application on their own.
10/6/09	Original Tree Permit Application made by property owner and real estate agent.
10/7/09	Tree Permit application marked as "Statutory Denial" with comments, "Provide plan of proposed development, showing surveyed location of all 8 protected size trees, with respect to development." Also, requested at bottom of form that a tree survey with meets and bounds be provided.
10/14/09	Building Permit approved / issued
11/13/09	Tree Permit requirements re-submitted with site plan showing driveway being moved to overlay on original driveway that was left after tear down. Tree Permit was approved by Jim Gobel with comments, "New driveway near 36" & 28" on adj property to be established above grade & In old driveway locations. Water & W/W lines to be established center of lot. Additional requirements below." (see Tree Permit approval for requirements checked)
11/16/09	New/Revised site plan approved by the City of Austin (Building Permit Dept.)*
11/20/09	Start Construction
7/16/10	Driveway pre-inspection failed
7/26/10	Jim Gobel called Mike Huus with David Weekley Homes and told him we had violated conditions of Tree Permit
7/27/10	Keith Mars contacts Jim Einhaus with David Weekley Homes about addressing what treatments need to happen to protected trees by certified arborist on the property.
8/6/10	All treatment work completed by Certified Arbor Care on specificed trees as follows:

Deep root fertilize all trees on site

1.

- 2. Root rejuvenation treatment for 40" Live Oak (including root prune and seal)
- 3. Dead wood prune Elm near the house
- Follow up Deep Root Fertilization on 40° Live Oak completed on 8/10/10

8/10/10 David Weekley Homes paid Certified Arbor Care for work completed

8/18/10 Mike Huus and Jim Einhaus with David Weekley Homes meet Keith Mars, Jim Gobel, Michael Embesi, and Joe Almazan at City of Austin to discuss resolution and options.

*David Weekley Homes applied for the Building Permit for 4709 Highland Terrace independity of the property owner applying for the Tree Permit. As a result, the site plan that was originally submitted with the Building Permit application was approved before the Tree Permit was approved. Because the Tree Permit approval required a revision to the site plan before it could be approved, there was a second approved site plan that was stamped by the City of Austin. When construction began, the Builder was unknowingly working off of the original approved site plan as opposed to the second approved site plan which showed a different driveway location thus causing the Issue at hand.

In preparing for the new driveway, contractors removed existing driveway, and prepared for the sidewalk and new driveway/turn around area by scraping off existing grass, approximately 2-3" in depth. As a result, per Certified Arbor Care, the following observations were made:

Overall Observations:

- 40" Live Oak on left side of driveway: sever root cuts, exposed roots, and excessive fill present.
- 28" and 36" Live Oaks in neighbor's yard; have minimal impact from construction.
- 18" Elm near home: Root damage from house construction.
- 18" Elm and 30" Live Oalc minimum damage.
- Most trees on site have excessive fill

Once the arborist's report was received and reviewed by the City of Austin, David Weekley Homes had all the recommended treatments completed as expeditiously as possible. Additionally, as recommended by the City of Austin, David Weekley Homes backfilled with compost mulch and topsoil the areas that had been scraped for the proposed sidewalk and driveway.

In summary, we are not asking for a variance to remove any trees. David Weekley Homes agrees to pay into the sidewalk fund in order to avoid building a sidewalk in the ½ critical root zone of the 40" Heritage Live Oak at the front left corner of the lot. Additionally, upon meeting with Jim Gobel at the lot last Thursday, 8/26/10, we have come up with a plan to keep the driveway out of the




½ critical root zone of the 40" Live Oak as well. The plan is to move the driveway approach to the south approximately 9-10 ft. This way we keep the entire approach and driveway out of the ½ critical root zone of the Live Oak. Lastly, we propose using decomposed granite in the part of the driveway that encroaches the neighbor's (North side) 26" Heritage tree's ½ critical root zone. The granite will be supported with steel trim on the outside edge of the ½ critical root zone of the 26" Heritage tree.





Directions to 4709 Highland Terrace, Austin, TX 78731 5.8 mi – about **11 mins** – up to 25 mins in traffic





1. Head west on Barton Springs Rd toward S 1st St	go 197 t total 197 t
2. Turn right at 8 1st 8t About 2 mins	go 0.4 m total 0.5 m
3. Sharp left at W 1st St/W Cesar Chavez St About 4 mins	go 1.3 m total 1.8 m
4. Take the ramp onto TX-1 Loop N About 3 mins	go 3.3 m total 5.1 m
5. Take the 45th St exit	go 0.1 m total 5.3 m
6. Turn left at W 45th St About 1 min	go 0.2 m total 5.5 m
7. Continue onto Highland Terrace	go 0.2 m total 5.6 m
8. Turn right at Perry Ln	go 85 f total 5.7 m
9. Turn left at Highland Terrace Destination will be on the right	go 0.1 m total 5.8 m
4709 Highland Terrace, Austin, TX 78731	

These directions are for planning purposes only. You may find that construction projects, traffic, weather, or other events may cause conditions to differ from the map results, and you should plan your route accordingly. You must obey all signs or notices regarding your route. Map data ©2010 Google

Directions weren't right? Please find your route on maps google.com and click "Report a problem" at the bottom left.

Exhibit #1

,4.P




Tree Permit


Planning and Development Review Department
One Texas Conter, 505 Borton Springs Road, 4" Boot
Phone: (512) 974-1676
Page (512) 974-3010


Phone: (512) 974-1676 Fac: (512) 974-3010 Empl: Michael Embedi@cl.sustin tx.us Websitz: www.cl.austin.tx.us/rees	_
Application request (specify all that apply): Dingle Family Home / Duplex or Char	
Ramoval of a protected-size tree;	
Davelopment exceeding allowable standards for encreachment in the tree's critical root zone;	
Removal of more than 30% of a tree's crown.	
* Rolor to Lond Development Code (25-5-801) and Environmental Caleria Manual (Section 5, App. F) Applicant understands that all treasures may be under the health of the tree and that approved of this application down not proceed towards investible in results.	,
Address of Property (Including sip code): 4709 Highland Tewace Libin TX71 News of Owner or Authorized Agent 7 diskas kas or Dana Two willy	70
1	
Building Permit Number (if applicable): [Apply applicable to to the pariet (assess) Telephone # 417-073 Fex #: 328-3522 E-mail: Qua @ 10 mg/15 Pariet ex-	
Telephone # 417-0736 FEE # 328-3922 E-mail dana @ Turnquist party ex	5 9
Type of Tree Bole - Live Cole Location on Lot FRONT Right	
Type of Tree: GOLC - Live (M.L. Location on Lot: FRONT RIGIL! Trunk size at 4 % feet above ground; chaunterway (Suches around) 30° or demanter.	
General Tree Condition: Roov	
Report tor Receiped Lement for building home.	
Owned Authorized Agent Significans Date Date	
 Attach an annial drawing that includes the location of the tree and the proposed development, including driveways, using lines, inigation systems, etc. This application is reviewed for tree impact only; not for zoning or other applicable regulations. The application may be annalled, faxed, or delivered to the above address. Payment (\$25 check to the City of Austin) must be made prior to City personnel completing this application. No less is required for dead or diseased trees. 	
V	
TO BE COMPLETED BY CITY ARBORIST PERSONNEL	
Approved Mapproved With Conditions* Denied Statutory Denial (more information required)	
Commenter PRIVEWAY NEAR 36' 178 ON ADJ PROPERTY TO BE ESTABLISHED AGOVE	
GIMP ELLOCO DIVENMY DEATON. WATER! WIN THES TO BE EGTHENSIEN COURT	
of lot. ADDITIONAL PEQUIREMENTS BELOW	
*Conditions of Approval: None; V As described within Arbortat Comments (see above); and	
N	ı
A Elm, Mountain Leurel) on the lot prior to obtaining a Certificate of Occupancy (minimum 2-inch trunk diameter).	
Applicant agrees to plant _{// collect inchise, container grown, City of Austin Class 1 trees (Le. Live Oak, Ceder	
fencing (chain-link, five-feet in height) throughout the project duration. [X] Provide a receipt for remedial tree care and / or any required pruning as performed by a certified arborist.	
M Provide a receipt for remediar use case and / or any required pruning gas performed by a calined alborial. The impacts are permitted within the tree % critical root zone (see EGM 3/5-2), including penching for utilities.	
1 /// 11/2/09	
Commelant Committee Date City Arterial Chronism Date	

David	Weekle	y Hon	ies 🛼	dry Hagnes, Jan. 1998	R	1 B/Z3/09 ADG 2 10/21/09 ADG
Drawing No.	PLAN	Orgwn By: DRN		Scale: SC ALE	V.	3 10/28/09 ADG 4 11/09/09 ADG

FINAL 10-28-09 PROPERTY ZONING: SF-3












Exhibit #5



September 3, 2010

Mike Huus David Weekley Homes

RE: 4709 Highland Terrace

Mike:

As Per my site visit at 4709 Highland Terrace in Austin, Texas; below are my observations and recommendations. These observations are based on my site visit, experience, and opinion. Please do not hesitate to contact me with any questions or concerns.

Overall Observations:

- 40" Live Oak on left side of drive way: sever root cuts, exposed roots and excessive fill present.
- 28" and 36" Live Oaks in neighbor's yard: have minimal impact from construction.
- 18" Elm near home: root damage from house construction.
- 18" Elm and 30" Live Oak: minimum damage.
- Most trees on site have excessive fill.

Recommendations:

- A deep root stimulator should be applied to all trees on site.
- All excessive fill dirt should be removed from the base of the tree.
- Prune and seal all exposed roots on the 40" Live Oak.
- The 40" Live Oak should undergo root rejuvenation treatment.
- All dead wood should be removed from the 18" Elm near the house to encourage growth.
- The 40" Live Oak should have a follow up fertilization one year from the initial treatment.

Deep Root Fertilization: The trees should be deep root fertilized with Plant Health Care Mycor-Injectable and applied via subsurface high pressure soil injection at a rate less than or equal to 100-150 PSI using a soil probe. Application rate was 2 liters per injection site on a 3 foot grid beneath the drip line of the trees.

Root Rejuvenation: Root rejuvenation uses an air spade to aerate the soil and incorporate organic material into the upper level of the soil profile, creating a conducive environment for the tree roots to grow.

Should you have any questions or concerns please feel free to contact me on my mobile 512.203.3770 or through email: lee@certifiedarbor.com.

Sincerely.

Lee Evans President

Certified Arbor Care, Inc.

Heetrong

ISA Certified Arborist TX-1339A
Texas Oak Wilt Certified TOWC-0024




phone 512-571-5755 fax 512-522-5272 p.o. 90x 1965 round rock, TX 78850 www.carlifiedarbor.com











SIDE VALL ARTICULATION

LEGAL DESCRIPTION

HIGHLAND PARK MEST LOT 6, BLOCK 'D' 4709 HIGHLAND TERRACE

FAR CALCULATIONS

1 3 clar my imposite titlette.	
TOTAL SROSS PLOOR AREA	2,716,00
ESARASE (attached)	120,00
(Shistreet 200,00 sq. It for all-street parting	+300 <i>0</i> 0
TOTAL GROSS PLOOR AREA	3,044,00
TOTAL GROSS GROSS AREA OF LOT	
PLOCE AREA RATIO	15,425
from OAS of ick creek	

BUILDING COVERAGE

DVILDING	00 124 02	
LOT SQ. FT.	18,853.72 10	% 00.00
LIVING AREA (o/c)	2,176.00	
SARASE (attached)	520.00	
COV. PATIO	144,00	
COV. PORCH	37.00	
TOTAL BUILDING COV	ERA68541.00	PLO18
MPER	vious cov.	
	. 22-1	

TOTAL BUILDING COV. 5547.00

DRIVENAY 1244.00 A/C PADS (2 e 4.0) 18.00

TOTAL IMPERY. COVERAGE 4,054.00 29.77%



SITE PLAN

56ALB 1" + 50-0"

