#### ZONING CHANGE REVIEW SHEET

CASE NUMBER: C14H-2010-0039

HLC DATE: September 27, 2010

October 25, 2010

PC DATE:

December 14, 2010 January 11, 2011

APPLICANT: Historic Landmark Commission

HISTORIC NAME: Bradford Nohra House

WATERSHED: Waller Creek

ADDRESS OF PROPOSED ZONING CHANGE: 4213 Avenue G

ZONING FROM: SF-6-NCCD to SF-6-NCCD-H

SUMMARY STAFF RECOMMENDATION: Staff does not recommend the proposed zoning change from Townhouse-Condominium Residence - Neighborhood Conservation Combining District (SF-6-NCCD) to Townhouse-Condominium Residence - Neighborhood Conservation Combining District - Historic (SF-6-NCCD-H) Combining District zoning. Staff recommends release of the demolition permit. The 1908 wood-frame house was completely obliterated when the house was stuccoed over and all of the windows were replaced with jalousie windows. A test for whether a building retains its integrity of materials and design is whether a figure from the historic period of the house would recognize it today, and staff believes that that house has lost its historic wood-frame appearance to such an extent that the house associated with the Bradfords has been completely lost. To qualify as an individual landmark, the Land Development Code states that a structure must maintain its historic appearance, and this house clearly does not. Therefore, while recognizing that the house has significance to the Hyde Park neighborhood groups who have pushed constantly for its preservation, the house does not qualify as a historic landmark because of the massive changes to its exterior. The current owner has no plans for restoration of the house because of its deteriorated state, and staff cannot recommend a building for landmark designation without a restoration of its historic appearance.

HISTORIC LANDMARK COMMISSION ACTION: September 27, 2010: Initiated a historic zoning case. Vote: 6.0 (Leary absent). October 25, 2010: Recommended a zoning change from SF-6-NCCD to SF-6-H-NCCD. Vote: 5-1 (Leary opposed; Hansen absent).

PLANNING COMMISSION ACTION: Postponed to January 11, 2011 at the neighborhood's request. Vote: 6.0 (Chimenti, Reddy, and Hernandez absent).

**DEPARTMENT COMMENTS**: The house is listed as potentially contributing to the Hyde Park National Register Historic District.

CITY COUNCIL DATE / ACTION: December 16, 2010: Postponed to January 13, 2011 at staff's request due to the postponement by the Planning Commission.

**ORDINANCE READINGS:** 

ORDINANCE NUMBER:

CASE MANAGER: Steve Sadowsky

PHONE: 974-6454

#### NEIGHBORHOOD ORGANIZATION:

Cl

Hyde Park Neighborhood Association

#### **BASIS FOR RECOMMENDATION:**

The house does not maintain its historic appearance, and staff cannot recommend a house that does not maintain its historic integrity to this extent. The original frame house has been stuccoed; all the original windows have been removed and replaced with jalousie-type windows; the sleeping porches on the south side of the central block have been enclosed, and an unsympathetic non-historic addition has been built to the southeast of the main house at an odd angle. The house is not contributing to the Hyde Park National Register Historic District with all of these modifications and therefore does not maintain sufficient integrity of materials and design to qualify as a historic landmark.

The Hyde Park Neighborhood Association has been extremely diligent in researching the property and has found several photographs from the early part of the century which show the original appearance of the house; the photographs confirm the vast difference in the historic and current appearance of the house.

#### Architecture:

The building was originally a two-story frame house with a two-story porch wrapping around the front and south side. Full-length columns embellish the façade, with jalousie windows arranged two on each side and six above the simply pedimented door. The house is capped by a hipped roof with dormers on the north and south sides. A two-story addition is set at an unusual diagonal angle off the back with a style reminiscent of the 1940s, including metal-frame windows and a rooftop with an open metal railing. It is difficult to assess exactly when these changes were made - the 1922, 1935 and 1962 Sanborn maps all show the structure with the two-story wrap-around porch but without the angled addition.

#### Historical Associations:

The first known owner of the house was William A. Stewart, a real estate man, as evidenced by the listing in the 1909-1910 city directories. By 1912-13, the house was occupied by the Bradford family, who lived here for over 30 years. Clyde A. Bradford formed and become the president of Bradford-Dorflinger Company (later, the C.A. Bradford Company), which sold paints, oils, varnishes, and wall papers at 705 Congress Avenue.

Dewey C. Bradford was born in 1896 in Round Rock, was a former heavyweight boxer, a chariot driver, a football player for the U.T. Longhorns and served in the U.S. Marines during World War I. As a youth, he was interested in acting and spent time in Hollywood before returning to assume duties in the family business. He was also a patron of the arts, having introduced Porfirio Salinas, Charles Berkeley Normann and G. Harvey Jones to the art world. He assisted President Lyndon Baines Johnson and Lady Bird in selecting paintings for the White House. The Country Arts Store Gallery, located at 1304 Lavaca, was one of his businesses. Dewey Bradford lived in this house with his parents in the 1920s, and then he and his wife Josephine lived here until around 1944. The present owner purchased the property around 1944 and has lived here ever since. Helen Nohra, the current owner, is the widow of Charles Nohra. Charles Nohra was a restaurateur who owned or managed several cafes downtown. The Nohras lived here in the late 1940s, then rented the house out in the early 1950s; Helen Nohra operated the Parkview Nursing Home at 56 East Avenue, where she lived for several years, as well as the Shady Oaks Nursing Home on S. 1st Street before returning to this house.

PARCEL NO.: 02200614060000

LEGAL DESCRIPTION: Lots 1-5, Block 20, Hyde Park Addition No. 1.

CI 3

ANNUAL TAX ABATEMENT: \$2,715 (owner-occupied); city portion: \$1,358 - no AISD or

ACC participation.

APPRAISED VALUE: \$541,013

PRESENT USE: Residence

**CONDITION**: Poor

#### PRESENT OWNER:

Helen Nohra Sylvia Dudney, Trustee 4211 Avenue G Austin, TX 78751-3815

DATE BUILT: ca. 1908


ALTERATIONS/ADDITIONS: Several additions; the house has been covered in stucco, the windows are not original, and the gable on the south has been removed. The second story porch has been enclosed and is shown as a wrap-around porch by the Sanborn maps rather than a side porch. An odd diagonal addition appears to have been added in the 1940s.

ORIGINAL OWNER(S): William A. Stewart

OTHER HISTORICAL DESIGNATIONS: None.

Location Map





#### **HISTORIC ZONING**

ZONING CASE#: C14H-2010-0039 LOCATION: 4213 AVENUE G

GRID: K25

MANAGER: S.SADOWSKY

OF ADAM TO

This map has been produced by the Communications Technology Management Dept. on behalf of the Planning Development Review Dept. for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.



9329 LIGHTWOOD LOOP AUSTIN, TEXAS 78748 OFFICE: (512) 282-0455 FAX: (512) 282-2029

#### **PROPERTY INSPECTION REPORT**

Prenared For:	Dufney
riginina i oi,	(Name of Circuit) (Report Not Transferable to any other buyer without company a consent)
	4213 Ave. 6
Соповілініў:	(Addies or Other Identification of Inspecies Property)
175.	Contt Penns 1959 I.i. 6 2007
By:	Scott Freeze 2363 July 6, 2007   Plama and Literate Number of Inspector (Date)
	708
	Namy, Learne Number and Signature of Sporagging Inspector, it coupers)
The inspection up of cland must indicate which datus. This report is inspended to item to unclose, you should it is recommended must disclosure, providus may and approximent. You should represent the company under the company under the company under the company.	perly listed above must be performed in compliance with the basis of the Taxas Real Estate Compression (TREC). Borns which the present and restite at the trate of the repectors, and all of the equipment is used about the remain inclass. The responsibility of repetit or are not tended or regist or are not tended in the same required by TREC rules. provide you with information concerning and will report on all applicable time required by TREC rules. provide you with information concerning the conductor of the property at the arms of inspection. Please read on report carefully, if a required definition in your obtains as much healthy, rule is another to concerning this property. This historical intormation may include copies of any self-vention or engine and reports property are provided to the or by refocation comparies, manageal impectation destinations, lenders, made in a provided to the specific position or other such historical base have taken place at this indirection and the careful subcommy readers of this indirection and
tim is facilised dispective.	a perform an inspection to might their specific meets and to obtain curries informative concerning this property
	ADDITIONAL INFORMATION PROVIDED BY INSPECTOR:
	CONTRACT - READ BEFORE SIGNING - SUBJECT TO BINDING ARBITRATION
ONLY as at the day of intent	inual perpany condition inspection for a FirmAS installed and organized only of accessible times, and is a subjective report of the organized process and respective times or conditions of the process of new process of new process of the process o
net or so writte takes work to	tied nomblered hinch are concerned of rocure disascemble, not high employed level level nast induced stied object in combined. No engre Morned Design operation with the societ of the engresion of AG wind study was an experience <u>(interest) entre bed</u> presented for Her dix occupy the 1981, he object to safety sacrating so design from the highestors.
of detection of the participation of the participat	is with insued to the ferm intended. Where A comment is made, we recommend and regimes to contain a dust had spooland to answer education to the contained of the design and in a part of the contained of the contained in the contained of the contained of the contained in the contained of the contained in the contained in the contained in the contained of the contained and the contained in the contained and the larger of the based of the contained and the cont
Precision funded to agareta withe ended to all energies	and Burge agree is binding whitehold is selde and repower. Duyen by each have but the culture entries transported dealers of control of \$25 billing not extended at temperature
There seed uncertand and	IES, EXPRESCIO HOR (LIPELEE). And country the Eurymagnes to block Francisco one was in lette to come renderative before mixing replaced to convenients. By according or using the recording on using the recording on using the recording on the pupils of the superstay agree to above terms. Buyer ogreen to wrife an even of purchase for moving agree restances and as BEFORE they contribute end evenish.
Bayer X Orph	DIMERING OME 7/9/27
imi mont not wa	TO MATHOUR SYSTEM AT ORCY
of the states about the section of	to mappet applit systems. Buyer agreen to have an inspection & records check by a sandarian as well as a pumpout balors movern, ngor propies loves 1946 time charved only et apparation. If Alland Stolet systems and chartes! If Alland solved if arrives base \$50°, to 196° Frankin model - 4] Vie de nor ethnik forminne we tastaten ladvage. If Ne de not ethnik eventure at Mark. As frankinsk por chartes Frankin of swed not archested. It Sewal had, authorising a Discolet had been an expecting of the premisions are chartest.
the property but as not she not an despite despited in	infacted to true roper. Nead then very Calatrily, Eris report may not be complete without the abustralants. If an nem is paction, the "Ni" column will be shocked and an anplanation is necessary. Comments may be provided by the inspector whether reved of repair.
I M NP R	Inspection item
ngs/steps leani d is wet/moist dum (attached)	Unispected Number Inspected NP-Net Present Rangi Functioning or in Need of Repol- 1. STRUCTURAL SYSTEMS A. Foundations if all claw's pace areas are not extended, provide an espapation ) Converse (As combons as mendancy): is settling especially at the left side, suggest an engineers report; porting in towards bouse (drains water that way), little to no ventilation under under house from plumbing leaks/rain, some white rot occurring, see foundathin house is primarily pier and beam with a slab addition to back left (family room) slab and check for crocks
0001	B. Grading and Drainage
	Carryons, the sides of house and it the front some all the side

and around additions slab (will cause slab to settle)

Report transferation ..... \_page2 telespected. Plt-flot Inspected. APpliet Present. ReNot Functioning or in Need at Repair NI NP R Inspection Beni wood roof trid water dandged at more areas around roof edge still, shingles form offat the front right corner of the upper roof (can see through to attic), water pooling at flat roof area at the lower front right roof above porch, roof surface wearing out above back right roof deck door area, D. Rood Structure and Affic di the attacker inscreenship, report the method used to respect to comments seal lead pipe flashings at the tops of the plumbing vent pipes at back, railings around upper back right roof not child proofed, reinforce rafter support braces at upper roof + no ridge beam or corner rafter beamy support braces, some caves are water damaged, a sewer wont pipe terminates in th Some wood siding water damaged at upper right enclosed porch, many diagonal cracks in the interior walls of house especially at tub wall tiles, interior walls water stnined/damaged at laundry room (down); note - numerous repairs have occurred at the exterior stucco siding collings water stained/damaged from past bathroom leaks above at laundry/down right kitchon and nt up back left sunroom from past roof leak (all dry now); floors water stained damaged under most hat rooms, floors slope through out house especially at left spartment

O 0 0 00001 (Natorina and Exterior) Commence G. Doors (Interior and Exterior) Comments: lower door frame trim starting to rot at the back left/right and upper right roof occess door, "opair/replace water heater closet door and frame, soveral interior doors open onto staltwell, front door damaged at latch/strlke plate 3 3 3 M. Windows (it is not styles possible to determine if the pane window seas are two ope to drift, adversomens or climate conditions). ;lass broken and many windows especially at metal windows, window slils rotten at the left apt. a/c, many screens are missing, right metal bathroom window rusting out.

1. Finplace/Chimney Comments nnne are functional J. G use J. Porches, Docks and Campers (Attached Commons roter stain at the upper front porch ceiling from past roof leak + howed, lower left front porch column rotten, right side steph railings nor child proofed, front porch slah/stone work broken at m most areas, no hand railing at left entry steps 2398 K. Other Comments. some roof caves are water damaged, roof cave leaks/ water damaged shove the right wooden Roof: Roof; some root eaves are water usuaged, too, the training at back interior stairs; no band railing at back interior stairs; note - bouse bad been divided into 4 apartments in the past with separate kitchens/baths but all were on the same elec./water/gas meters with one central furnace and water heater

a ELECTRICAL SYSTEMS

A Service Entering and Passes Comments
on main breaker, separate ground and neutral wires at all sub elec. pannis off main elec. panel, no ground wire clamp at plumbing pipe, secure inner elec. panel covers, Dushings missing around som wires coming into place panels, some federni pacific elec. problems considered problematic in the 0005 8 Branch Circuits a Connected Devices and Flatures (Report as in need of import the first of ground fault circuit protection where required (Speed & territoring switch on tans not checked. Comments: past and some breakers have been recalled, have a lic. electricism evaluate elec. systems and make repairs where needed, replace all knob and tubEwiring and related outdated outlets and switches whe here needed, there are few to no gf! plugs at kitchens/hath/exteriors, many 3 prong outlets are not grounded, most of the elec. power to the addition out/nock not work, most summer actions and some lights are not grounded above sinks, exterior surface wiring loose/not in conduit at elec. pan and to most window n/c units (some of the wires have insulation coming off), open wire splices under the HEADBER, VENTILATION AND ARE CONDITIONING SYSTEMS (CO detectors recommended), outset and in attic Comments. grounded, most of the elec. power to the addition out/hops not work, most smoke alarms missing/inop A. Mesting Equipment Type and Energy Sources central gas/ gas space heaters central furnace inop. + replace brass gan lines to control valve, do not use gas space heaters (not vented) cap off ail gas jets to space heaters, air supply from inside house B. Cooling Equipment Special Window a/c units

clean all filters , some older models not working properly

Comments.

0 0 0 0 C. Descis and Ventil Comments: clean out right clathes dryer vent pipe/cap, loft dryer vents under house

/ IV. PLUIABRING SYSTEM many of the water lines to all slake/tub-shower faucets have lower water pressure problems/leak/lea at stems/varying water pressures when other faucets are tuned on/clogged water lines and or not working at all, water lines very rusted/corroded and looking to addition, there is a broken water supply line under ground/in slab at addition area, many commodos not flushing properly + bowls are loose on floors at some baths, some tub and sink stoppers inop./missing, no back flow preventers at outsido hose fauceta, some water lines are corroded under house + some starting to loak,

	Roje	4; 20·	ent fo	ca 🏻	76e 3		n d major vines . v
					-	<[n:	pecies Mi-Not Inspected NP=Not Present ReNot Functioning or in Need of Repair
			Et p	4b	R		Inspection Item
bibe	so sat	WE	io: Igb:	074 E 4	s ac i	ak man nto	D. Drains. Wastes. Verms Comments and are very corroded under house (suggest a newer line leaks test), sewer very areas where they were run along the exterior of house and terminate under upper attic (one).  White Meaning Equipment (Paper) is in most of most conditions expectedly, indeed as a pooprised interesting if the content of the conditions of th
			_				water heater (GAS')
supp	ir ly	at	420	00	eq. i	00	e relief line not 18" metal pipe from valve, one 40 gal. water heater t house
	9	Q	1,2	1	9	ē	, Hydro-Therapy Equipment Comments
	<b>*</b> 2	נ	1	J	3	A	PPLIANCES Distrimator Comments Tusted
Olae :	are	dl	sec	enr	ected	I/n	ot working/and or trays were, and run noisy
most	40	πĊ	T T	ior	k	B	. Food Whate Disposer Commons:
none	i wo	rk,	all	1	naeq	g g	Range Hopd Communic TVICE, make sure thay vent outside
serv	ice	ál	1 7	td	ves n	nil	RangesOvensCooklops Company replace brass gas line connectors to stoves where needed
	J	ņ	-2	,	٠	£.	therewave Cooking Equipment Comments
	J	J	Į,		J	F	Trash Compactor Gurarrents
gaș u	u vali	ပ (၂)	t.	er.	s not		Dath-com Exhaust Fans and/or Heaters almostrats ented outside, do not use
	٦	٦	a	1	å	H.	Whole House Vacuum Systems Comments
	4	,i	-			Į,	Garage Door Operators Comments
ok	1	0	7			J.	Open Bell and Chimes Comments
	3	3	J		'/1		TIONAL SYSTEMS Lawn Sprinklers Conneces
	5	4	u	7		Ω.	Summing Pools and Equipment/Spat. Companies
	¥	ū	3			¢.	Outbusdings Conncerts
	ú	ij	3	9		D	Outdobi Cooking Equipment Convincia
	_	9	J	ū		E	Water Wells (A colitain energic is recommended ) Type of Puriti. Submarsible Type of Storage Equipment (pressure land Comments

13 3 3 F. Miscellaneous Commenter

refrigerators not grounded, eave above right wood stairs leaks/rotten at corner there, 4 mitlet box left of elec. panel has no cover/hange from wire/ not mounted and has not off plugs, were the distance of the control of the contro

At this time foundation is supporting the house without unusual or excessive deflections in my opinion and needs no repair except as noted on page 1 of the report. Foundation is 102 years old and does not comply with current code or engineering standards nor should it be expected to. Due to this, another inspector or engineer may say the foundation is defective and needs expensive repair. Ongoing movement of the building will occur causing sheetrock cracks, sticking doors, sloping floors, etc. If this is unacceptable to you, consult a structural engineer for a detailed foundation analysis before your option period expires.

MAXWELL ENVIROTECH INC.

751 LONESOME TRAIL # 300 DRIFTWOOD, TEXAS 78619

**44444444444** Telephone / Fax Number (512) 847-2797

Date: July 24, 2008

Proj. No. 080787 Page 1 of 3

To:

Sylvia Dudney

4211 Avenue G Austin, Texas 78751

Re: IAQ Investigation

4213 Avenue G Austin, Texas

Dear Mrs. Dudney:

Maxwell Envirotech, Inc. performed Phase I Mold Bulk Sampling and Air - O - Celi Total Mold on the above referenced project July 14 and 21, 2008.

#### Inspection Summary

The initial visual inspection found water damage apparently attributable to various plumbing leaks (see photographs attached). The bulk sampling (Quantem Set ID 163971 attached) Samples SD.1-8 showed concentrations of mold in all rooms tested except the 2nd floor porch and north kitchen. The Air-O-Cell Total Mold air monitoring (Quantem Set ID: 164297 attached) showed elevated levels of several genuses of airborne mold in the kitchen (Sample SD-10) elevated 73% the outside air (Sample SD-12) and the living room (Sample SD-11) elevated 185% the outside air. Of particular concern was the presence of genuses (esp. Aspergillus/Penicillium) reported inside that were not present in the outside air.

#### Discussion

The presence of elevated mold in indoor air samples is a signpost of poor indoor air quality and a reason for concern. When disturbed by vibration, air movement or maintenance, etc. the presence of fungal contamination can result in increased episodic exposure. Occupancy of the area is not recommended for persons very young, old, pre-disposed to fungal aeroallergens or otherwise immuno-compromised.

#### Recommendations

The residence cannot be remediated for mold without prior extensive renovation of the structural, plumbing and mechanical systems which are beyond the scope of this report. In addition to the parameters causing the mold problems the facility does not meet code in numerous areas also beyond the scope of this report. It is the opinion of Maxwell Envirothech, Inc. the restoration of the facility to livable space is not economically feasible.

4213 Avenue G (cont)

Proj. No. 080787 Page 2 of 3



## Total Biogerosol Sampling

Total bioaerosol/particulate sampling was performed to identify and characterize general fungal and particulate concentrations. Total bioaerosol exposure is the result of both viable and non-viable airborne fractions. Samples were collected using Zefon Air-O-Cells linked to a vacuum pump calibrated at a flow rate of 15 liters per minute. Indoor collections were made over a 5-minute period. Morphologically distinct fungal components were identified to genus. Fungal spores having a spherical shape between 1-3 microns are reported as Aspergillus/Penicillium-like. Other particulate was identified into general categories of Mycelial debris and fibers when appropriate. All components were individually reported in particles per cubic meter (Part/m3). A total Particle/m3 was provided for each sample site. No scientific peer reviewed research is currently of record that indicates typical and/or acceptable levels for total (culturable and nonculturable) indoor fungal bioacrosols. Case studies published in leading industry journals and papers, generally suggest that total bloacrosols within indoor environments should be below 2000 particles (Part) per cubic meter (m3) and generally 50% of outdoor levels. No individual concentration criterion for these organisms has been established to date. This value is considered to be a "reactionary threshold". The principle fractions of the total concentration are typically due to the presence of Aspergillus I Penicillium-like and Cladosporium components. Concentrations exceeding 2000 Part/m3 and/or having unusual populations of fungi that are not mentioned in the outdoor air should incite some additional level of investigation with respect to a potential bias from prominent outdoor bioaerosols, inadequate air filtration, poor housekeeping, excessive indoor humidity and/or micro-humidity environments, and/or potential indigenous contamination sources. These recommendations are suggested as general guidelines only the author cautions on the indiscriminate use of any bioaerosol data and/or any specific remedial recommendation based solely on bioacrosol findings. Additionally, the >2000 Part/m3 is not intended to represent a threshold value having a medical or health significance with respect to exposure, nor is it necessarily representative of an unacceptable indoor environment. Rather, it is intended to be a "reactionary threshold" to incite further investigation as to the cause(s) of what is considered to be an above average concentration for total indoor bioaerosols.

To date, there is no data that supports a threshold limit or dose / response relationship for exposure to fungal aeroallergens. The Occupational Safety and Health Association (OSHA), The National Institute of Occupational Safety and Health (NIOSH), as well as other occupational health related associations, have not established permissible exposure levels (PEL's), recommended exposure limits (REL's), or other limit values for aeroallergens.

### Bulk / Tape Samples

Tape samples were collected by placing the adhesive surface of clear cellophane tape directly on suspected contamination sites. Tape samples were placed on a standard microscope slide for light

(cont)

4213 Avenue G (cont)

Proj. No. 080787 Page 3 of 3



microscopic evaluation. Tape/bulk samples were analyzed to evaluate and characterize general populations of potential fungal contaminants, as well as, to distinguish active and/or transitory fungal presence. The presence of active fungal growth in an indoor environment is not consistent with the practice of maintaining acceptable indoor environments and/or air quality.

#### Statement of Certification:

The undersigned certify that to the best knowledge and belief:

The statements of fact contained in the report are true and correct.

The reported analyses and conclusions are limited only by the availability of documentation and limiting conditions and are our personal, unbiased professional analyses, opinions and conclusions.

No other warranty either expressed or implied is hereby made.

Our compensation is not contingent on an action or event resulting from the analyses, opinions or conclusions in, or the use of this report.

Scott A. Maxwell is a Texas Licensed Mold Consultant and EPA Certified Inspector & Management Planner and NIOSH 582 Air Monitor, personally reviewed the available documentation and made personal inspection of the site.

1.24.200B

Respectfully submitted.

MAXWELL ENVIROTECH, INC.

Scott A. Maxwell, I.H. - Pres.

**TX#MAC0314** 

SM:vm enclosures



2033 Heritage Park Drive / Oldahoma City, OK 73120 / (405) 755-7272 / Fax (405) 755-2058

# Microbiology Analytical Report

QuanTEM Lab ID 163971

Client:

002

Maxwell Envirotech, Inc.

Date Received: Received By:

07/15/2008 Rachel Molieri

751 Lonesome Trail #300 Driffwood, TX 78619

Analyzed By:

Todd Jelinek 07/18/2008

Account Number:

Date Analyzed: Methodology:

QuanTEM Sample ID

Bulk, Qualitative NonCulturable

001

B000 Project:

MM005

Location:

080787 N/A

AIHA ID Number: 101352

Project No:

N/A 003 004

		002	003	; 004	1	Ì
Client Sample ID	SD.1	SD.2	SD.3	SD.4		
	Results	Results	Results	Results	Results	Results
Alternaria	Present					
Aspergillus	Present					
Cladosporium	Present					
Penícillium		Present		<u> </u>		
Pollen	Present		<del> </del>			
No Mold Detected			×			
Comments:			No Mold Detected	No Mold Detected		

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Approved:

The results taken from your home, building, etc. cannot be interpreted without physical inspection of the contaminated area or without considering the building's characteristics and the factors that led to the present condition. Interpretation of results is the responsibility of the company or individual who

This report shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be used to claim endorsement by AIHA or any other agency of the U.S. Government



2033 Heritage Park Drive / Oklahoma City, OK 73120 / (405) 755-7272 / Fax (405) 755-2058

Client:

# Microbiology Analytical Report

QuanTEM Lab ID 163971

Date Received:

07/15/2008

Received By:

Rachel Molieri

Analyzed By: Date Analyzed: Todd Jelinck

Methodology:

07/18/2008

MM002

Tape, Qualitative NonCulturable

Project:

Account Number: B000

080787

· Maxwell Envirotech, Inc.

Driftwood, TX 78619

751 Lonesome Trail #300

Location:

N/A N/A

AIHA ID Number: 101352 Project No:

			] 101	14154	
QuanTEM Sample ID	005	006	007	008	
Client Sample ID	\$D.5	SD.6	SD.7	SD.8	

	Results	Results	Results	Results	Results	Results
Alternaria		Moderate				
Ascospores		Moderate		Moderate	<u> </u>	
Aspergillus	Abundant			Modelare		
Basidiospores		Few				
Bipolaris/Drechstera Group (2)		Moderate	<del> </del>			
Chaetomium	Abundant	Moderate				
Cladosportum		Moderate	Moderate			
Curvularia		Few				
<b>Ерісосси</b> т		Few				
Vigrospora		Few				
Penicillium				Abundant		
Periconia/Myxomyceles/Smuts	Few	Moderate		Few		
ollen	Few	Moderate				
richoderma			Abundant	Few		
Comments:			Vanidati		·	
Lomments:						

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Approved:

(2) Also includes spores from Exosporium, Exserohilum and Helminthosporium

Few=10 or fewer fungal structures detected over area analyzed; Abundant=fungal structures detected in 75% or more of the area analyzed or more than 500 fungal structures present; Moderate fungal structure concentrations between few & abundant

The results taken from your home, building, etc. cannot be interpreted without physical inspection of the contaminated area or without considering the building's characteristics and the factors that led to the present condition. Interpretation of results is the responsibility of the company or individual who conducted the investigation.

This report shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be used to claim endorsement by AIHA or any other agency of the U.S. Government



914

# 2033 Heritage Park Drive / Oklahoma City, OK 73120 / (405) 755-7272 / Fax (405) 755-2058

# Microbiology Analytical Report

QuanTEM Lab ID 164297

Date Received:

07/22/2008

Received By:

Barbara Holder

Analyzed By: Date Analyzed: Todd Jelinek 07/23/2008

Methodology:

Air-O-Cell, Quantitative

NonCulturable MM001

AIHA ID Number: 101352

Client

Maxwell Envirotech, Inc.

751 Lonesome Trail #300

Driffwood, TX 78619

Account Number: 8000

080787

Project: Location:

N/A

Project No:

N/A

QuanTEM Sample ID Client Sample ID	001 SD.16	002 3D.11	003 SD,12	7	Ante es	
Volume (L)	60	60	60			
Detection Limit (Counts/m <sup>3</sup> )	17	17	17	1	88 W.	1 39 330

	itesuits Counts/m³	Results Counts/m <sup>2</sup>	Results Counts/m <sup>2</sup>	Results Counts/m*	Results Counts/m²	Results Counts/m*
Alternaria	183	517	217			Counts/10
Ascospores	- 283	550	983		<u> </u>	
Aspergillus/Penicillum Group		317		- 49 ****** ***********	All bear to come a fermion was to a	
Basidiosporca	<b>30</b> .	217	33		<u></u>	-
Bipolaris/Drechsteru Group (2)	83	367				
Cercospora			17			
Chaetyrisum	17	67	The Comment of the Comment	Office III or or a		
Cladosportun	183	133	583			
Curvularia	67	367				
Spicoccum	33	117		1	in man	js post <b>us</b> 50
Fusterium			150			
Hyphal Fragments	533	583	167			
Nigrospora	50	83	17			
Periconia/Myxomycetce/Smuts	183	800	[33			
Pithomycas/Uocladium	17	50				
Pollen		117	17			
poridesmium	17	The same of the same of				
Torvia		17				
Fotal Results (Counts/ar*)	1699	4302	2317			
Percent Coverage (%)	20	90	35			





#### 2033 Heritage Park Drive / Oktahoma City, OK 73120 / (405) 755-7272 / Fax (405) 755-2058

#### Microbiology Analytical Report

QuanTEM Lab ID 163971

Client:

Maxwell Envirotech, Inc.

Date Received:

07/15/2008 Rachel Molieri 751 Lonesome Trail #300 Driffwood, TX 78619

Received By: Analyzed By:

Todd Jelinek

Account Number: B000

Date Analyzed:

07/18/2008

Project:

080787

Methodology:

Bulk, Qualitative NonCulturable

Location:

N/A

MM005

AllHA ID Number: 101352			Project No:	N/A		
QuanTBM Sample ID	001	002	003	004		
Client Sample ID	SD.I	SD.2	SD.3	SD.4		
	Kirch clo	Kitch FLP	2 FLA PAR	A ZNO FLD	***************************************	1
	Results 9	Results	Results	Results	Results	Results
Alternaria	Present					
Aspergillus	Present			20		
Cladosportum	Present					
Penicilitum		Present				
Pollen	Present					
No Mold Detected			Х	х		
Comments:			No Mold Detected	No Mold Detected		

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Approved:

The results taken from your home, building, etc. cannot be interpreted without physical juspection of the contaminated area or without considering the building's characteristics and the factors that led to the present condition. Interpretation of results is the responsibility of the company or individual who conducted the investigation.

This report shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be used to claim endorsement by AIHA or any other agency of the U.S. Government





# 2033 Heritage Park Drive / Oldehóma City, OK 73120 / (405) 755-7272 / Fax (405) 755-2058

#### Microbiology Analytical Report

QuanTEM Lab ID 163971

07/15/2008

Date Received: Received By:

Rachel Molieri

Analyzed By:

Todd Jelinek

Date Analyzed: Methodology:

07/18/2008

Tape, Qualitative NonCulturable

MM002

Client:

Project:

Maxwell Envirotech, Inc.

751 Lonesome Trail #300

Driftwood, TX 78619

Account Number: B000

080787 N/A

Location: Project No:.

N/A

AIHA ID Number: 101352			Project No:.	N/A		
QuanTEM Sample ID	005	006	007	008		
Client Sample ID	SD,5	SD.6	\$D,7	SD.8	i	00.000

	N WALL	Util Rm Results	Vt1 L R	Results	D-c-le-
		Results	Remits	Damille	The analysis
- 1				Magnitz	Results
		WALL	646		
Mı	oderate				
Me	oderate		Moderate		
ndant					
	Few				
Me	oderate				
idant Mi	oderate				
Mo	oderate	Moderate			
	Few				
	Few				
	Few				
			Abundant		
w Me	oderato		Few		
w M	oderate		Few		
		Abundant			
	w M	Few Few Few Moderate	Few Few Few  W Moderate W Moderate	Few Few Few Abundant W Moderate Few W Moderate Few	Few Few Few Abundant W Moderato Few W Moderate Few

I believe achievering materi	upon receipt the	condition of	the sample	was noceptable	e for analysis.

Approved:

(2)Also includes spores from Exosporium. Excerohillum and Helminthosporium

Fow=10 or fewer flingsi structures detected over area analyzed; Abundant=fungal structures detected in 75% or more of the area analyzed or more than 500 fangal structures present; Moderato-fungal structure concentrations between few & abundant.

The results taken from your home, building, etc. cannot be interpreted without physical inspection of the contaminated area or without considering the building's characteristics and the factors that ied to the present condition. Interpretation of results is the responsibility of the company or individual who conducted the investigation.

This report shall not be reproduced except in full, without the written approval of the laboratory.

This report may not be used to claim endorsement by AIHA or any other agency of the U.S. Government

# CG&S Design-Bulld

Probable Cost of Construction

Date: 10-Nov-08 Client: Sylvia & John Dudney Address: 4211 Avenue G.

Phase: Remedial Estimating
Job Description: Restoration/ Rehabilitation at 4213 Average G



information at garage (Availloways on private property if stoops/ledings/exidentor stairs andation piers at house and ston piers at house atted substructure reinforcement(shaker beems, etc) a and replace existing underphraing to excess foundation if conditions, Protection of Finishea, re & Accessories Installation, Venting, Temporary Protection if Daily Site Citeanu-pinterior & Gizea Citeanup (1-polish Cen er and Inspection Fees Required demo at garage I original proches desting wallakestings as necessary for excess to MEPs desting floor ceiting materials as necessary statins kitchens(2) entral stailway (non-compilant) subfloor as required for excess and Finsh Materials.	25,075 7,400 4,200 35,000 12,188 10, 4,444 ction, out). 47,684 1,200 5,625 2,000 1,590 7,560 5,670 2,836			demo existing and pow bernath existing anoral structure demo existing includes concrete demo
undation at gamps  Availlavarys on private property  F stoops/ladinga/enderior stairs  andation piera at house  atted substructure reinforcement(shaker beems, etc)  a and replace existing underphrating to access foundation  Conditions, Protection of Finishes,  re & Accessories Installation, Venting, Temporary Prote  I Dally Site Cteanup Interior & Glass Cleanup (1-polish  Cen  er  and inspection Fees  tequired demo at garage  to original porches  stating floor/ ceiting materials as necessary  stating floor/ ceiting materials as necessary  stating floor/ ceiting materials  and inspection fees  deting floor/ ceiting materials  as necessary  stating floor ceiting materials  as necessary  stating floor ceiting materials  as necessary  stating floor ceiting materials  as necessary  certain floor ceiting materials  as necessary	21,074 7,400 4,200 35,000 12,188 4,444 ction, out). 47,684 1,200 5,825 2,000 1,890 7,560 5,670 2,836 1,134 2,208			demo existing and pow bernath existing anoral structure demo existing includes concrete demo
Weathways on private property  Fishops/ladings/enderior stairs andation piers at house altad substructure reinforcement(shaker beems, etc)  and replace existing underphraing to access foundation  Conditions, Protection of Finishes,  re & Accessories Installation, Venting, Temporary Protein  (1 Daily Site Cteanupfinierior & Gizsa Cleanup (1-polish  cen  er  and Inspection Fees  Keguired demo at garage  I originat porches  disting walls/callings as necessary for access to MEPs  disting floor/ ceiting materials as necessary  postatrs kitchens(2)  antral stainway (non-compliant)  subfloor as required for access	21,074 7,400 4,200 35,000 12,188 4,444 ction, out). 47,684 1,200 5,825 2,000 1,890 7,560 5,670 2,836 1,134 2,208			ac accounts and pour barnath existing shored structure  of demo axisting  if includes concrete demo  iii
Fishops/ladings/enderior stairs andation piers at house satisd substructure reinforcement(shaker beems, etc) and replace edisting underphraing to eccess foundatio Conditions, Protection of Finishes, re & Accessories Installation, Venting, Temporary Prote J Daily Site Cleanupfinterior & Glass Cleanup (1-polish Cer. er and Inspection Fees Required demo at garage I originat porches disting floor/ ceiting materials as necessary setating floor/ ceiting materials as necessary setating lichens(2) antral stainway (non-compliant) subfloor as required for access	7,400 4,200 35,000 12,188 1,444 ction, out). 47,684 1,200 5,825 2,000 1,890 7,560 5,670 2,836 1,134 2,268			91 demo existing 91 includes concrete demo 9
andation piera at house atted substructure reinforcement (shaker beems, etc) a and replace edisting underphrating to access foundation. Conditions, Protection of Finishes, re & Accessories Installation, Venting, Temporary Prote. I Daily Site Cteanup finishfor & Glass Cleanup (1-polish Cen er and inspection Fees. Required demo at garage. Loriginal porches string floor/ cetting materials as necessary patains kitchens(2) intral stallating in accessary autification of the component of the control of t	4,200 35,000 12,165 1,166 4,444 ction, out) 47,684 1,200 5,625 2,000 1,890 7,560 5,670 2,836 1,134 2,265			DE Includes concrete demo
aliad substructure reinforcement (shaker beems, etc) o and replace existing underphrating to access foundation of Conditions, Protection of Finishea, re & Accessories Installation, Venting, Temporary Protection of State Cleanup (1-polish Ceneral Condition) of Conditions of Conditio	35,000 12,185 4,444 ction, out). 47,684 1,200 5,825 2,000 1,890 7,560 5,670 2,836 1,134 2,205			
a and replace edisting underphrating to eccess foundation of Conditions, Protection of Finishes, re- 8 Accessories Installation, Venting, Temporary Protect of Daily Site Cleanup American & Glass Cleanup (1-potish Ceneral and Inspection Fees Required demo at garage original porches design wallakealtings as necessary for scoess to MEPs desting floor cetting materials as necessary postatis kitchens (2) and allower (non-compliant) subfloor as required for access	n 4,444 ction, out) 47,684 1,200 5,625 2,000 1,890 7,560 5,570 2,836 1,134 2,268			
Conditions, Protection of Finishes, re & Accessories Installation, Venting, Temporary Prote // Daily Site Citeanu-pinterior & Glesa Cleanup (1-polish Den er and Inspection Fees Required demo at garage I original porches disting walla/callings as necessary for scoess to MEPs disting floor/ ceiting materials as necessary postatrs kitchens (2) antral stainway (non-compliant) subfloor as required for access	ction, out). 47,684 1,200 5,825 2,000 1,890 7,560 5,670 2,835 1,134 2,205	3 3 3 3 3 3 3		
re & Accessories Installation, Venting, Temporary Prote.  J Daily Site Cleanup Amerior & Glass Cleanup (1-polish Cen er end Inspection Fees Required demo at garage I original porches deting wallshollings as necessary for scoess to MEPs disting floor/cetting materials as necessary patains kitchens(2) mitral stalinesy (non-compliant) subfloor as required for access	ORB). 47,684 1,200 5,625 2,000 1,890 7,560 5,670 2,836 1,134 2,268	3 3 3 3 3 3 3		
If Daily Site Cteanup (1-podsh- cen er and inspection Fees tequired demo at garage I original porches string malarballings as necessary for scoess to MEPs dating floor/ ceiling materials as necessary patains kitchens(2) entral stainway (non-compliant) subfloor as required for access	ORB). 47,684 1,200 5,625 2,000 1,890 7,560 5,670 2,836 1,134 2,268	3 3 3 3 3 3 3		
can ser	7,200 5,625 2,000 1,890 7,560 5,670 2,836 1,134 2,268	3 3 3 3 3 3 3		
er  and inspection Fees  Required demo at garage I original porches  disting wallabellings as necessary for scoess to MEPs  disting floor/celling materials as necessary  pateria kitchens(2)  mitral stainway (non-compliant)  subfloor as required for access	5,825 2,000 1,890 7,560 5,670 2,836 1,134 2,268	3 3 3 5 5		
and Inspection Fees Required demo at garage I original porches stating wallatratings as necessary for access to MEPs stating floor ceiling materials as necessary statins (blothers(2) antral statinway (non-compliant) subfloor as required for access	2,000 1,890 7,560 5,670 2,836 1,134 2,268	3 3 3 3 3		Ni -
Required demo at garage  I original porches disting wallatestings as necessary for scoess to MEPs disting floor ceiting materials as necessary pastains kitchens(2) antral etathway (non-compliant) subfloor as required for accass	1,890 7,560 5,670 2,836 1,134 2,268	3 3 3 3 3		B P
I original porches define wallabellings as necessary for sccess to MEPs disting floor ceiling materials as necessary distains kitchens(2) aniral etailway (non-compliant) subfloor as regulated for access	7,560 5,670 2,835 1,134 2,268	3 3 3 3	1 890 00	
dsting wallakelitings as necessary for scoess to MEPs dsting floor/ceiting materials as necessary costairs kitchens(2) antral stainway (non-compliant) subfloor as required for access	7,560 5,670 2,835 1,134 2,268		.7,566.Dá	
dsting floor ceiling materials as necessary patials kitchens(2) miral etainwsy (non-compliant) subfloor as regulated for accass	5,670 2,836 1,134 2,268			demo to facilitate restoration of original purchas/varang
dsting floor ceiling materials as necessary patials kitchens(2) miral etainwsy (non-compliant) subfloor as regulated for accass	2,836 1,134 2,268	8.	6,870.00	Desired to recreate seasons not original porchase and
estate kitchens(2) entral stainway (non-compliant) subfloor as required for access	1,134 2,268		State 2.19.900	
entral stainway (non-compliant) subfloor as required for access	2,265	6.0	Sel:134.00	
subfloor as required for access				The state of the s
nd Finsh Materials:	2/0		357.00	reconstruction of stainway necessary to meet codes
	34,562	1 R A	3 7 7 7 7	
	54,000			Comice ferterior trim, porch cellings and frim, Columns,
		1	10 600	(1978070 Etalfs, Walls/Collings of steinwell, and garage from
		40		Garage anodroperating Garage confined feature
		34	313	PEDISCONDERDITEDENT, PICKES COMICS STROKES FOR COMICS
Labor	64.000		J. 34, 400	porches, Startwell walls-bellings stairs, close up non
Rentor and Extenor	54,035	3 9 9	54,036.00	OOMATAN Afainmen
d Garage Door & Opener	2 500			
	2,500	100	2,00,00	Demo axisting windows / Replace all windows
	44,000	3.44	44,000.00	Demo existing windows / Replace all windows
House and garage demo and new stucco	93,996		83,950.00	As a result of window replacement, existing cracking in Studen aubsequent cracking/diamage as a result of in levellingit is assumed that all studen will need to be completely replaced:
	25,760	M	CHARLEST NEWS TWO	re-roof house and garage replace roof vents/figahings,re flesh all penetrations
& Rough Materials	15,000 17,600	X S		Identify and correct repairable plumbing and gas replace plumbing and gas as required- ellowance for 160 hrs. ea. plumbenhelper
Fixtures	9,300	100	THE PERSON NAMED IN	Territoria) el det
			A 10.11	assumed new midranga fidure at kitchen and 6 baths
	40,000	-		new hivec systems- 10 tons
& Rough Materials	71,591	5776	100	
Fixtures- included	11,001	100	1 1 10 1 10 D	navira house/garage to code, rebuild service demo exist
	10,732			
	10,732		- 10,132,00	Insulate at accessible walls/ballings
apa, Floet, and Texture		32	A.S.	raptace all drywall where possible due to weter demagent and access lasues
nd Cabinet / Millwork Finishes	10,890	3.73	10,880.00	and access lasues
	68,432		60/(32.00)	
& Accessories - Doors and Cabinets	15,600		16,600,00	assumed low to midrange cabbinary at kilohen/baths
A CANADAMIN - DIAMA (ELL CEDITORS)		3.7	10 C	assumed reuse eidsting
	43,580		43,560.00	essumed Boaring damo and replacement throughout hon at midrange everage
Pad	1	125	A A A	
pe .		54	7770	curpet assumed at some areas in peneral flooring budget
Pers	5,040	Rim	5,040.00	low to midrange countertops in hitchen and 8 bathroom
T WAY	5,000	12.5	5,000:00:	
Stone Tile - All tile work	15,000		4	il is assumed that due to house levelling, ell wall unfaces/fishes will require replacement
antiu I abov	12			
BINT POP	7,020	SW	2.000	New Irim labor as required/house existing trim where feasi
and the best of the state of th				low to midrange appliances in kilichen
and installation	estand El	25.5		
s and installation r/Job Foreman 12 mos. @8 hridsy @ 25,00km	58,882 758,764	50	7814 B18:00:	
r / Job Foreman 12 mos. @ 8 hr/day @ 25.00 hr				711
r / Job Foreman 12 mas. @ 8 hr/day @ 25,00/hr Son Costa Subtotal Mas				
	ny Labor nd Installation Ob Foreman 12 mos. <b>©</b> 8 hridsy <b>©</b> 25,00 hy I Costs Subtotal Mas	ry Labor 7,020  **Molecular	ry Labor 7,020 (4)  Initialisation 2,500 (4)  It is talked to 2,500 (4)  It is talked to 3,500 (4)  It	y Labor 7,020 (4 7,20,06) (4

INFrastructure + Interiors

Ave G.

127851 Demo - open walls (cilings as necessary where possible to access existing MEA.S 0 le 3=90 5670 Remove Fronting (ciling mut. 1. 163 45 2885. Demo Z spstair Kitchens 163 18 1134 Demo Stairs | Stairwell Francis | 84 2268. Remove Sub Cloor as rayed 142 9 378 [Z1872] R+F materials @ 8/1 First floor original house 1546\$ Second Hour wort porches/Add-- 1188 of Includes mutil cost to Reframe Stairwell walls close up non-compliant stairs warnsont well 110,530/ framing to accommodate new electrical electrical Francing Cabor - 36/42@ 3 Neeks 135 hrs. 32600 Plumbing - hely rate to identify leaks / problems das tast, trace leaks repair etc. 4 wks. + matel 1 plumber / helper @ 110/11. 17600 + mat-1 est, 15,000 [34,450] V Electrical - Pewise to code @ 5445 De Electrical Service Rebuild [40,000] Mech System - Add 10 tons @ 4000/fon includes associated duct work 110732 / Attic Insulation / Floor Inc. @ 1.00/# 2433 @ 3/# 2433 = 7299 Wall 1-s. as regid. 1000,000

[10890] v Drywall work @ ceilings/wainscots walls/120

Stairwells: 5445@ 2/4

4213 Ave. G. Sylvia Dudney - Rehab estimating Due Story Garage 1163 14 house Foundation lotals - 2433 \$ x2 level = 4866 \$ covered Front porch area 579 \$ total area under roof = 3012 \$ thatwork perches stoops I sidewalks at house (not street) 740%;

demo Flandings (stoop pour 2 landing 1 t stoops (4200) pour 70 piers + beams reinforcement: etc. 70 piers @ 500 ea. = 24500,00 [12165] | + floor Framin / Shaker beams etc. @ 5/0. 12165 demo / replace under pin= 444 \$ 1010 4444.00 (4444) 146310 - Restore porches . Fear (Up) side (2111. ) front (Atrium Ld.) Remove replace regions damaged covince @ all fascia Porch Ceilings etc. = R+F mal-1s. 2221f-fasein @ 5/14. 1110/ forch certinos/trin 2538 thes/0/12690) Demo Labor - Parches - 0/4 2 wks 84 x20 (7560) Framing Kornice abor Porches/183/6 2 WKs. 108/126 x 90-[21060] Porch collumns @ 1000 ec. 1+ m = 5000 144000] Who replacement truco 1000 ea. 44000 Stucco work (mostly replacement 222 lfx30= 6660 Car 12/4 = 79,920 21,500,60 Rossino/flashings/15215/ Penetrations/13012 +1-4=43 sq. 43. sq. @ 450/sq. + tenr off 500/sq. 27725 Painting 05/0 5445= Totals Hard cost subtotal 282164 General Conditions 89 22573 Supervision 8 % 505+01ml 327,310 ÷ .75 [436,413]

con+ - Firishes 135,392/ Int. Painting 5445 @ 6.50 Apoutry Cabio [15600] (Cabs. Kitchen 12'Uppers, 12' lowers 6,000 = + 6 bathram Vanitys @ 600 ex. +4/inchs [43560] / Florring total St. @ avg. 8/8 = (0 1/200 e. 5445@ 8 00 > average assumes carpetin. Some areas/refinishing etc' 50401. Mountertons - Assume 72 \$@ 70/04 15000/ Shower pars. (15000) Tile Work 6 boths avg. 2500 (9300) Fixtures - Eitchen, Sink, Faucets 1000,00 6 boths vanity. 400 Como de: 400 aug. 1550 x6
Showedard or tub 600 125001 appliances /d/w, oven, disposal trim Carpentry 90 hrs. 36/42 hardcost subtotal 336771 26941 GC, 26941 رجر دک 390653 7,75 (520.870) total Hotels 436,413 Ext. 520,870 Int. 134,856 Garage 1092,139.00

Garage remediation 1163 \$ New Garage Foundation @ 25/0 17445 V Shore walls | temp supports | replace reprive damage New roof Framing etc. [4250] | Poofing 1163 x 1.4 = 17 sq. @ 250/5q.

18901 Demo as needed 45 hrs. @ /42 1 25,01 Garage Doors.

181411 / Eloctrical Wiring@7/6

Hood Electrical Service Hood MHO76 | Siding Ext. Cladding Stucco, 1173 & wall footage @

Dant @ 5/4 1163 \$

subjotal Garage bland costs. 87192 6975 6975 Subtotal 101,142

475

total Garage 1134856

22

4213 Avenue G ca. 1908





# Occupancy History 4213 Avenue G

CI 23

City Directory Research, Austin History Center By City Historic Preservation Office March, 2007

1987 Helen D. Nohra, owner

Retired

1981 A: Vacant

B: No return

1975 No return

B: No return

1970 Greg Truelove, owner

No occupation listed

1966 Mrs. Helen D. Nohra, owner

Proprietor, Parkview Nursing Home, 56 East Avenue

Also listed are Charles Nohra, a book-keeper for Russell J. Horn, a lawyer with offices at 711 W. 7th

Street; Charlotte Nohra, a pharmacist at Mt. Carmel Hospital; and Sylvia Nohra, a student.

1962 Mrs. Helen D. Nohra, owner

Proprietor, Parkview Nursing Home, 56 East Avenue, Shady Oaks Nursing Home (with Mrs. Lucille Baker), 804 S. 1<sup>st</sup> Street, and Vice-President, Allandale Nursing Home (Mrs. Lucille Baker, president),

2105 Cullen Avenue)

1958 Mrs. Helen D. Nohra, owner

Proprietor, Parkview Nursing Home, 56 East Avenue.

Rear: Philippe and Maria Saucade, renters

Laborer

1954 Mrs. Helen D. Nohra, owner

Manager, Parkview Convalescent Home, 56 East Avenue

1952 Jim and Corrine Larvin, renters

Jim: Student

Corrine: Lab tech, D. William P. Morgan, physician, 306 Capitol National Bank Building

Also listed is Bernard J. Larvin, a student at UT

NOTE: Charles J. and Helen Nohra are listed as living at 56 East Avenue (the address of the

Parkview Convalescent Home); Charles J. Nohra operated the Monte Carlo Café at 903 E. 6th Street.

1949 Eugene and Betty Schuster, renters

Salesman

1947 Charles and Helen Nora, owners

Manager, Golden Glove Inn restaurant, 721 E. 6th Street

1944-45 Vacant

NOTE: Charles and Helen Nohra (or Nora) are not listed in the directory.

1942 Dewey C. and Josephine H. Bradford, owners

President, Bradford Paint Company, 9th and Colorado Streets

NOTE: There is also a listing for the Gamma Phi Beta Sorority at this address.

1940 Dewey C. and Josephine H. Bradford, owners

President, Bradford Paint Company, 9th and Colorado Streets

1937 Dewey C. and Josephine H. Bradford, owners

President, Bradford Paint Company, 201-03 W. 9th Street (corner Colorado Street)

1935 Dewey C. Bradford, owner

President, Bradford Paint Company, 201-03 W. 9th Street (corner Colorado Street).

NOTE: Josephine Bradford is not listed in the directory.

Carleton F. and Thelma Card, renters

Salesman, Swift & Company

1932-33 Dewey C. Bradford, owner

Vice-President/Secretary, The Bradford-Barrett Company, Inc. (C.E. Barrett, President; wholesale and retail paint, wall paper, window glass, picture frames, 201-03 W. 9<sup>th</sup> Street, corner Colorado Street).

Carleton F. and Thelma Card, renters

Salesman, Swift & Company

1930-31 Dewey C. Bradford, owner

Vice-President/Secretary, The Bradford-Barrett Company (C.E. Barrett, President; wholesale and retail paint, wall paper, window glass, picture frames, 201-03 W. 9<sup>th</sup> Street, corner Colorado Street).

Carleton F. and Thelma Card, renters

Salesman, Swift & Company

1929 Dewey C. Bradford, owner

Vice-President/Secretary, The Bradford-Barrett Company, Inc. (C.E. Barrett, President; wholesale and retail paint, wall paper, window glass, picture frames; 201-03 W. 9<sup>th</sup> Street, corner Colorado Street).

1927 Carleton F. and Thelma Card, owners

Salesman, Swift & Company

NOTE: It appears that Thelma Card was the former Thelma Bradford, residing at this address while a

student.

Dewey C. Bradford

Employed by C.A. (Clyde A.) Bradford, paint, glass, wall papers, 201-03 W. 9th Street, corner Colorado

Street

1924 Mrs. Lula V. Bradford, owner

Widow, Christopher C. Bradford

No occupation listed

Also listed are Dewey C. Bradford, an employee of Clyde A. Bradford, paints, glass, and wall papers,

201-03 W. 9th Street; and Thelma Bradford, no occupation listed.

NOTE: Carleton F. Card is not listed in the directory.

1922 Mrs. Lula V. Bradford, owner

Widow, Christopher C. Bradford

No occupation listed

Also listed are Dewey C. Bradford, a salesman for C.A. Bradford (paints, glass, and wall papers), 705

Congress Avenue, and Thelma Bradford, no occupation given.

1920 Mrs. Lula V. Bradford, owner

Widow, Christopher C. Bradford

No occupation listed

Also listed are Dewey C. Bradford and Thelma Bradford; neither listed an occupation.

9

1918 Clyde A. and Myrtle Bradford, owners

President, C.A. Bradford Company, paints, glass, and wall papers, 705 Congress Avenue.

Also listed are Mrs. Lula V. Bradford, the widow of Christopher C. Bradford, no occupation given;

Dewey C. Bradford, a student, and Thelma Bradford, a student.

1916 Clyde A. Bradford

President, C. A. Bradford Company, wall paper and paints, 705 Congress Avenue.

Also listed is Lula V. Bradford, the widow of Christopher C. Bradford, no occupation given; Dewey

Bradford, a student; and Thelma Bradford, a student.

NOTE: This house is the only house in this block on both sides of the street.

1914 Clyde A. Bradford

President, Bradford-Dorflinger Company, paints, oils, varnishes, wall papers, 705 Congress Avenue

Also listed is Lula Bradford, the widow of Christopher C. Bradford, no occupation given.

1912-13 Clyde A. Bradford

Lands and city properties, 418 Littlefield Building

Also listed is Lula V. Bradford, the widow of Christopher C. Bradford, no occupation given.

1910-11 George E. Christian

President, Austin Lumber Company, 220 W. 2nd Street.

Also listed is George E. Christian, the secretary-treasurer of Austin Lumber Company.

NOTE: The Bradfords are not listed in the directory.

1909-10 William A. Stewart

Real estate

NOTE: House is listed as 4215, and is the only house on this block.


NOTE: George Christian (no occupation given) is listed as living at 310 W. 10<sup>th</sup> Street: George E.

Christian, a student at the University of Texas, is listed at the same address.

1906-07 Address not listed

# PHOTOGRAPHS PROVIDED BY THE HYDE PARK NEIGHBORHOOD ASSOCIATION





















C1 28






The 1922 Sanborn map shows the house with a two-story wraparound porch as shown in the historic photographs.



The 1935 Sanborn map shows the two-story wraparound porch and a one-story rear addition.



The 1962 Sanborn map shows the same configuration as the 1935 map; the current rectangular addition to the southeast is not shown on this map.

Umerican States no 19,1166

# BRADFORD PAINT CO.

That Minter Carry



### Dewey Bradford

Serving Dealers Wholesale in the Following Towns:


Bartlett Bastrop Belton Bertram Burnet Cameron Elgin Florence Georgetown Giddings Granger Hutto Killeen Lampasas Leander Liberty Hill Llano Lockhart Manor Rockdala Round Rock Rogers San Marcos San Saba Smithville Taylor Temple Thorndale Thrall

# Serving Central Texas Wholesale Retail

DISTRIBUTORS FOR 27 PAINT, WALPAPER AND ART MATERIAL LINES

#### OUR OBJECTIVE

- 1. To carry in stock the largest possible amount of materials necessary to supply any demand.
- 2. To select for the customer safe products that he may have the cheapest that is good and the best that money can buy; assortments in grade, color and price.
- To be an absolute authority on the method of application, chemistry of the product and responsible for the service of everything we sell.
- 4. To employ intelligent people who are completely trained in every detail SPECIALIZA-TION—
- 5. To serve Austin and our customers faithful to one ideal, quality. Independent— Free to choose from all the world the best, most efficient, sensible products for our friends, the Painters, the Architects and decorators,






### C. B. Mallory

Jobbers for the following Benj. Moors & Co.'s Faints. Complete Line Reardon's Bondex and Modex Dutch Boy Lead, Nat'l Lead Pol-Mer-lk Linseed Oil Day's Shellace Illinois Alluminum Sunflex Casein Paint Valspar Varnish Periseal Varnish Tiliey Ladders Painter's Supplies Wooster Brushes. Wolster Drublics.
Wallpapers from
Birge, Lennon, Strahan,
Becker-Smith-Page, Niagara.
Paper Hanger's Supplies
Picture Mouldings from Grumbacher Art Brushes and Supplies Winsor Newton Art Colors Show Card Colors and Boards Artist's Canvas and Papers Pictures, Oils, Water Colors, and Prints. Picture Frames Insulation—"Metallation"
Old English and Jewel Floor
Wax
Polishing Brushes

Am. St. 7/19/1936

Colorado at Ninth St. WALL PAPER. PICTURE FRAMING AND ADD BEARING



1937

Dewey Bradford

Owner Bradford Paint Co.

# Dewey Bradtord BRADE-ORD, Dewey Character

'Art's the water, I'm the windmill' white the

By MARK SEAL Citizen Staff

it was a morning now lost in time. The phone rang. Dawey Bradford, founder of the Country Store Art Gallery, answered it.
"Mr. Bradford," the woman's voice

said. "I want you to make my husband famous."

The woman's hosband painter, Melvin Warren, and Bradford and never heard of him. But not being a man to judge something before he's seen it. Bradford told Mrs. Warren to send her husband to Austin with 10 of

send her muscam to Austin wan 10 or his best paintings.

When Warren arrived, Bradford found an artist who didn't know his own talents. His paintings were surrealistic "twilight zone" scenes, but in his work Bradford saw a glimpse of talent.

"The state of the stat

"I told him to paint natural things," Bradford rumembers. "He was to do 10 oil paintings for me and the tenth would be his masterpiece."

So II was. Warren, constantly coached by Bradford, improved with each canvas. Gone was the surrealism in his art. In its place, Wasren painted things that he knew best — Texas

The tenth painting, "A Stopover at oerne," with its rustic country Boerne, stagecoach scena, became not only Warren's musterwork hut a true Texas art classic. His work soon hung in Lyndon Johnson's White House and the homes of the privileged.

Mrs. Warren's desire, expressed in the phone call, had been realized. But for Bradford, it was just another in-stance of an artist finding justice.

Today, Warren's painting hangs on a wall in Bradford's home near Zilker Park. The painting is accompanied by the works of other artists whom Bradford has helped, criticized and

commissioned through the years.

Bradford is Austin's premier patron of the arts and though he is now 80 and his Country Store is under new management, the subject of art is indelibly painted on Dewey Brad-ford's mind.

"An oyster will not produce anything unless there is a piece of sand in his belly," says Bradford, standing in the center of his living room, his back to the wall of paintings and facing a picture window full of th park and the Austin skyline. "Well, it's the same with the artist. He must be irritated to produce his best work."
To artists like Warren and Porfirio

Salinas, Dewey Bradford supplied the

Bradford's history is a long story and, when asked about it, he struck a lecturer's pose in front of the picture window, in his bright red western shirt and orange scort, and began a steady stream of oralory.

"If I had any dreams or ambitions at all, it was surely as a thespian," he explained. "I was in dramatics in all manner of fact at UT. Later I went to Hollywood and played Ramon



Dewey Bradford is Austin's patron of the arts. The artists whom he's beined, criticized and commissioned now have their work hung on the walls of the wealthy and their names inscribed in the annals of history. Citizen photo by Mark Seal

could hear the news and be near the

"This new era," Bradford continued, "made people conscious of their decor, in order to let their image reflect their personality they needed decorative accessories.

"This was the threshold to admit people of talent. There was an impetus of skutches and realistic photography. Local artists brought in prisring oils on canvas. The artists that alcetched the outdoor scenes up and down Bull Creek considered the Texas wildflower to be exotic and nexus withintered to be exolic and you'd think they'd just discovered the cactus in bloom. Their art was an swaltening for the people of Texas who had always accepted all this beauty because it had always just ham there." been there.

Bradford paused, for emphasis, and

said, "New paregraph."
"Then there appeared Porfirlo
Salimas," he said. "This artist transported to canvas an honesty in nature. He did the creeks, wildflowers, hills of burning colors, ranches and the Texas landscape. Born in Bastrop, his paintings were laithful to the seasons. And he become famous for the reason that he never changed his category of art and painted only the rustic ocenery (with) which people were familiar."

Bradford's relationship with Selinas was one of the most important ones of his and the artist's life. For Salinas, whose bluebonnets and Texas landrealist. He died in 1973, but today the art of Porfirio Salinas has never been

more alive.

According to Dewey Bradford, the greatest artist has never painted. The strongest man doesn't know his own strength. The greatest writer has never appeared in print. The finest voice has never been heard.

And it's all because the artist, a strange creature if there ever was one, doesn't usually have the sbility to

get his art to the people.
"Few people have been allowed to reach their peak as artists," Bradford said. "Most art has been accidental and only a very small percentage of artists is ever recognized."

"Take this watercolor," he said, pointing to a crude Mexican painting hanging on one of his kitchen walls. "I picked this up in Mexico for \$2. This guy's a great painter. He's down there starving to death and I could make

Now that Bradford has retired and the artists whom he har helped have received their proper place in history,

these are days for retrospection.
"In the language of food, I'd say I ran an artistic smorgasbord," he explained. "It was all full of flavor and spice and there was never one picture that was to hang alone.

"To me, the artist is the conquists dor."

d you? Possibly the horse? And "No," he said with a grin. "Art is the water in the ground. And I — I'm no date

When warren arrived, praumu i found an artist who didn't know his own talents. His paintings were surrealistic "twilight zone" scenes, but in his work Bradford saw a

glimpse of talent.
"I told him to paint natural things," Bradford remembers. "He was to do 10 oil paintings for me and the tenth would be his masterpiece."

So it was Warren, constantly coached by Bradford, Improved with each canvas. Gone was the surrealism in his art. In its place, Warren painted things that he knew best - Texas

The tenth painting, "A Stopover at with its rustle country Boerne," stagecoach scene, became not only Warren's masterwork but a Texas art classic. His work soon hung in Lyndon Johnson's White House and the homes of the privileged.

Mrs. Warren's desire, expressed in the phone call, had been realized. But

for Bradford, it was just another in-stance of an artist finding justice. Today, Warren's painting hangs on a wall in Bradford's home near Zilker Park. The painting is accompanied by the works of other artists whom Bradford has helped, criticised and commissioned through the years.

Bradford is Austin's premier patron of the arts and though he is now 80 and his Country Store is under new management, the subject of art is indelibly painted on Dewsy Brad-ford's mind.

ford's mind.

"An oyster will not produce anything unless there is a piece of sand in his belly," says Bradford, standing in the center of his hiving room, his back to the wall of paintings. and facing a picture window full of the park and the Austin skyline. "Well, it's the same with the artist. He must

be irritated to produce his best work." To artists like Warren and Porfirio Sailnes, Dewey Bradford supplied the grain of sand.


Bradford's bistory is a long story and, when asked about it, he struck a lecturer's pose in front of the picture window, in his bright red western shirt and orange scarf, and began a steady stream of oratory.

"Il I had any dreams or amhitions at all, it was surely as a thespian," be explained. "I was in dramatics in all manner of fact at UT. Later I went to Hollywood and played Ramon Novarro's double in the first 'Ben Her." among other things. But when my mother died and left me her mess, an Austin paint store, I had to decide whether I wanted to throw my acting career away or come back to Austin and be civilized."

Bradford chose civilization.

"I was always intrigued by the local tists," Elisabet Ney, Peter Manartists. spendel (a woodcarver), Sim Gideon and others. They were the beginning of formal art in Austin. At that time, in the early to mid-1900s, people were entertained outdoors. They pitched horseshoes, had hayrides, they hunted and fished and they spent their lelsure time outdoors.

"Suddenly, though, when the radio, air-conditioning, wall-to-wall carpet and acoustical living rooms came about, averybody went indoors. Then, the swim parties and the man in the haramock moved indoors where he



Dewey Bradford is Austin's pures of the arts. The artists whom he's helped, criticized and commissioned now have their work hung on the helped, criticized and commissioned new have their work hung on the walls of the wealthy and their names inscribed in the ansats of h Citizen photo by Mark Sent

could hear the news and be near the

"This new era," Bradford con-tinued, "made people conscious of their decor. In order to let their image reflect their personality they needed decorative accessories.
"This was the threshold to admit

people of talent. There was an impetus of shetches and realistic photography. Local artists brought in original oils on canvas. The artists that sketched the outdoor scenes up and down Bull Creek considered the Texas wildflower to be exotic and you'd think they'd just discovered the cactus in bloom. Their art was an awakening for the people of Texas who had always accepted all this beauty because it had always just been there.

Bradford paused, for emphasis, and

said, "New paragraph."
"Then there appeared Purfirio
Salinas," he said. "This artist trap-Salinas," he said. "This artist tran-sported to canvas an honesty in nature. He did like creeks, with-flowers, hills of burning colors, ranches and the Texas landscape. Born in Bastrop, his paintings were faithful to the seasons. And he became famous for the reason that he never changed his category of art and painted only the rustic scenery (with) which people were familiar."

Bradford's relationship with Salinas

was one of the most important ones of his and the artist's life. For Sailnas, whose bluebonnets and Texas landscapes hang everywhere from the Governor's mansion to local beer joints, became Texas' foremost realist. He died in 1973, but today the art of Porfirio Salinas has never more alive.

According to Dewey Bradford, the greatest artist has never painted. The strongest man doesn't know his own strength. The greatest writer has never appeared in print. The finest voice has never been heard.

And it's all because the artist, a strange creature if there ever was one, doesn't usually have the ability to

get his art to the people.

"Few people have been allowed to reach their peak as artists," Bradford gaid. "Most art has been accidental and only a very small percentage of artists is ever recognized." "Take this watercolor," he said,

pointing to a crude Mexican painting hanging on one of his kitchen walls. "I picked this up in Mexico for \$2. This guy's a great painter. He's down there starving to death and I could make him femous

Now that Bradford has retired and the artists whom he has helped have received their proper place in history, these are days for retrospection.

"In the language of food, I'd say I ran an artistic smorgasbord," he explained. "It was all full of flavor and spice and there was never one picture that was to hang alone.

"To me, the artist is the onquistador." conquistade

And you? Possibly the horse?
"No." he said with a grin. "Art is the water to the ground. And I - I'm the windmill."



#### DEWRY BRADFORD

1 Later 182.

Fit wor

Mr. Dewey Charies Bradford was born on October 4, 1896, in Round Rock, Texas, the son of Christopher Columbus Bradford and Lula Coffee Bradford. He is a former heavyweight boxer, a chariotiver, a football player (a guard for The University of Texas Longhorms), and a World War I marine. He has acted in local productions, and world war I marine. He has acted in local production, and will be reasumbered for this role in The Drunkard! the palinted pictures for a number of years, and some suspect he was a much better artist than he admitted. He is a masterful story teller. His picturesque vecabulary and graphic narrative style reveal that he coold have been a capable writer in addition to all his other accomplishments. His various trips, both in the United States and elsewhere, make him a most interesting conventationalist. He has made many trips to Europe, collecting art and making friends who were instrumental in locating many of the lovely paintings and art objects he has displayed and sold at his Country Store Gallery in Austin. Austin

objects he has displayed and sold at his Country Store Gallery in Austin.

Mr. Bradford is not the man who sold a refrigerator to an Eskimo, but he could have sold the salesmen ice cubes to carry as zamples. Part of the charm of visiting his linesed-nil-and-landscape salen is discovering the proprietor's mood. One may be greeted warmly or coldly, Ristared, entertained, or ignored. One of his favorite approaches is to go up to an old friend with extended hand and an apologetic smile and early. If swear i have seen your face a thousand times, but i can't call your name."

Having thus put the visitor at ease, Mr. Bradford may follow up with several frash, observations as to the man's generally run-down appearance, his seedly apparel, and his atvocious taste in any and all matters pertaining to art. Impressed with his own unworthiness, the coatomer humbly accepts Mr. Bradford's vantly superior fudgmant in the transaction at hand. Deway does not easend it total strangers in this manner, of course, and his friends have learned that his wide knowledge of art and his concers for their satisfaction make him a man to be trusted. His charming and persuasive manner also make him a master salesman. His wearthing extends to the resisted fields of interior and exterior decorating; and in this work he has the help of his wife Josephine, a lovely lady who bears up well under the strain.

Porfire Salinas was one of many artists who took refure in

of ma ware observed.

Porfuso Salinas was one of many artists who took refuge in Dewey Bradford's sanctuary. As a result of his association with Austin's paint-art-and-portrait entreprensur, he became better known in Austin than in his nativa San Antonio. For three decades 48

Bradford pushed Salinas — pushed his art on the market, that is, because Salinas was a full-time ertist who pushed himself. He was no more averse to making money than Bradford. This may have had something to do with their rocky relationship, at one time bringing the artist to the point of accusing Bradford of holding out commissions from him. Dawey produced avidence substantialing his innocence and did not hold the incident against Salinax since he well knew that some artists are temperamental.

knew that some artists are temperamental.

Salinas' range of artistic subjects was not great; but he knew a bloebonnet, a husache, hanging moss, creeks, and Texas skies when he saw them. According to bis biographer, Ruth Goddard, he knew them from his early youth, a situation which mede John Connilly ask Bradford why, if the quality was the same, the price (of his later pointings) should go so high? He got no answer, but "Big Johns, who came from bumble beginnings, made it rich and became world famous when President Lyndon Johnson purchased a number of his paintings for the White House and for his ranch home. He left a legacy which Dewey Bradford has promoted in a businessike manner.

Salinas was only one of many artists whose talents Dewey recog-nised, took into a business arrangement, and guided in successful careers. He persuaded these artists to paint what customers liked to buy and featured their works in subfisits and gallery showings.

buy and fastured their works in subhits and gallery showings. Roy Bediehak, the famour Texas naturalist and loves of birds, had observed the woodpacker for many years and regarded him as the clown of the bird world. He was also impressed by the birds carpenter work on telephone potes. Roy observed that the hole on the pole was always on the east side, or all in shape, and beautifully and skitlifully seveled, as if it were made by the tools of a master craftsman. Morsover, all this careful laber sid planning were not without logic. This bird house was intended as a permanent homestend for generations of woodpecker families.

Roy explained to Dewar thet mendocker families.

stend for generations of woodpecker families.

Roy explained to Dewey that woodpeckers descried the trees in the forests when telephone poles were introduced because it was senior for the birds to dig in the softer wood for insects. That, of course, left many magnificent forest trees improtected from the insects. After the poles began to be chemically treated and telephone wires were sometimes laid underground, however, the birds found it necessary to return to their original habitat for a living.

To commemorate the telephone-pole era, Miss Carol Peabody, an artist, sculptore, and naturalist, accepted the Bedichek observations as a challenge and produced a museum art piece. She cut a section of a pole with a ewodpecker's nest in it and artistically mounted three woodpeckers on it. The birds were artificial but covered with real feathers. This historical artifact was presented to Mr. Bradford, who

Book review by "Bill" Warren of Ruth Goddard's Parfirio Salinas, published in the destin American-Statesman on November 23, 1878.

prizes it above all his other valuable possessions and regrets that Roy Bedithek did not live to see it.

The writer is indebted to Josephine Bradford for the biographical data on Dewey Bradford, and to Dewey himself for the story of his

By Mabelle Porcell



hir. Dewey Bradford displays next cut from a talaphone pole on it. Photo by Joe Coltharp. diford displays his prized historical artifact, a woodpecker's

#### JOSEPH M. BURGER

JOSEPH M. BURGER

As a phenomenal boy soprana. Joseph M. Burger of San Antonio sang professionally at the Princess Theeley, a combination movie and musical thealer where the present Bots Brothers store is now located, and at other prominent placer in San Antonio. After his voice changed to barisone, he won ties scholaschips from the Teasa Pederation of Music Citubs to study under Mrs. Arendt and with William Bhakespeer, belto of Chicago. The latter was a son of the famous William Bhakespeer, a vicie teacher of London, England.

After graduating at the American Conservatory of Music in Chicago, Burger did postpriphicate work at the Astilliand School of Music in New York. He studied under stud famous tauchers as Blesnor Mac Tellev, whom he chydielers his best teacher. She teught Ellem Farrell, Jan Paiere, Roberts Peters, Brian Sollivan, and Mack Harrell, all Metropolitan Obyra Company critist. The latter was also a Texan and excellent both in recitals and as a teacher. Burger's other excellent teachers were Karlton Hackett and Edward Gaccedots in opera, and Sondor Redowship, all of Chicago, and Mary Jordan, Joseph Rognor, and Monleys Bingher. His Town Hail dobut in New York is we with Fay Foster, the encourant away writer of the Pay Foster the renowmed many writer of the Pay Foster the encourant away writer of the Pay Foster the also taught in two Texas universities, The University of Texas at Arlington and Trinity University in San Autenio.

In his later years, Burger maintained studies of voice and conducted challed for the action of the part of the text of the pay for the Chicago and document of the pay for the Chicago. The payer and also dead of voice and conducted challed for the case of the payer of the chicago. The payer of the child the payer and a started the payer than the payer of the payer and a started the payer of the payer to the payer of the payer to the payer of the payer to the payer of the payer of the payer to the pa

Alexand &

versity in San Antonio.

In his laker years, Burger maintained atudies of voice and conducted choins for five years at Sh. David's Episcopel Church in San Antonio. He then moved his estadio to Corpus Christi and conducted the chair in the Church of the Good Shepherd. During this latter period, he also had a studio in nearby Robetown, Texas. He is sught in a special room in the Purcell home one block from each of the three public schools, alementary it-3], middle (4-6), and high school (7-1). This location provided an excellent opportunity for pupils (with parental approval) to step across the school playground and surfaith their lives with all kinds of music. This room was also used by another famous musician, George Beaver, to touch any instrument anyone had the desire to learn. The three Purcell children, then teenagen, were tought by both sanchers.

The three Furcelis provided the string easemble for all gelsen

The three Purcells provided the string ensemble for all golden adding anniversaries of that area, church functions, and school

Countrey Hotiman President Jahn Rosart President-Elect Knsy Comun First Vice President August Harra, Ill Second Vice President

Shelly Herningson Secretary Nikhi Sinha Ireasurer Nandy Deelay Immediate Past President

Paula Aaronson Nancy Burns John Donisi Jay Farrali Masjone Harris Lindsay Rose Hunter Saundra Kris Srianne Lendry Tirk League Emity Little Peter Flagg Maxson John Mayfalc Afyson McGee Andina McM'Riams Tere O'Covnell Moniza Penick Sarah Cureen Greg Phatips Enc Smith Edward Tasce Unda Feam Bratian Thomason Stephen Wapo Kristen Wacke

Michael Hotleran, U.C. School of Arch Bergan Casey, Inherit Austin John Rosato, Landmark Commusion Mile Ward, Pichaer Farras 34

STAFF Jacqui Schraad Executive Director



Chair Laurie Limbacher and Commission Members Historic Landmark Commission City of Austin sent via e-mail

Re: Bradford-Nohra House

Dear Chair Limbacher and Commission Members:



The Board of Directors of the Heritage Society of Austin would like to show our support for the preservation of the historic Bradford-Nohra House, located at 4213 Avenue G. This home is a stately 100-year-old building that is graciously sited on a prominent gateway lot in the historic Hyde Park neighborhood. It is clearly worthy of preservation because of its historic character and its well-established value to the community, evidenced through the heroic efforts of the Hyde Park Neighborhood Association and demonstrated support from other community leaders. In fact, a member of our board and architect, Emily Little, FAIA, has provided assistance to the neighborhood association to determine some site development options that would allow keeping the historic house and garage while maintaining the front and side yards. Sensitive rehabilitation of the property would not only preserve an important piece of our city's history, but also promote our shared community values to reduce waste and protect the historic character of our inner-city neighborhoods.

It is fortunate that the Bradford-Nohra House is a contributing historic property in the pending Hyde Park Local Historic District application. We encourage the City to shepherd that application through to ratification in a timely manner in order to provide guidance relative to this property disposition and others in this exceptional neighborhood. Should the owners elect to rehabilitate the building as approved in accordance with the Design Standards created for the District, they will be eligible for a rehabilitation-based tax benefit to offset the costs of this work. The program benefits the owner and the community by encouraging reinvestment and maintenance in our historic properties.

Specifically related to the pending demolition permit that has spurred this heating, we know that the potential loss of the Bradford-Nohra House would be felt deeply not only in Hyde Park, but throughout the City. We respectfully encourage the property owners to reconsider their demolition proposal, and the City of Austin to pursue the

www.heritagesocletyauttin.org

CI

appropriate measures to recognize this valuable resource. We will be glad to assist in any way that we can.

Thank you all for your many hours of hard work to preserve what is best about Austin for future generations.

Sincerely,

Courtney Read Hoffman

President