



Before 2005












Before 2005



Neighborhood Context


















19th Century view, undated, A. J. Jernigan House. The house was built in 1875. The view is looking north, towards the south elevation of the house. PICH 01952. Austin History Center. Austin Public Library.




20th Century view, about 1975, A. J. Jernigan House/Las Ventanas. The view is looking west, towards the east elevation of the house. A portion of a late 1880's masonry addition is shown on the right. The covered porch was added in 1912 along with a wood frame addition to the northwest corner, by Charles Capron, the second owner of the house. PICH 08793, Austin History Center, Austin Public Library.
















1 DEMOLITION PHOTOS
Actual Size
















2016































ADDITIONS TO THE A.J. JERNIGAN HOUSE





Finishes and Materials



INDIAN WHITE WOOD EAVE TRIM COLOR

IVY LANE CEMENTITIOUS BOARD SIDING



PAINT GRIP ROOF, GUTTER, DOWNSPOUT Color



BRONZE MARVIN INTEGRITY Window Color



UMBRA GREY
MHB Steel Window Color