FIRE DEPT. CONNECTION AT WALL

FIRE DEPT. CONNECTION FREE STANDING

X WALL TAG FOR NEW OR INFILL WALLS, RE: A5.0

EXISTING EXPOSED CONCRETE

NEW EXPOSED CONCRETE

NEW STRUCTURAL FLOOR

1 HOUR FIRE BARRIER (IBC 707)

1 HOUR FIRE PARTITION (IBC 708)

• • • • • • 30 MINUTE SMOKE PARTITION (IBC 708)


30 MINUTE FIRE PARTITION (IBC 708)

NEW TILE

the supervision of Paul C is not to be used for regu approval, permitting, or construction purposes.

ISSUED DATE PROJECT NUMBER

ASI-06



DRAWING LEGEND

EXISTING WALL TO REMAIN

NEW CONSTRUCTION

NEW DOOR

EXISTING TILE

EXISTING DOOR TO REMAIN (U.N.O)

AREA BELOW GRADE LEVEL

EXISTING WOOD FLOORING

RESTORATION NOTES

2. NEW HVAC THROUGHOUT.

THROUGHOUT.

TO REMAIN IN PLACE.

FABRICATED TO MATCH EXISTING.

3. NEW PLUMBING THROUGHOUT.

THROUGHOUT. REFER TO FIRE PLAN.

DECAYED AND DAMAGED FLOOR FRAMING.

5. NEW FIRE SPRINKLER SYSTEM TO BE INSTALLED

REPLACEMENT OF HISTORIC CERAMIC FLOOR TILE.

10. PATCH, REPAIR, AND REFINISH WOOD TRIM.

1. FOUNDATION TO BE REPAIRED THROUGHOUT. REPLACE ALL

4. GAS LINES AND SUPPLY TO BE INSPECTED AND REPLACED

6. EXISTING WOOD FLOORS TO REMAIN ARE TO BE SANDED AND RESEALED W/ DURABLE MATTE SEALER THROUGHOUT. RE:

7. EXISTING TILE FLOORS TO REMAIN ARE TO BE REGROUTED

INTERIOR STANDARDS PRESERVATION BRIEF 40 FOR REPAIR AND

8. REMNANTS OF OLD CALL SYSTEM THROUGHOUT THE HOUSE

AND REPAIRED AS REQUIRED. REFER TO SECRETARY OF THE

9. DOOR HARDWARE TO BE REMOVED, CATALOGUED,

REPAIRED AND REPLACED IN SAME PLACE THROUGHOUT. IF HARDWARE CANNOT BE REPAIRED NEW HARDWARE TO BE

11. ALL WINDOWS ARE TO BE INSPECTED FOR WOOD ROT,

REPLACE ANY ROTTEN WOOD IN KIND. SEAL SHUT FROM EXTERIOR. INTERIOR FINISH TO MATCH ADJACENT WALLS. LEVEL



A-A5.5

FLOOR DRAIN -

FIRE RISER ROOM

SPRINKLER RISER

FLOOR DRAINS RE: PLUMB.

MECHANICAL UNITS, TYP.

DUMB WAITER, RE: SPECS AND DETAIL 4/A-A5.6

AREA BELOW GRADE


RE: PLUMB.


6' - 1 3/8"

1/A-SK5.4

EXISTING STEM WALL

A-A1.1
FIRST FLOOR







FIRE DEPT. CONNECTION AT WALL

FIRE DEPT. CONNECTION FREE

X WALL TAG FOR NEW OR INFILL WALLS, RE: A5.0

STANDING

EXISTING EXPOSED CONCRETE

NEW EXPOSED CONCRETE

NEW STRUCTURAL FLOOR

1 HOUR FIRE PARTITION (IBC 708)

● ● ● ● ● ■ 30 MINUTE SMOKE PARTITION (IBC 708)

30 MINUTE FIRE PARTITION (IBC 708)

1 HOUR FIRE BARRIER (IBC 707)

NEW TILE

REPAIR/REPLACE DAMAGED WINDOW TRIM TO MATCH ORIGINAL _____ - NEW FLOOR STRUCTURE & SPRINKLER RISER — FLOORING TO MATCH existing, re: structural r------LINE OF ROOF ABOVE LINE OF ROOF ABOVE — _____ LIMIT OF CONSTRUCTION LIMIT OF CONSTRUCTION ______ — D.S. - INDICATES EXISTING GUEST BATH MRS PERRY'S BATH DOWNSPOUT TO REMAIN, A-A4.3REPAIR AS REQUIRED, TYP. L-----GUEST BEDROOM — ARCHED C.O. _/_ - - - - - - - - - -PATCH AND REPAIR MAID'S SUITE EXISTING PLASTER -NEW ARCHED EXISTING MTL. HVAC SEAL OFF SHAFT TO FLOOR AND WALL SHAFT BELOW, KEEP MR & MRS PERRY'S LIVING GRILLE TO REMAIN existing - PRESERVE EXISTING PASS ROOM A-208 DUMBWAITER BOX THROUGH & RAILING -MRS PERRY'S BEDROOM AT THIS LEVEL TO BE SEAL OFF W/ 30MIN FIRE MR PERRY'S BEDROOM RATING SON'S SUITE re-used as cabinet SON'S BEDROOM SITTING ROOM - PATCH AND REPAIR EXISTING PLASTER – PATCH AND REPAIR EXISTING PLASTER -- REPAIR DAMAGED DOOR TRIM RE: SPEC NEW FABRIC AWNING - RE: SPEC -MR PERRY'S BATH - PATCH AND REPAIR EXISTING PLASTER -_____ REPAIR DAMAGED RE: SPEC REPAIR DAMAGED WINDOW PLASTER AND — PATCH AND REPAIR EXISTING KEEP EXISTING DOOR, HARDWARE AND BASE TRIM AS WINDOW TRIM INSTALL NEW DOOR ON MR. PLASTER PERRY'S SIDE IN EXISTING r----------------REPLACE EXISTING DOOR FRAME -- SEAL EXISTING WINDOW, REMOVE AND FABRIC AWNING SALVAGE MANUAL WINDOW CRANKS, TYP. WITH NEW - RE: SPEC – PATCH AND REPAIR EXISTING PLASTER L-----LIMIT OF CONSTRUCTION NEW STEEL TRELLIS — NOTE: ALL FLOORING TO BE CAREFULLY REMOVED KEEPING AS MUCH AS POSSIBLE TO RE-INSTALL. ADD ACOUSTIC UNDERLAYMENT AND BLOW-IN ACOUSTIC INSULATION BEFORE NEW FLOOR INSTALLATION. REFER TO FL-1 ON A-A5.0 AND SPECIFICAITONS FOR INSULATION.

RESTORATION NOTES

2. NEW HVAC THROUGHOUT.

THROUGHOUT.

TO REMAIN IN PLACE.

FINISH TO MATCH.

FABRICATED TO MATCH EXISTING.

3. NEW PLUMBING THROUGHOUT.

THROUGHOUT. REFER TO FIRE PLAN.

DECAYED AND DAMAGED FLOOR FRAMING.

5. NEW FIRE SPRINKLER SYSTEM TO BE INSTALLED

REPLACEMENT OF HISTORIC CERAMIC FLOOR TILE.

10. PATCH, REPAIR, AND REFINISH WOOD TRIM.

1. FOUNDATION TO BE REPAIRED THROUGHOUT. REPLACE ALL

4. GAS LINES AND SUPPLY TO BE INSPECTED AND REPLACED

6. EXISTING WOOD FLOORS TO REMAIN ARE TO BE SANDED AND RESEALED W/ DURABLE MATTE SEALER THROUGHOUT. RE:

7. EXISTING TILE FLOORS TO REMAIN ARE TO BE REGROUTED

INTERIOR STANDARDS PRESERVATION BRIEF 40 FOR REPAIR AND

8. REMNANTS OF OLD CALL SYSTEM THROUGHOUT THE HOUSE

AND REPAIRED AS REQUIRED. REFER TO SECRETARY OF THE

9. DOOR HARDWARE TO BE REMOVED, CATALOGUED,

REPAIRED AND REPLACED IN SAME PLACE THROUGHOUT. IF HARDWARE CANNOT BE REPAIRED NEW HARDWARE TO BE

11. ALL WINDOWS ARE TO BE INSPECTED FOR WOOD ROT,

REPLACE ANY ROTTEN WOOD IN KIND. SEAL SHUT FROM EXTERIOR. INTERIOR FINISH TO MATCH ADJACENT WALLS. LEVEL 2 LEVER HANDLES TO BE REMOVED, ALL OTHER HARDWARE TO REMAIN. CAP ALL OPENINGS AT HEAD JAMBS WITH WOOD AND DRAWING LEGEND

EXISTING WALL TO REMAIN

NEW DOOR

EXISTING TILE

NEW CONSTRUCTION

EXISTING DOOR TO REMAIN (U.N.O)

AREA BELOW GRADE LEVEL

EXISTING WOOD FLOORING

SECOND FLO