



Historic Review Application

For Office Use Only

Date of Submission: _____

Plan Review #: _____

Property Address: 506 Barton Blvd, Austin TX 78704

Historic Landmark ☒ N/A

Local Historic District ☒ N/A

National Register Historic District ☒ N/A

Historic Landmark Name or N/A

Historic District Name: _____

Applicant Name: Umlauf Sculpture Garden Phone #: 512-445-5582 Email: curator@umlaufsculpture.org

Applicant Address: 605 Azie Morton Rd City: Austin State: TX Zip: 78704

Please describe all proposed exterior changes with location and materials. If you need more space, attach an additional sheet.

PROPOSED CHANGE(S)	LOCATION OF PROPOSED CHANGE(S)	PROPOSED MATERIAL(S)
1) Replace the existing roof with a new 3-tab shingle, and standing seam double lock galvalume roof. This will mimic what is on the roof now, and bring it back to historical context	Exterior roof	Tamko 3-tab shingle, Standing seam galvalume roof.
2) Re-frame the back laundry area, due to rotted 2x material, decking, and fascia needing to be replaced before new shingles is installed.	North facing side of existing house.	Lumber.
3) Point up all exterior masonry cracks due to foundation shift, in order to keep elements from entering interior envelope. Close up underpinning to prevent critter infiltration.	Exterior facade.	Hydraulic Cement, Chopped Limestone.

Submittal Requirements

1. One set of dimensioned building plans. Plans must: a) specify materials and finishes to be used, and b) show existing and proposed conditions for alterations and additions.

Site Plan ☐ Elevations ☐ Floor Plan ☐ Roof Plan ☐

2. Color photographs of building and site:

Elevation(s) proposed to be modified ☐ Detailed view of each area proposed to be modified ☒

Applicant Signature: Kee Rish

17 June 2020
Date: _____

UMLAUF – Heritage
Grant 2018 Roof
replacement/repair
506 Barton Blvd
Austin TX 78704

Existing shingles:
southeast slope



UMLAUF – Heritage
Grant 2018 Roof
replacement/repair
506 Barton Blvd
Austin TX 78704

Existing shingle roof –
west slope



UMLAUF – Heritage
Grant 2018 Roof
replacement/repair
506 Barton Blvd
Austin TX 78704

Existing shingle roof –
south and eastern
slopes



UMLAUF – Heritage
Grant 2018 Roof
replacement/repair
506 Barton Blvd
Austin TX 78704

Metal roof, west slope
with flashing and
limestone



UMLAUF – Heritage
Grant 2018 Roof
replacement/repair
506 Barton Blvd
Austin TX 78704

Existing metal roof –
north slope



UMLAUF – Heritage
Grant 2018 Roof
replacement/repair
506 Barton Blvd
Austin TX 78704

Existing metal roof –
rusted vents and
flashing



UMLAUF – Heritage
Grant 2018 Roof
replacement/repair
506 Barton Blvd
Austin TX 78704

Existing metal roof –
rusted vents and
flashing



UMLAUF –
Heritage
Grant 2018
Roof
replacement/
repair
506 Barton
Blvd
Austin TX
78704

Existing
shingle
roofing
South slopes
and ridge



UMLAUF – Heritage
Grant 2018 Roof
replacement/repair
506 Barton Blvd
Austin TX 78704

Existing shingle ridge



UMLAUF – Heritage
Grant 2018 Roof
replacement/repair
506 Barton Blvd
Austin TX 78704

Underside of rotten
eaves



UMLAUF –
Heritage Grant
2018 Roof
replacement/repair
– back porch



UMLAUF –
Heritage
Grant 2018
Roof
replacement/
repair – back
porch viewed
from east



UMLAUF – Heritage Grant
2018 Roof
replacement/repair – back
porch dilapidation



UMLAUF –
Heritage Grant
2018 –
Hole under
porch



UMLAUF –
Heritage
Grant 2018
Roof
replacement/
repair –
Cracks in
limestone

