

Photos of Existing Structure



Rotted cedar stump post



CMU blocks used as posts



Cracks from shifting foundation



Compromised wall system



Front Facade



West Facade



East Facade



Back