



Order Summary

dba: RENEWAL BY ANDERSEN OF AUSTIN

Legal Name: CL Cashion Enterprises, LLC | License #
2100 Kramer Lane, Suite 600 | Austin, TX 78758

Phone: 512-834-8383 | Fax: 512-490-0011 | SalesAUS@thebestwindow.com

Measure Tech: Jake Guy, (480)784-7682

CHRIS & GAYDEN BRECKWOLDT

1504 Westover Rd

Austin, TX 78703

H: (512)845-8170 | C:

ID#	ROOM	SIZE	DETAILS
JOB			
101	Room 1 Dinningg	70" 60" 63 7/8" x 61 1/2"	Window: Picture, Insert Frame, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 6w x 5h Misc: Rework Buck Frame (inc P/S), I22, f7 Construction: None Material: None
102	dining	30" 60" 30 5/8" 61 1/8" 3/4	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7 Construction: None Material: None
103	dining	30" 60" 30 5/8" 61 1/8" 30 3/4" 61 3/4" 3/4	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7 Construction: None Material: None Rot New Sill
104	kitchen	31" 45" 30 5/8" 45 3/4"	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: Fiberglass, Full Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7 Construction: None Material: None
105	kitchen	31" 45" 30 5/8" 45 3/4"	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: Fiberglass, Full Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7 Construction: None Material: None



Order Summary

dba: RENEWAL BY ANDERSEN OF AUSTIN

Legal Name: CL Cashion Enterprises, LLC | License #
2100 Kramer Lane, Suite 600 | Austin, TX 78758

Phone: 512-834-8383 | Fax: 512-490-0011 | SalesAUS@thebestwindow.com

Measure Tech: Jake Guy, (480)784-7682

CHRIS & GAYDEN BRECKWOLDT

1504 Westover Rd

Austin, TX 78703

H: (512)845-8170 | C:

ID#	ROOM	SIZE		DETAILS
106	liv	36"	70"	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: No Grille Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None 34 3/4 68 5/8
107	liv	36"	70"	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: No Grille Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None 34 3/4 68 5/8
108	liv	36"	70"	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: No Grille Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None 34 3/4 68 5/8
109	game room	70"	60"	Window: Picture, Insert Frame, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 6w x 5h Misc: Rework Buck Frame (inc P/S), I22, f7 Construction: None Material: None 61 1/2 34 5/8
110	game room	36"	60"	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None 30 3/4 61 3/4 34



Order Summary

dba: RENEWAL BY ANDERSEN OF AUSTIN

Legal Name: CL. Cashion Enterprises, LLC | License #
2100 Kramer Lane, Suite 600 | Austin, TX 78758

Phone: 512-834-8383 | Fax: 512-490-0011 | SalesAUS@thebestwindow.com

Measure Tech: Jake Guy, (480)784-7682

CHRIS & GAYDEN BRECKWOLDT

1504 Westover Rd

Austin, TX 78703

H: (512)845-8170 | C:

ID#	ROOM	SIZE	DETAILS
111	front room	36" 60"	<i>Handwritten: 30 3/4 61 5/8</i> Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None
112	front room	70" 60"	<i>Handwritten: 63 7/8 61 3/8 3/4</i> Window: Picture, Insert Frame, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 6w x 5h Misc: Rework Buck Frame (inc P/S), I22, f7 Construction: None Material: None
114	stairs	70" 60"	<i>Handwritten: 63 1/4 61 3/4 63 7/8</i> Window: Picture, Insert Frame, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern, Tempered Glass Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 6w x 5h Misc: Rework Buck Frame (inc P/S), I22, f7 Construction: None Material: None
115	girls room	36" 60"	<i>Handwritten: 30 7/8 3/4 60 3/4 60 3/4</i> Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None
116	girls room	36" 60"	<i>Handwritten: 30 7/8 3/4 60 3/4 61 5/8</i> Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None



Order Summary

dba: RENEWAL BY ANDERSEN OF AUSTIN

Legal Name: CL Cashion Enterprises, LLC | License #

2100 Kramer Lane, Suite 600 | Austin, TX 78758

Phone: 512-834-8383 | Fax: 512-490-0011 | SalesAUS@thebestwindow.com

Measure Tech: Jake Guy, (480)784-7682

CHRIS & GAYDEN BRECKWOLDT

1504 Westover Rd

Austin, TX 78703

H: (512)845-8170 | C:

ID#	ROOM	SIZE	DETAILS
117	girls room	36" 60" 30 3/4 61 3/4	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None
118	girls room	36" 60" 30 3/4 61 3/4	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None
119	george	36" 60" Facing Back 30 3/4 61 3/4	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None
120	george	36" 60" Facing front 30 3/4 61 5/8	Window: Double-Hung, 1:1, Flat Sill Insert, Contemporary Checkrail, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Hardware: Canvas Screen: No Screen Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 3w x 2h Misc: Rework Buck Frame (inc P/S), I22, f7, Blinds, i19 Construction: None Material: None
121	george	70" 60" Facing side 63 7/8 61 1/2	Window: Picture, Insert Frame, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 6w x 5h Misc: Rework Buck Frame (inc P/S), I22, f7 Construction: None Material: None



Order Summary

dba: RENEWAL BY ANDERSEN OF AUSTIN

Legal Name: CL Cashion Enterprises, LLC | License #

2100 Kramer Lane, Suite 600 | Austin, TX 78758

Phone: 512-834-8383 | Fax: 512-490-0011 | SalesAUS@thebestwindow.com

Measure Tech: Jake Guy, (480)784-7682

CHRIS & GAYDEN BRECKWOLDT

1504 Westover Rd

Austin, TX 78703

H: (512)845-8170 | C:

ID#	ROOM	SIZE	DETAILS
		0" 0"	Misc: Misc, Processing Fee, <Enter Description Here> Construction: None Material: None
113	front room	70" 60" 63 7/8 61 7/4	Window: Picture, Insert Frame, Exterior Canvas, Interior Canvas Glass: All Sash: High Performance SmartSun Glass, No Pattern Grille Style: Simulated Divided Light (FDL w/o spacer) Grille Pattern: All Sash: Colonial 6w x 5h Misc: Rework Buck Frame (inc P/S), I22, f7 Construction: None Material: None

PRODUCTS: 22 WINDOWS: 21 PATIO DOORS: 0 SPECIALTY: 0 MISC: 1

Updated 7/26/20

JOB NOTES

Estimated Duration:

FLOORPLAN - 1ST FLOOR




UNIT NOTES

<Enter Description Here>


Do not remove until final code inspection. Save label for future reference.

ENERGY STAR® Certified in Highlighted Regions
Certifié ENERGY STAR dans les régions en surbrillance

Canada
 energystar.gc.ca



U.S. / É.U.
 energystar.gov



ER/RE 20



**Renewal
 by Andersen**
 WINDOW REPLACEMENT an Andersen Company



AND-N-36-00595-00001
 Vinyl/Wood Composite Material
 Dual-Pane HP-SmartSun with Argon
 Product Type: Picture

ENERGY PERFORMANCE RATINGS

U-Factor
0.271
 (U.S./I-P)

Solar Heat Gain Coefficient
0.23
 (Metric/SI) *max*

ADDITIONAL PERFORMANCE RATINGS

Visible Transmittance
0.53

Manufacturer stipulates that these ratings conform to applicable NFRC procedures for determining whole product performance. NFRC ratings are determined for a fixed set of environmental conditions and a specific product size. NFRC does not recommend any product and does not warrant the suitability of any product for any specific use. Consult manufacturer's literature for other product performance information.
 www.nfrc.org

WINDOW & CURTAIN
 MANUFACTURERS ASSOCIATION
WDMA
 Hallmark Certified
 www.wdma.com

Licensee: 129-H-723.03 129-H-723.04

Andersen Corporation
 RbA Picture Window

Manufacturer stipulates certification to the applicable standards.


STANDARD	RATING
AAMA/WDMA/CSA 101/I.S.2/A440-08	Class LC-PG50 Size Tested: 48.0x48.0 in DP +50/-50
AAMA/WDMA/CSA 101/I.S.2/A440-05	FW-LC5048.0 inx48.0 in
AAMA/WDMA/CSA 101/I.S.2/A440-08 A440S1-09	Class LC-PG50 Size Tested: 1219x1219 mm; Positive/Negative Design Pressure (DP): 2400 Pa Water Penetration Resistance Test Pressure: 360 Pa Canadian Air Infiltration/Exfiltration: Fixed

ENERGY STAR® Certified in Highlighted Regions
Certifié ENERGY STAR dans les régions en surbrillance

Canada
 energystar.gc.ca



U.S. / É.U.
 energystar.gov



ER/RE 11

DO NOT REMOVE UNTIL FINAL INSPECTION/NE PAS RETIRER AVANT L'INSPECTION FINALE



**Renewal
 by Andersen**
 WINDOW REPLACEMENT an Andersen Company



AND-N-28-02026-00001
 Vinyl/Wood Composite Material
 Dual-Pane with Argon
 Product Type: Double Hung

ENERGY PERFORMANCE RATINGS

U-Factor
0.31
 (U.S./I-P)

Solar Heat Gain Coefficient
0.19
 (Metric/SI)

ADDITIONAL PERFORMANCE RATINGS

Visible Transmittance
0.29

Manufacturer stipulates that these ratings conform to applicable NFRC procedures for determining whole product performance. NFRC ratings are determined for a fixed set of environmental conditions and a specific product size. NFRC does not recommend any product and does not warrant the suitability of any product for any specific use. Consult manufacturer's literature for other product performance information.
 www.nfrc.org

WINDOW & CURTAIN
 MANUFACTURERS ASSOCIATION
WDMA
 Hallmark Certified
 www.wdma.com

Licensee: 129-H-835.06 129-H-835.07

Andersen Corporation
 RbA Double-Hung

Manufacturer stipulates certification to the applicable standards.

STANDARD	RATING
AAMA/WDMA/CSA 101/I.S.2/A440-08	Class A-PG25 Size Tested: 45x77 in DP +35/-35
AAMA/WDMA/CSA 101/I.S.2/A440-05	H-R2545x77+35/-35
AAMA/WDMA/CSA 101/I.S.2/A440-08 A440S1-09	Class A-PG25 Size Tested: 1143x1955mm Positive/Negative Design Pressure (DP): 1680 Pa Water Penetration Resistance Test Pressure: 25 Canadian Air Infiltration/Exfiltration: R2