D-7/1-PRESENTATION

904 Avondale Rd.

Application for Variance -Screened porch encroaching into front yard setback & Variance for nonconforming use (substandard lot size).

Owners: Frank and Jeannine Clark.




^{*}Frank is a restoration carpenter with 25 years of experience.

^{*}Jeannine is an interior designer.

^{*}This is our retirement home.

D-7/2-PRESENTATION



LOCATION:
904 Avondale.
Travis Heights
Neighborhood.
Between Travis
Heights Blvd &
Alta Vista Avenue.
South of Riverside
Drive.

D-7/3-PRESENTATION

EXISTING



This corner of the porch intersects the required front yard setback from 25' to 17

Existing porch footprint to remain.

New Porch with roof extension and screens, open on two sides. New porch will not extend past the current street-side face of the home.

Coverage area: approx. 8' x 16'.



D-7/4-PRESENTATION

Current condition:


Existing 1949 vintage 'small home' Cottage—594 square feet, 1 bedroom.

Goal:

- Restoration of the existing home to conform to the character of the neighborhood without adding interior square footage.
- Add screened front porch as part of the renovations. (at existing non-enclosed front porch).

Conflicts which require variance:

- A triangle portion of the proposed screened porch encroaches the required 25' front yard setback per LD Code 25-2-513G. Request to reduce setback in this area to align with front of existing home, approx. 17' from property line.
- LD Code 25-2-947. Lot size is 5292 s.f., which is a non conforming size lot.



D-7/5-PRESENTATION

HARDSHIP SUMMARY


There is, quite literally, no other location we can add this screened porch, and the porch is vital to the enjoyment of our tiny home.

The shape of the lot: The pie-shape creates a very small area for any construction due to the lot depth and angles of the setbacks. The angle of the front setback cuts through a portion of the porch and house since the lot is so shallow on the short end; therefore the buildable area is severely restricted.

The size of the lot: The lot is considered substandard by the current city code since it does not meet the minimum lot depth or size. The lot is measured at 5,292 SF. In many other areas of town, the city has acknowledged the need to provide a means of developing on small lots and therefore allows small lot amnesty; however in our case, the small lot amnesty is not applicable due to the neighborhood not adopting the code, and limits the amount of improvements. The improvements will be in character of the neighborhood and do not increase the conditioned square footage of the existing house.

Heritage trees: There are three heritage Live Oak Trees on the property. In order to limit the adverse effects of building around the trees, construction impact must stay out of the 1/2 CRZ. Taking into account the critical root zones of the trees, the allowable site disturbance is very limiting.

Topography of the lot: There is 21 feet of vertical grade change on the property. The lot is measured at 5,292 SF, so the slope is significant. This limits the location options for a screened porch. In addition to the above mentioned constraints, the flattest portion of the property is where the front porch is located.



D-7/6-PRESENTATION






Photo showing lot slope

Photo showing our largest Live Oak Tree

D-7/7-PRESENTATION



We have the full support of our closest neighbors!

