

SPICEWOOD SPRINGS ROAD REGIONAL MOBILITY IMPROVEMENTS

Wastewater Rehabilitation in Critical Natural Resources


CONNECTING YOU ALL AROUND AUSTIN














Project Location / Background



- Identified Needing Rehabilitation
 - Approx. 779 LF 18" Concrete Pipe and Manholes (Built 1972)

Critical Pipe Characteristics

- Critical Condition- A failure may impact health & safety
- Possible obstruction in pipe
- Pipe is in the bed of tributary of Bull Creek.

Location Characteristics

- Edwards AquiferRecharge Zoneaccording to City ofAustin
- Golden-cheekedWarbler Zone 1
- Endangered CaveSpecies Habitat Karst –Zone 1

- Location Characteristics
 - Erosion Hazard
 Zone
 - Critical WaterQuality Zone
 - BCCP zone
 - Threatened Salamanders in creek
 - > 100 YR Floodplain



Cured-In-Place Pipe Rehabilitation

- Approx. 779 LF 18" pipe to be rehabilitated
- Use one manhole MH#40115 to insert liner and other manhole MH#40391 to capture liner
- Minimal impact to Environment
- Bypass pumping pipe to be routed through the top culvert to minimize impact to salamanders and traffic
- Construction method eliminates the need for US Fish and Wildlife permit
- Increase life of pipe with minimal disturbance to creek



PROJECT DETAILS

Construction Cost Estimate	\$250,000
Area of Parkland needed for temporary use:	1,066 sq. ft. for work area. 6,138 sq. ft. for staging area
Permitting	Site Plan Development Permit, Temporary traffic control permit from TxDOT, Balcones Conservation Canyon Preserve, Stormwater Pollution Prevention Plan.
Design & Permitting Duration	6 months
Construction Duration	2 weeks installation; One-month total construction time
Construction Method	Cured in place Rehabilitation
Tree Impact	Trim trees for clearance
Public Impact	Block section of Trail and parking lot while rehabilitating segment in Parkland and during spoils removal.