### 1104 Charlotte St

Kindra Welch and family



720 sqft

Structural Board-Batten Siding,

Original front porch,

original front door,

3 out of 8 original windows











minor structural issues with original Juniper piers

1. Eastern front corner sits directly on the ground enabling deterioration of wood structure and a near constant termite invasion



#### 2. Driveway slopes towards the house



3. The house is the focal point of 12th street traffic, including restaurant and retail traffic from commercial area 1 block away. New Years Eve '03-'04 a driver crashed his truck through the front wall and into the living room.






- 1. One corner sits directly in contact with the ground.
- 2. Driveway slopes towards the house
- 3. The house is the focal point of 12th street traffic.


#### LONG TERM SOLUTION:

Significantly Raise the House


(And hopefully maintain Historic Contributing Status)




#### **EXISTING SITEPLAN**



#### DEMO BACK PORCH



## PUSH HOUSE AWAY FROM THE STREET APPROX. 4'-4" AND RAISE UP 6'-7'



# PROPOSAL "NORTH DRIVEWAY"



VIEW FROM THE EAST "NORTH DRIVE"



VIEW FROM THE SOUTHEAST "NORTH DRIVE"




VIEW FROM THE SOUTH "NORTH DRIVE"

#### .38, W N 31°32'36" E 38.13' wood fence 10, 8 POND #127 dition #122 8D cre . ft. wood deck 59"34'59" ONE STORY HOUSE finished floor elev. 101.94' 109.93 = 436.50' 3.12' (58.08') 58.08' (58.04') 534'12" W Found 1/2" Iron Rod Radius = 436.50' Arc = 53.83' (53.84')

#### SECOND SITEPLAN PROPOSAL

"SOUTH DRIVE"

PUSH HOUSE ABOUT 6' INTO CURRENT DRIVEWAY AND MOVE DRIVEWAY TO OPPOSITE SIDE OF THE HOUSE






VIEW FROM THE EAST "SOUTH DRIVE"




VIEW FROM THE SOUTHEAST "SOUTH DRIVE"



VIEW FROM THE SOUTH "SOUTH DRIVE"













Neighborhood context

#### Neighborhood context

