



NON-ORIGINAL ALTERATIONS AT DEEPER COVERED PORCH ROOF SUPPORT BEAMS, SHORTENED COLUMNS AND PLYWOOD AT COVERED PORCH CEILING.



DETERIORATING FOUNDATION, METAL SKIRT AT PORCH DECK AND EXPOSED SOIL STACK.



REPLACE NON-ORIGINAL SIDE ENTRANCE DOOR



REFRESH FRONT ENTRANCE DOOR