


EAST ELEVATION (BAYLOR STREET)



SOUTH ELEVATION (PARTIAL)



OBLIQUE SOUTH AND WEST ELEVATIONS – AREA OF NEW STAIRS AND WOOD STRUCTURE REPAIR




WEST ELEVATION



NORTH ELEVATION (PARTIAL) W. 6TH ST.



NORTH ELEVATION (PARTIAL) W. 6TH ST.



DAMAGE TO STRUCTURE AND DECKING OF UPPER GALLERY



INTERIOR DAMAGE TO BE REPAIRED – TYPICAL AT WINDOWS AND BASEBOARDS



SW SILL, DECK, STRUCTURE AND WALL DAMAGE – TYPICAL WEST WOODEN STRUCTURE



FOUNDATION DAMAGE – SOUTH WEST CORNER



SEALANT AND INAPPROPRIATE MORTAR TO BE REMOVED AT HISTORIC BRICK ADDITION



DETERIORATED WOOD INFILL ON WEST. NEW WINDOWS AND SCREENS TO MATCH EXISTING



HISTORIC PHOTO CIRCA 1974