

1 SITE PLAN
1/8" = 1'-0"

ELEMENT 5 ARCHITECTURE

RESIDENTIAL & HOSPITALITY ARCHITECTURE & PLANNING

1212 Chicon Street Ste. 101
Austin, TX 78702
(512) 473. 8228 Voice

www.element5architecture.com

THIS SET OF DRAWINGS IS FOR INTERIM REVIEW ONLY THIS DOCUMENT IS INCOMPLETE


NOT FOR REGULATORY APPROVAL / PERMITTING / BIDDING OR CONSTRUCTON NICK MEHL REGISTRATION NO. 17752


MONROE RESIDENCE

407 E MONROE AUSTIN, TX 78704

SITE PLAN

A1.0





1446 SF

1 BASEMENT FLOOR
1/4" = 1'-0"

2 FIRST FLOOR
1/4" = 1'-0"

ELEMENT 5
ARCHITECTURE
RESIDENTIAL & HOSPITALITY

RESIDENTIAL & HOSPITALITY ARCHITECTURE & PLANNING

1212 Chicon Street Ste. 101 Austin, TX 78702 (512) 473. 8228 Voice

www.element5architecture.com

THIS SET OF DRAWINGS IS
FOR
INTERIM REVIEW ONLY
THIS DOCUMENT IS
INCOMPLETE

NOT FOR REGULATORY APPROVAL / PERMITTING / BIDDING OR CONSTRUCTON NICK MEHL REGISTRATION NO. 17752

MONROE RESIDENCE

407 E MONROE AUSTIN, TX 78704

FLOOR PLANS

A2.0





952 SF

3 SECOND FLOOR
1/4" = 1'-0"

4 ATTIC FLOOR
1/4" = 1'-0"

ELEMENT 5 ARCHITECTURE

RESIDENTIAL & HOSPITALITY ARCHITECTURE & PLANNING

1212 Chicon Street Ste. 101 Austin, TX 78702 (512) 473. 8228 Voice

www.element5architecture.com

THIS SET OF DRAWINGS IS FOR INTERIM REVIEW ONLY

THIS DOCUMENT IS INCOMPLETE

NOT FOR REGULATORY APPROVAL / PERMITTING / BIDDING OR CONSTRUCTON


NICK MEHL REGISTRATION NO. 17752

MONROE RESIDENCE

407 E MONROE AUSTIN, TX 78704

FLOOR PLANS

A2.1



1 ROOF PLAN
1/4" = 1'-0"

ELEMENT 5 ARCHITECTURE

RESIDENTIAL & HOSPITALITY ARCHITECTURE & PLANNING

1212 Chicon Street Ste. 101 Austin, TX 78702 (512) 473. 8228 Voice

www.element5architecture.com

THIS SET OF DRAWINGS IS
FOR
INTERIM REVIEW ONLY
THIS DOCUMENT IS
INCOMPLETE

NOT FOR REGULATORY APPROVAL / PERMITTING / BIDDING OR CONSTRUCTON NICK MEHL REGISTRATION NO. 17752

MONROE RESIDENCE


407 E MONROE AUSTIN, TX 78704

ROOF PLAN

A2.2










METAL SIDING & ROOF

EXTERIOR MATERIALS



STUCCO -STUCCO STUCCO

2 EAST ELEVATION

1/4" - 1' 0"

ARCHITECTURE

RESIDENTIAL & HOSPITALITY ARCHITECTURE & PLANNING 1212 Chicon Street Ste. 101 Austin, TX 78702 (512) 473. 8228 Voice

www.element5architecture.com

THIS SET OF DRAWINGS IS FOR INTERIM REVIEW ONLY THIS DOCUMENT IS INCOMPLETE

NOT FOR REGULATORY APPROVAL / PERMITTING / BIDDING OR CONSTRUCTON NICK MEHL REGISTRATION NO. 17752

MONROE RESIDENCE

407 E MONROE AUSTIN, TX 78704

EXTERIOR ELEVATIONS

A3.0

© COPYRIGHT 2019 , E5A . ALL RIGHTS RESERVED

1 SOUTH ELEVATION










METAL SIDING & ROOF

EXTERIOR MATERIALS



RESIDENTIAL & HOSPITALITY
ARCHITECTURE & PLANNING

1212 Chicon Street
Ste. 101
Austin, TX 78702
(512) 473. 8228 Voice

www.element5architecture.com

THIS SET OF DRAWINGS IS
FOR
INTERIM REVIEW ONLY

THIS DOCUMENT IS
INCOMPLETE

NOT FOR REGULATORY
APPROVAL / PERMITTING /
BIDDING OR CONSTRUCTON

BIDDING OR CONSTRUCTON NICK MEHL REGISTRATION NO. 17752

MONROE RESIDENCE

407 E MONROE AUSTIN, TX 78704

EXTERIOR ELEVATIONS

A3.1

5/17/22, 3:24 PM Back Side.jpg



5/17/22, 3:25 PM Detail 1.jpg



04/08/2022

Oam Parkash & Eva Khazana 512.945.0788 Austin, Texas

Dear Mr. Parkash & Ms. Khazana,

On 05 April 2022, R. Derek Hammond of RDH C&E performed a site observation to 407 E. Monroe Street in Austin, Texas to view the condition of the existing ADU. Based on the site observations, and calculations it appears the roof, attic, and portions floor framing are over spanned and insufficient for code required loading. Sagging in framing, cracking within the veneer, and rotting within the soffit and around the bottom plate were also observed. Roof & upper attic framing would all need to be removed and replaced or reinforced with additional framing and bracing. The 4x6 2nd floor framing support was also found to be deficient and would need to be reinforced or removed and replaced. Rotting was noted around the perimeter of the building due to the proximity of grade to the bottom plate of the wall. Termite damage was confirmed, and all wall framing at was damaged would need to be replaced.

The following report details site observations, conclusions and recommendations for the structure. If you have any questions, please do not hesitate to contact us. Thank you for the opportunity to provide these services to you. If we have erred in our understanding of the work feel free to contact me and we will be happy to adjust and resend,

Respectfully,



R. Derek Hammond, PE Owner RDH C&E LLC

General Conditions

The existing apartment dwelling unit (ADU) was located at 407 East Monroe in Southwest Austin, Texas. The front of the residence faces north, toward East Monroe. The residence is located East of I-35 approximately 2 miles and south of Lady Bird Lake approximately 1 mile. The existing structure was a two story, stick framed structure resting on concrete stem walls with a slab on grade foundation.

email: rhammond@RDHCE.com

phone: 956.367.5561

Structure Composition

Roof and attic framing were composed of 2x4's at 24" OC. Hip and ridge beams were also 2x4 framing members. Floor and roofs were decked with ship lap boards and wall covering. The lateral system appeared to be braced walls. Wall sheathing and wall framing at the second floor were concealed and unable to be view during the observation. The second floor framing was composed of 2x8's at 16" on center (OC) resting on a 4x6 beam that ran the length of the building parallel to the front of the building. The concrete stem walls were approximately 2'-0" to 3'-0" tall and retained soil from the South and West sides. Reinforcement within the slab and stem wall were unable to be determined.

Structural Issues/Deficiencies

Roof framing and attic framing (2x4's at 24") were determined to be deficient for code required live and dead loading. Ridge and hip beams were also undersized and would need to be increased in size, or braced from walls below. The 2x8 floor framing is adequately sized provided no additional point loading is added to it from the roof above. The 4x6 framing carrying the 2x8's however were undersized for the required loading. The 4x6 beam center support was concealed from view and unable to be confirmed, a 4x4 post and foundation would be required for the loading.

Soils around the South and West sides were observed to be above the bottom plate of the wooden portions of the exterior wall framing. Cracking was observed in the skirting around the base of the home and sand bags were present to mitigate water infiltration. Wall framing was obscured from view, but is likely rotted due to the evidence of water infiltration over a long period of time. Rotting soffits were also noted around the perimeter of the ADU as well as evidence of settling, namely cracking around openings.

Termite damage had been confirmed within the walls, further investigation would be necessary to determine wall framing adequacy. Where damage or insufficient framing and/or sheathing attachments are discovered, removal and replacement would be recommended.

Conclusions

Roof framing, sheathing, attic framing and wall framing are deficient for current code required loading and likely water and/or termite damaged, respectively. Roof framing members and attic framing would need to be upgraded to 2x6 framing at the roof, 2x10's at the attic, and ridges would need to be reinforced, and possibly braced off of the interior walls. Bracing off of walls would require the 2x8 floor framing to be upgraded to support the added point loading from the roof bracing. The 4x6 framing



supporting the floor framing would need to be removed and replaced with a larger beam, but may create head height issues, so special consideration will need to be taken. Damaged walls and sheathing would need to be replaced, and evidence of damage was noted around the entire exterior.

email: rhammond@RDHCE.com

phone: 956.367.5561

Roof, attic framing, and primary 2nd floor framing support were noted as deficient, some to severe degrees. Removal and replacement would be necessary to a large portion of ADU wood framing. Headers were concealed from view and unable to be confirmed, but will also likely require replacement as well. Foundations and stem walls appeared in tact, however reinforcement (if any) was not confirmed, nor slab depth, grade beam depth, or the existence of spread footings below the interior support for the second floor framing. Further investigation would be necessary, but after trenching for plumbing, water proofing for the retaining wall, and re-grading to avoid water infiltration on the rear, it may be more economical to demo the slab and stem walls as well. Shoring or replacement of the 4x6 beam would be recommended to avoid safety issue for any work crews prior to working on the ADU.



Figure 1: 2x4 roof framing at 24", 2x4 ridge beam, and 2x4hip beam, note lack of vertical support at hip to ridge connection.



Figure 2: 2x8 floor framing at 16".



Figure 3: Rear wall, SW corner, sand bags, and soil built up above bottom plate.



Figure 4: Rotting soffit and crack stucco veneer on rear wall



Figure 5: Rotted soffit on West side of ADU.



eva konvit <eva@designtreehome.com>

A-Tex Pest Management

1 message

Chris Roddy <cratexpest@gmail.com> To: eva@designtreehome.com

Fri, Apr 1, 2022 at 9:58 AM

Hi this is Chris with A-Tex Pest Management. I am the one who performed the termite inspection for both 407 and 409 Monroe. I have sent over a treatment plan for both including treatment around the detached garage. I highly recommend a treatment due to all the conducive conditions for example wood touching the ground which also hides areas during the inspection. Also the condition of the wood sitting on all 3 structures is in poor condition which attracts termites. While on site I saw no evidence or proof a treatment had been done so in those cases we recommend having the property treated and in tern will provide protection. The product we use states it provides protection against termites for up to 15 years and will also eliminate and existing termites in 90 days. I hope this recommendation email helps and we look forward to your business.

Thanks, Chris

Sent from my iPad



Thank you for choosing A-TEX PEST MANAGEMENT INC!

Welcome to our newly featured customer portal, for your convenience you may pay your bill from here, see your service history and invoice details as well, it is our goal to provide as many tools as possible to make your service experience with us 2nd to none! Thank you for allowing us to serve you!

Please review the following document and then sign. You will receive a copy via email for your records. Thank you!



A https://www.atexpest.com P.O. Box 80081 - Austin, Texas 78708

	PEST N	IANAGEMENT		428-6967 L#12357		MAPSCO
			11 0	L# 12331		
3/30/22			EVA CONVIT			
Date		-	Account Name			
EVA CONVIT			407 E MONRO	E ST		
Billing Name			Service Address			
407 E MONROE ST	Γ		Austin		TX	78704
Billing Address			Service City		State	Zip
Austin	TX	78704	(512) 751-566			
Billing City	State	Zip	Service Phone #			Person To Contact
(512) 751-5667		Damasa Ta Camtast	eva@designtr Email	eenome.com		
Billing Phone #		Person To Contact				
"Customer" (the buyer under the "service add). The Company agree lress" and to guarante	Termite Servind the party indicated above to finish Eastern Subtrement for a per	ove and hereinafter refer erranean termite control riod of one year from the	red to as the "C service to the s	structure(s)	specified above
Subject to any limitation	<u>Limited Life</u> s or restrictions set forth	and Conditions" on the betime Renewable Ten in the graph, specification terment obligates the compared to the	ermite Re-Treatme	to the General te	erms and con	
After completion of the ingraph. The Agreement vole before each anniversary annual renewal fee is su	nitial treatment, the agrevill be effective when the date of the agreement object to increase after the date of the second control o	tation of subterranean term eement will apply to the bu e initial charge for treatmer . The annual renewal fee in the 5th fiscal year no more	ilding at the above stated nt are paid and after that, indicated below is due on the than 10% per year.	service address upon payment of he anniversary d	and describe f the annual r late of the init	d in the attached enewal fee on or ial treatment. The
Customer warrants full conducive to re-infestation	cooperation with the cor on, such as excessive r round. Any alterations c ement may be transferre	npany, and agrees to make the bennpany, and agrees to main moisture, wood debris, trassor additions to the building sed to any new owner at any	tain the building located a th or allowing lumber or wo shall not be included in thi y time, the service and wa	t the service add ood adjacent or a s agreement unl	attached to th ess the comp	e building to come in pany has also treated
Type of Treatment [[(Refer to the "Definition of]Physical Barrier [ons of Treatment" (]Pier & Beam		START DATE	/	/
[X]Attach Copy of La [X]Attach Graph show Treatment Charge \$_ Inspections Recomm	ving termite treatin 625		MSDS Sheet er Information Sheet = \$ 676.56		. Sheet Att	tached
Amount Remitted with	h this Agreement \$					

You, the buyer, may cancel this transaction at anytime prior to midnight of the third business day after the date of this transaction. Ask for details and/or

see the back of this document.

In the event payment is not met, A-TEX will submit for collection and all expenses, charges, fees, etc. will be added to the amount due and owed by Customer. There will be a \$25.00 fee for all returned checks.

The undersigned property owner/customer acknowledges that they have read and understand the foregoing agreement. They also understand that they will be bound by its terms.

A-TEX PEST MANAGEMENT INC.

ACCEPTED BY:

Chris Roddy

Representative Name

Special Instructions/Payment Arrangements:

LICENSED & REGULATED BY: TEXAS DEPARTMENT OF AGRICULTURE

P.O. BOX 12847 AUSTIN, TX 78711-2847, PHONE: (806) 918-4481, FAX:(888) 232-2567

GENERAL TERMS AND CONDITIONS

It is agreed that the Company is not responsible for the repair of visible or hidden damage existing as of the date of his contract. It is further agreed that the customer is solely responsible for the repair of such damage.

Excessive moisture, structural or mechanical defects which result in water leakage and stress cracks in foundation and sub-slab areas may destroy the effectiveness of the treatment and permit the infestation to continue after the date of initial treatment. If moisture and/or structural conditions which are conductive to subterranean termite infestation (such as structural wood to ground contact, water leakage stucco/veneer below grade, firewood adjacent to structure, milch beds adjacent to structure) are found to exist after the date of this agreement the Company shall be relieved of any and all liability for damage occurring during the term of this agreement. If such repairs are discovered, it is agreed that the customer will be responsible for making such repairs as are necessary to correct the defect and the company will within one year from the date of this contract, upon completions of said repairs, provide treatment to control the infestation.

Any claim for breach of this guarantee shall be made in writing to the Company. The parties hereto agree to submit all disputes to binding arbitration if the parties are unable to agree to a resolution of any dispute. In no event may any lawsuit be brought more than two (2) years after the breach of the guarantee. The Company's liability shall be terminated should the Company be prevented from fulfilling its responsibilities under the terms of the Guarantee by reason of acts of war, whether declared or undeclared, acts of any duly constituted government authority, strikes, acts of God, or failure by the customer to allow the Company access to the premises for any purpose contemplated by the Guarantee, specifically including re-inspection, whether such re-inspection was requested by the customer or deemed necessary by the Company.

This agreement covers the premises diagram on the attached Graph and specifications as of the date actual treatment, and the event the premises are structurally modified, altered, sold, transferred or otherwise changed after date of initial treatment, this agreement shall terminate as to that portion modified, altered, sold, transferred or changed unless a prior written agreement shall have been entered into between the customer and the Company to re-inspect the premises, provide additional treatment and/or adjust the annual renewal fee.

It is understood and agreed between the parties that this Agreement, the attached Graph and specifications constitute the complete agreement between the parties and that said agreement may not be transferred, changed or altered in any manner, oral or otherwise, unless the alteration or change is in writing and executed by a duly authorized representative of the Company.

It is specifically understood and agreed that the Company and the Customer are bound only by the terms and conditions of this agreement and have not relied on any other representation oral or otherwise.

Customer acknowledges and agrees that no insecticides shall be applied to the baited/monitored sites, that all bait stations shall remain the property of the company, that customer shall be responsible for missing or damaged bait stations, and that customer shall not move, open or handle bait stations. Customer acknowledges and agrees that control subterranean termites through a baiting system shall be provided through baiting and monitoring by the company. The subterranean termite baiting system is designed to reduce and/or eliminate termite activity to the extent required to provide structural protection from further damage, Achievement of this end result make take several months or in some cases longer depending on the size and number of termite colonies presents, the number of conductive conditions, the treatment method used, and the number of station used and their placement. Additional damage may occur because of the time needed to gain control. The company will not be responsible for such damage.

It is agreed that the agreement does not cover Drywood, Formosan or any other species of Termites other than Eastern Subterranean Termites.

DEFINITIONS OF TREATMENT

A subterranean termite treatment may be a partial treatment or a spot treatment using termiticide, approved physical barriers or a baiting system, These types of treatments are defined as follows:

Partial Treatment

This technique allows a wide variety of treatment strategies but is more involved than a spot treatment. (See definition below.) Ex: treatment of some or all of the perimeter, bath traps, expansion joints, stress cracks, portions of framing, walls and bait locations.

Pier and Beam: Generally defined as the treatment of the outer perimeter including porches, patios and treatment of the attached garage. In the crawl space, treatment would include any soil to structure contacts as well as removal of any wood debris on the ground.

Slab Construction: Generally defined as treatment of the perimeter and all known slab penetrations as well as any known expansion joints or stress cracks.

Spot Treatment

Any treatment which concerns a limited, defined area less than ten (10) linear or square feet that is intended to protect a specific location or "spot." Often there are adjacent areas susceptible to termite infestation, which are not treated.

Baiting

This type of treatment may include interior and/or perimeter placement of monitoring or baiting systems along with routine inspection intervals. The baiting technique may include one or more baiting locations as prescribed by the product label and instructions.

For all treatment there will be a graph showing exactly what will be treated. Treatment specifications and warranties for those treatments may vary widely. Review the pesticides label provided to you for minimum treatment specifications. If you have any questions, contact the service provider or the Texas Department of Agriculture P.O. Box 12847, Austin, TX 78711 Phone:866-918-4481 or Fax: 888-232-2567

Notice of Cancellation

I, the buyer, having been informed of my right to cancel this transaction at anytime prior to midnight of the third business day after the date of this transaction hereby exercise my right of cancellation.

Buyer	Date:	Time:	



https://www.atexpest.com P.O. Box 80081 - Austin, Texas 78708

(512) 428-6967 TPCL#12357

X	=A0	CTI	/F	TFF	ЗM	ITF:	S

A = TRENCH

B = DRILL

C = BATH & TRAPS

D = WASHER/DRYER

E = SINKS

F = ICE MAKER

G=SHOWER PAN

H = ROD

I = LONG ROD

NOTES

APPROX: 125 LIN. FT.

APPROX: 30-40 CHEM. GALS.

APPROX: 2-3 HR. LABOR

GRAPHED BY: CR

Name: EVA CONVIT

Address: 407 E MONROE ST

Austin, TX 78704

Phone #: H (512) 751-5667 W


TOTAL \$ 625

SERVICE CHARGE \$

TAX \$

TOTAL:\$

1 SQ# FT



+

Add Diagram Legend

Finish

A-TEX PEST MANAGEMENT INC PO BOX 80081 AUSTIN, TX 78708



Demolition Permit Application

DevelopmentATX.com | Phone: 311 (or 512-974-2000 outside Austin)
For submittal and fee information, see <u>austintexas gov/digitaldevelopment</u>

Download application before entering information.

For Office Use (Only - Permit Information			
PR-	BP-	Historic Review:Year Built:	888	
		Historic District Name:		
Release permit				
Historic Preservation	Office	Date		
expire after twenty-		ojects. If you do not schedule a final inspection, the permit it activation. To close an expired permit, applicants must sui		
DO NOT LET YOU	R PERMIT EXPIRE!			
local or National Re		this property is a historic landmark or a contributing propert ations and fees apply. Visit the Historic Preservation Office rvation for more information.		
Submittal Requ	irements		Die.	
		ottom of the next page, OR a notarized letter of authorization apply. Electronically notarized applications are preferred.	in	
2. Dimensione				
3. Notarized A	ffidavit of Compliance			
4. Certified tax	coertificate(s) from the Travis County To	ax Assessor (5501 Airport Boulevard, 512-854-9473)		
	ach side of structure. One photo must sixels (1200 x 1600 pixels) or larger	show the entire elevation visible from the street. Photos mus	st be	
☐ 6. Tree survey	with all trees 19" or greater shown on	plans		
Additional require	ments for commercial demolitions:	3		
7. Approved/R	Red-stamped Site Plan OR an approved	Site Plan Exemption Form		
■ 8. Texas Depart	artment of Health Asbestos Notification	Form completed by a licensed inspector or contractor		
Property Inform	mation	Proposed Demolition	TO.	
Address: 407 Ea	st Monroe	▼ Total Greater than 50% of exterior, identify the state of the	he	
City: Austin	Zip: 7870			
Current Use: Va	acant	demonstred on site planvatively and priotos.		
Demolition Con	ntractor Information	Structural Information		
Company: Poss	um Trot	Square Feet: 1,177 sqft		
	Vest 9th ST	Building Materials: Stucco, Stick Frame		
City: Austin	Zip: 78703			
Phone: 512-520		Estimated Cost of Demolition: \$15,000		

Owi	ner	Applicant
Nam	e: Parkash Builders LLC	Name: Khazana Design Team
Addr	ess: 1212 West 9th St	Address: 9327 TX-71
City:	Austin Zip: 78703	City: Austin Zip; 78735
Phor		Phone: 512-520-8878
Ema	ParkashBuilders@gmail.com	Email: khazanadesignteam@gmail.com
Add	litional Questions	
Are t	here trees 19 inches or greater in diameter on the site o	r along neighboring properties? (Residential only) ✓ Yes No
Was	the structure inhabited within the last 12 months?	✓Yes □ No
Wha	t is the total number of housing units that will be demolis	thed? 1 (Commercial only)
Wha	t is the total number of bedrooms in the units that will be	
	many currently occupied residential units will be demoli-	
Deve	or more, tenant notification and a certified form may be re elopment Code (Division 23-4E-8; F25-1-712 and 713). Note information.	equired with your application per the City of Austin Land Visit www.austintexas.gov/page/tenant-relocation-assistance
Is the	e property located in a National Register historic district, Yes	a historic district (zoned HD), or a historic landmark (zoned
Wha	t is the total square footage being demolished?1,177	sqft
Willt	this project involve implosion? s, contact Austin Water at 512-972-0101 to determine if	□ Yes 🗹 No
Stric	dplain: Is the property located in the City of Austin regula ter permit regulations apply to any building, remodeling, plain. Approval for demolition does not guarantee appro	construction or other development on locations in the
Con	sent, Authorizations, and Signatures	
1 und	erstand and will adhere to the following rules or regulati	ons:
1.	No work may begin prior to issuance of this permit work.	. All required permits must be obtained prior to the start of
2.	Verify with the Development Assistance Center that ne PRIOR to submitting this application.	w construction will be permitted on the property at this location
3.		or sewer services provided by the City of Austin, you must 4-9400 to obtain specific water and sewer service information.
4.	For disconnect and removal of services by Austin Energy,	contact City of Austin's Utility Contact Center at 512-494-9400.
5.	Water/waste water tap permit <u>application</u> for Commerc (<u>AWTaps@austintexas.gov</u>). Water/waste water tap pe AB+C portal.	ial shall be emailed to Austin Water Taps rmit application for Residential shall be completed via the
6.	181). Failure to comply may result in a Stop Work Orde charges and fines of up to \$2,000 per day. Inspection of	city of Austin Land Development Code (§23-4D-7; F25-8- er and/or legal action by the City of Austin, including criminal of erosion, sedimentation controls, and tree protection must be 3-5B-6050 (B); F25-1-288). Call (512) 974-2278 or email hese inspections.
7.	Manual (§3.5.2 (A)). Proposed work that will remove, in	nt Code (Article 23-4C; F25-8-B) and Environmental Criteria inpact the critical root zone, or prune more than 25% of the tree permit. Note: Root zone protection measures (e.g. red prior to work.

- If the proposed work will require use of City right of way, a Right of Way Application must be approved. Obtain an application from the Transportation Department at (512) 974-7180 or www.austintexas.gov/rowman.
- 9. The Historic Preservation Office will determine if the referenced structure meets historic designation criteria as defined by the Land Development Code (Article 23-6E; F25-11-213 to 214; and §23-3C-10090; F25-2-352). Additional review by the Historic Landmark Commission may be required and additional fees may be assessed. If the property is a historic landmark or is located in a local or National Register historic district, the Historic Landmark Commission must review plans for new construction before the demolition permit is released. Call (512) 974-3583, email preservation@austintexas.gov, or visit www.austintexas.gov/department/historic-preservation for more information.
- 10. Construction projects exceeding 5,000 square feet of new, added, or remodeled floor area and all permitted commercial and multi-family demolition projects are required to divert construction debris from the landfill per the Land Development Code (§23-6C-2060; F25-11-39). Email constructionrecycling@austintexas.gov or visit www.austintexas.gov/department/construction-demolition-recycling-ordinance for more information.
- Approval of a demolition permit does not guarantee approval for new construction in the City of Austin regulatory floodplain.
- For properties in the City of Austin regulatory floodplain, a determination of substantial damage and/or substantial improvement (for partial demolitions) may trigger additional floodplain regulations.
- Greater than 50% of exterior walls demolished will require compliance with the Demolition Notification requirements (Ordinance 20201001-040)
- 14. Approved permits may be obtained from the Service Center. Any additional fees will be assessed at that time.

I, the undersigned, hereby swear or affirm that the information provided in this application is true and correct to the best of my knowledge and is an accurate reflection of my intentions for the above structure and/or property. I understand that any omission or incorrect information herein will render this application and any permit obtained invalid.

app	owner(s) of the property described in this application, I/we hereby authorize the Applica plication to act on my/our behalf during the processing and presentation of this request. ncipal contact with the City in processing this application.		
Sig	nature of Applicant (if different than owner):	Date:	3-31-22
Sig	nature of Owner:	Date:	
Sw	orn and subscribed before me this 31 day of 03 . 20 21		
Sig	nature of Public Notary: My commission ex	pires:	12/15/25
	Notary Publican and for the State of Texas		

THDMAS LE
Notary ID #129651740
My Commission Expires
December 15, 2025