



SYMBOL LEGEND



MATERIALS LEGEND



ABBREVIATIONS

 	And	EQ	Equal Spacing, Equivalent	MANUF	Manufacturer	S	South
#	Pound	EQUIP	Equipment	MAX	Maximum	SALV	Salvage
@	At	EXH	Exhaust	MECH	Mechanical	SAU	Self-Adhering Underlayment
A/C	Air Conditioning	EXST'G	Existing	M/E	Mechanical/Electrical	SCH'D	Scheduled
ACOUST	Acoustical	EXT	Exterior	MEP	Mechanical, Electrical, & Plumbing	SECT	Section
ADD'L	Additional	FAR	Floor-Area Ratio	MIN	Minimum	SEP	Seperate, Separated
ADJ	Adjacent	FF(E)	Finished Floor (Elevation)	MISC	Miscellaneous	SF	Square Feet
AFF	Above Finish Floor	FIN	Finish(ed)	MTD	Mounted	SHT	Sheet
AHJ	Authority Having Jurisdiction	FIXT	Fixture	MTL	Metal	SIM	Similar
AHU	Air Handling Unit	FLR	Floor			SHTG	Sheathing
APPROX	Approximately	FT	Feet, Foot	N	North	SK	Sink
ARCH	Architect	FTG	Footing	NA	Not Applicable	SMACNA	Sheet Metal & Air Conditioning National Association, Inc.
ASTM	American Society for Testing & Materials	FV	Field Verify	NIC	Not in Contract	SPECS	Specifications
		FV HT	Field Verify Height	NO	Number	SPEC'D	Specified
				NSF	Net Square Feet	SQ	Square
				NTS	Not to Scale	STL	Stainless Steel
BOR	Bottom of Rafter	GA	Gauge			SS	Steel
BRD	Board	GALV	Galvanized	OC	On Center	STRUCT	Structural
BLDG	Building	GC	General Contractor	OCEW	On Center Each Way	SUSP	Suspended
BDRM	Bedroom	GFCI	Ground Fault Circuit Interrupt	OP'G	Opening	SW	Switch
BTM	Bottom	GL	Glass	OVHD	Overhead	SYM	Symmetrical
BTWN	Between	GM	Gas Meter	OZ	Ounce		
CAB	Cabinet	GPM	Gallons Per Minute			T&G	Tongue & Groove
CF	Cubic Feet	GR	Grade	P&I	Provide & Install	TEMP	Temporary, Tempered
CJ	Control Joint	GRND	Ground	PC	Photo Cell	THK	Thick
CL	Centerline	GSF	Gross Square Feet	PG	Page		
CLG	Ceiling	GYP BD	Gypsum Wall Board	PL	Plate or Plateline	TOT	Total
CLO	Closet					TOW	Top of Wall
CLR	Clear	HB	Hose Bib	PR	Pair	TRTD	Treated
COL	Column	HDR	Header	PSF	Pounds Per Square Foot	TYP	Typical
COMP	Composite	HDWR	Hardware	PSI	Pounds Per Square Inch		
CONC	Concrete	HORIZ	Horizontal	PT	Pressure Treated	UC	Under Counter
CONST	Construction	HR	Hour	PTD	Painted	UCR	Under Counter Refrigerator
CONT	Continuous	HT	Height	PVC	Polyvinyl Chloride	UL	Underwriter's Laboratory
COORD	Coordinate, Coordination	HTG	Heating	PVMT	Pavement	UNFIN	Unfinished
CRZ	Critical Root Zone	HVAC	Heat/Ventilation/ Air Conditioning	PWD	Plywood	UNO	Unless Noted Otherwise
CVR	Cover					VB	Vapor Barrier
CW	Cold Water	I.E.	Id Est (That Is)	QTR	Quarter	VERT	Vertical
		IN	Inches			VFY	Verify
D	Deep, Depth, Dryer	INAC	Inaccessible	R	Radius/Refrigerator		
DBL	Double	INCL	Including	RCP	Reflected Ceiling Plan	W	Wide, Width, West, Washing Machine
DEMO	Demolish, Demolition	INFO	Information	RE/REF	Reference	W/	With
DH	Double Hung	INSUL	Insulation	REINF	Reinforced	W/O	Without
DIA	Diameter	INT	Interior	REQ'D	Required	W/D	Stackable Washer Dryer
DIAG	Diagonal, Diagonally			REQMT'S	Requirements	WD	Wood
DN	Down	JNT	Joint	REV	Revision	WDW	Window
DS	Downspout	JST	Joist	RFG	Roofing	WH	Water Heater
DW	Dishwasher			RM	Room	WM	Water Meter
DWG	Drawing	KIT	Kitchen	RO	Rough Opening	WP	Waterproofing
DWR	Drawer			ROW	Right of Way	WT	Weight
		L	Length			YD	Yards
E	East	LAM	Laminated				
EA	Each	LAV	Lavatory				
EJ	Expansion Joint	LB(S)	Pound(s)				
EM	Electric Meter	LF	Linear Foot				
EQ	Equal Spacing, Equivalent	LP	Light Pole or Lightning Protection				
EQUIP	Equipment	LT	Light				
EXST'G	Existing	LVR	Louver				
EXT	Exterior						

DESIGN TEAM

ARCHITECTURE

O'CONNELL ARCHITECTURE, LLC
TERESA O'CONNELL, AIA
3908 AVENUE B, SUITE 309
AUSTIN, TEXAS 78751
512.751.1374

STRUCTURAL ENGINEERING

TSEN ENGINEERING
210 BARTON SPRINGS RD. SUITE 250
AUSTIN, TEXAS 78704
512.474.4001

CIVIL ENGINEERING

DUNAWAY ASSOCIATES, L.P.
5707 SOUTHWEST PARKWAY, SUITE 2-250
AUSTIN, TEXAS. 78735
817.335.1121

811-813 Park Blvd

LAND AREA	23089.5 SF		
MAIN HOUSE	Existing	New	Total
Basement **	229		229
First Floor	1637		1637
Second Floor	1645		1645
Attic *	UNF	578	578
GARAGE	Existing	New	Total
First Floor *	575		575
Second Floor	575		575
Building Impervious Cover			2212
			9.58%
SITE	Existing	New	Total
Site Walls & Fencing	56	227	283
Driveway		2763	2763
Sidewalks	238	1625	1863
Terrace		397	397
Equipment Pads	151	16	167
	445	5028	5473
Impervious Cover, total	2657		7685
	12%		33.28%
FAR *	0.17		0.2170
* Garage and Attic finished as Living Space			
** Basement Mechanical Space Exempt from FAR			

PROJECT INFORMATION

LEGAL DESCRIPTION: LOT 33 AND 34 BLK 23 OLT 14 DIV C PERRY ESTATE

ZONING: SF-3

YEAR CONSTRUCTED: 1929
Eligible for Austin Historic Landmark and National Register of Historic Places

APPLICABLE CODES: International Residential Code, 2021

OCCUPANCY: R-1, R-3

CONSTRUCTION TYPE: V-B

DRAWING INDEX


MAIN HOUSE	
A-101	SITE PLAN
A-102	SITE FENCING
A-110	FOUNDATION PLAN - DEMO
A-111	GROUND FLOOR PLAN - DEMO
A-112	SECOND FLOOR PLAN - DEMO
A-120	FOUNDATION PLAN
A-121	GROUND FLOOR PLAN - NEW
A-122	SECOND FLOOR PLAN - NEW
A-123	ATTIC PLAN
A-124	ROOF PLAN
A-211	NORTH ELEVATION
A-212	EAST ELEVATION
A-213	SOUTH ELEVATION
A-214	WEST ELEVATION
A-311	BUILDING SECTIONS
A-312	CELLAR STAIR SECTIONS
A-401	KITCHEN & DINING ELEVATIONS
A-402	BATH ELEVATIONS
A-403	ATTIC ELEVATIONS
A-411	KITCHEN LAYOUT & MAIN STAIRCASE
A-501	EXTERIOR DETAILS
A-610	WINDOW SCHEDULE & DETAILS
A-620	DOOR SCHEDULE & DETAILS
A-630	FINISH SCHEDULE
GARAGE	PERMIT 2022-055330-PR
A-900	COVER SHEET AND SITE PLAN
A-901	DEMOLITION PLANS AND FLOOR PLANS
A-902	NORTH AND WEST ELEVATIONS
A-903	SOUTH AND EAST ELEVATIONS
A-904	SECTIONS & WALL DETAILS
A-905	DETAILS
A-906	GARAGE DOOR DETAILS
A-907	SCHEDULES & ELECTRIC PLANS

GENERAL NOTES

- All work shall be performed in a professional matter, and in accordance with the International Residential Code, 2021, related trade codes, and applicable local codes, ordinances and laws.
- Historic designation of this building requires the Contractor and his subcontractors to exercise special caution in executing the work to prevent unnecessary damage to historic features, conditions, or materials. Contractor shall inform all subcontractors and workmen of these requirements.
- The Contractor shall thoroughly example and familiarize himself with the requirements of the Contract Documents. Any conflicts shall be brought to the Architect's attention for resolution prior to the work being installed.
- Perform all work in a safe and conscientious manner to prevent injuries and damage to the building and workers. Contractor shall maintain OSHA Standards for job safety and worker protection, and comply with applicable state and local government requirements.
- Building permitting will be coordinated by the Owner and Architect prior to construction. Contractor is responsible for all trade permits, inspections, and compliance requirements.
- Maintain the building and site in a clean and orderly condition.
- The Contractor shall visit the site of the proposed work and full acquaint himself with the existing conditions regarding site access, staging, parking limitations, security, and other aspects of constructibility.
- The Contractor shall coordinate work between all trades in this contract to ensure a smooth and timely workflow.
- All work to be warranted for one year from the date of Substantial Completion unless otherwise noted.



SITE LOCATION MAP



MILLER-LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751


ISSUE DATE
PRINT: 5/6/22

SHEET NAME

COVER SHEET

SHEET NUMBER

A-000



MILLER-LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751

813 PARK BOULEVARD, AUSTIN, TEXAS 78751

ISSUE DATE


PRINT: 5/6/22

SHEET NAME

PROPOSED SITE PLAN


SHEET NUMBER

A-101






2 VIEW from RED RIVER
Scale: 1/8" = 1'-0"



3 FENCE & WALL DETAIL
Scale: 1" = 1'-0"



1 PARTIAL VIEW of PROPOSED FENCE on PARK BLVD.
Scale: 1/4" = 1'-0"



O'Connell
ARCHITECTURE

3908 Avenue B, #309
Austin, Texas 78751
512/751-1374



MILLER LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751

ISSUE DATE



PRINT: 5/6/22

SHEET NAME

PROPOSED
FENCES

SHEET NUMBER

A-102



MILLER-LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751


ISSUE DATE
PRINT: 5/6/22

SHEET NAME

**FIRST FLOOR
PLAN - DEMO**



	SHEET NUMBER
--	--------------


A-111



1 FIRST FLOOR - DEMO
Scale: 1/4" = 1'-0" 1637 sq. ft. gross floor area

Dimensions are for planning purposes only, and accurate to one inch. Field verify all critical dimensions and all spatially sensitive locations.





O'Connell
ARCHITECTURE

3908 Avenue B, #309
Austin, Texas 78751
512/751-1374



MILLER-LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751


ISSUE DATE
PRINT: 5/6/22

SHEET NAME

**SECOND
FLOOR PLAN -
DEMO**



SHEET NUMBER


A-112



1 SECOND FLOOR - DEMO
Scale: 1/4" = 1'-0" 1645 sq. ft. gross floor area




Dimensions are for planning purposes only, and accurate to one inch. Field verify all critical dimensions and all spatially sensitive locations.






1 FOUNDATION PLAN
Scale: 1/4" = 1'-0"



Dimensions are for planning purposes only, and accurate to one inch. Field verify all critical dimensions and all spatially sensitive locations.







1 FIRST FLOOR - PROPOSED
Scale: 1/4" = 1'-0"

Dimensions are for planning purposes only,
and accurate to one inch. Field verify all
critical dimension, and at all spatially
sensitive locations.






3 BATH LAYOUT PLAN
Scale: 1/2" = 1'-0"






2 BATH LAYOUT PLAN
Scale: 1/2" = 1'-0"



1 SECOND FLOOR - PROPOSED
Scale: 1/4" = 1'-0"


Dimensions are for planning purposes only, and accurate to one inch. Field verify all critical dimensions and all spatially sensitive locations.





O'Connell
ARCHITECTURE

3908 Avenue B, #309
Austin, Texas 78751
512/751-1374



MILLER-LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751

ISSUE DATE


PRINT: 5/6/22


SHEET NAME

ATTIC FLOOR
PLAN

SHEET NUMBER

A-123





O'Connell
ARCHITECTURE

3908 Avenue B, #309
Austin, Texas 78751
512|751-1374



MILLER-LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751

ISSUE DATE


PRINT: 5/6/22

SHEET NAME



ROOF PLAN


SHEET NUMBER

A-124




1 ROOF PLAN
Scale: 1/4" = 1'-0"





1 NORTH ELEVATION
Scale: 1/4" = 1'-0"



RESTORATION SCOPE

Concrete

1. Repair/replace concrete foundation skirt over original buff-brick perimeter beam to match historic character, texture, and finish.

Stucco

2. Throughout second floor and first floor entry area, remove stucco finish and replace with new 3-coat stucco over wire lath. Insulate wall and install vapor barrier per details. Finish texture to match original "Lace and Skip" trowel finish – see supplemental information provided by Architect.
3. Window heads and sills at second and third floor are currently formed stucco – verify original detailing with Architect through selective demolition and investigations.

Masonry

4. Repoint all broken and deteriorated mortar joints with new mortar to match original in color, composition, texture, and tooling. Take particular note of mortar aggregate which must be matched.
5. Remove existing brick sills, clean bricks, install new sill flashing and relay with proper pitch to exterior. Refer to detail herein. Mortar to match original in color, composition, texture, and tooling. Take particular note of mortar aggregate which must be matched. Brick salvaged from the south elevation of the garage may be used in these repairs.
6. Repair and repoint brickwork at chimneys, reset chimney pots.
7. Clean all masonry to remove algae staining using gentlest means possible. Pressurized water not to exceed 400psi. Cleaning program including all products and processes to be approved by Architect and mocked-up prior to use.

Wood

8. Replace rotted wood at eaves and rake boards, finials, moldings, door and window trim with new to match original detailing. Wood species to be approved by Architect through submittal samples. Acceptable wood species include selected types of mahogany, smooth-finished cedar, or other rot-, warp-, and check-resistant wood. Paint finish to match historic or approved equal.
9. Restore exterior doors by removing finishes and using epoxy consolidation repair techniques in lieu of replacement to the maximum extent possible. Review condition of all doors and verify Restoration Program with Architect prior to start of work. Allow Architect access for evaluation of original finishes. Replace all door thresholds with solid oak tapered thresholds.

Hardware

10. Restore all original door hardware, or replace in kind if damage is beyond repair. Provide and install new deadbolts at exterior doors and as scheduled.
11. Replace broken hardware at casement windows to match original character. Weatherstrip all operable windows.

Steel Casement Windows

12. Remove, restore, and reinstall steel casement windows. Replace irreparable stock to match original character. Match original exterior finish: Black paint.
13. New steel casement window at attic level to match original character, refer to window

Roof


14. 10. Remove existing composition shingle roof and flashings and install new felt, flashings and architectural composition shingle roof. Product:
15. Replace all roof vents and appurtenances at roof, and paint finish to match roof. Locate all on the south (rear) face of the building.
16. Provide and install new skylights as indicated in Roof Plan.

Mechanical


17. New Mitsubishi mini-split ducted systems throughout.

Electrical

18. New electrical service to be underground to meter and disconnect where indicated on plan.
19. Restore all historic exterior light fixtures including new wiring and restored finishes.



3908 Avenue B, Suite 309
Austin, Texas 78751
512/751-1374



MILLER-LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751

ISSUE DATE

PRINT: 5/6/22

SHEET NAME

NORTH
ELEVATION

SHEET NUMBER

A-211



RESTORATION SCOPE

- Concrete**
1. Repair/replace concrete foundation skirt over original buff-brick perimeter beam to match historic character, texture, and finish.
- Stucco**
2. Throughout second floor and first floor entry area, remove stucco finish and replace with new 3-coat stucco over wire lath. Insulate wall and install vapor barrier per details. Finish texture to match original "Lace and Skip" trowel finish – see supplemental information provided by Architect.
 3. Window heads and sills at second and third floor are currently formed stucco – verify original detailing with Architect through selective demolition and investigations.
- Masonry**
4. Repoint all broken and deteriorated mortar joints with new mortar to match original in color, composition, texture, and tooling. Take particular note of mortar aggregate which must be matched.
 5. Remove existing brick sills, clean bricks, install new sill flashing and relay with proper pitch to exterior. Refer to detail herein. Mortar to match original in color, composition, texture, and tooling. Take particular note of mortar aggregate which must be matched. Brick salvaged from the south elevation of the garage may be used in these repairs.
 6. Repair and repoint brickwork at chimneys, reset chimney pots.
 7. Clean all masonry to remove algae staining using gentlest means possible. Pressurized water not to exceed 400psi. Cleaning program including all products and processes to be approved by Architect and mocked-up prior to use.
- Wood**
8. Replace rotted wood at eaves and rake boards, finials, moldings, door and window trim with new to match original detailing. Wood species to be approved by Architect through submittal samples. Acceptable wood species include selected types of mahogany, smooth-finished cedar, or other rot-, warp-, and check-resistant wood. Paint finish to match historic or approved equal.
 9. Restore exterior doors by removing finishes and using epoxy consolidation repair techniques in lieu of replacement to the maximum extent possible. Review condition of all doors and verify Restoration Program with Architect prior to start of work. Allow Architect access for evaluation of original finishes. Replace all door thresholds with solid oak tapered thresholds.
- Hardware**
10. Restore all original door hardware, or replace in kind if damage is beyond repair. Provide and install new deadbolts at exterior doors and as scheduled.
 11. Replace broken hardware at casement windows to match original character. Weatherstrip all operable windows.
- Steel Casement Windows**
12. Remove, restore, and reinstall steel casement windows. Replace irreparable stock to match original character. Match original exterior finish: Black paint.
 13. New steel casement window at attic level to match original character, refer to window
- Roof**
14. 10. Remove existing composition shingle roof and flashings and install new felt, flashings and architectural composition shingle roof. Product:
 15. Replace all roof vents and appurtenances at roof, and paint finish to match roof. Locate all on the south (rear) face of the building.
 16. Provide and install new skylights as indicated in Roof Plan.
- Mechanical**
17. New Mitsubishi mini-split ducted systems throughout.
- Electrical**
18. New electrical service to be underground to meter and disconnect where indicated on plan.
 19. Restore all historic exterior light fixtures including new wiring and restored finishes.



O'Connell
ARCHITECTURE

3908 Avenue B, Suite 309
Austin, Texas 78751
512/751-1374



MILLER-LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751

ISSUE DATE


PRINT: 5/6/22

SHEET NAME

EAST
ELEVATION

SHEET NUMBER

A-212



RESTORATION SCOPE

- Concrete**
1. Repair/replace concrete foundation skirt over original buff-brick perimeter beam to match historic character, texture, and finish.
- Stucco**
2. Throughout second floor and first floor entry area, remove stucco finish and replace with new 3-coat stucco over wire lath. Insulate wall and install vapor barrier per details. Finish texture to match original "Lace and Skip" trowel finish – see supplemental information provided by Architect.
 3. Window heads and sills at second and third floor are currently formed stucco – verify original detailing with Architect through selective demolition and investigations.
- Masonry**
4. Repoint all broken and deteriorated mortar joints with new mortar to match original in color, composition, texture, and tooling. Take particular note of mortar aggregate which must be matched.
 5. Remove existing brick sills, clean bricks, install new sill flashing and relay with proper pitch to exterior. Refer to detail herein. Mortar to match original in color, composition, texture, and tooling. Take particular note of mortar aggregate which must be matched. Brick salvaged from the south elevation of the garage may be used in these repairs.
 6. Repair and repoint brickwork at chimneys, reset chimney pots.
 7. Clean all masonry to remove algae staining using gentlest means possible. Pressurized water not to exceed 400psi. Cleaning program including all products and processes to be approved by Architect and mocked-up prior to use.
- Wood**
8. Replace rotted wood at eaves and rake boards, finials, moldings, door and window trim with new to match original detailing. Wood species to be approved by Architect through submittal samples. Acceptable wood species include selected types of mahogany, smooth-finished cedar, or other rot-, warp-, and check-resistant wood. Paint finish to match historic or approved equal.
 9. Restore exterior doors by removing finishes and using epoxy consolidation repair techniques in lieu of replacement to the maximum extent possible. Review condition of all doors and verify Restoration Program with Architect prior to start of work. Allow Architect access for evaluation of original finishes. Replace all door thresholds with solid oak tapered thresholds.
- Hardware**
10. Restore all original door hardware, or replace in kind if damage is beyond repair. Provide and install new deadbolts at exterior doors and as scheduled.
 11. Replace broken hardware at casement windows to match original character. Weatherstrip all operable windows.
- Steel Casement Windows**
12. Remove, restore, and reinstall steel casement windows. Replace irreparable stock to match original character. Match original exterior finish: Black paint.
 13. New steel casement window at attic level to match original character, refer to window
- Roof**
14. 10. Remove existing composition shingle roof and flashings and install new felt, flashings and architectural composition shingle roof. Product:
 15. Replace all roof vents and appurtenances at roof, and paint finish to match roof. Locate all on the south (rear) face of the building.
 16. Provide and install new skylights as indicated in Roof Plan.
- Mechanical**
17. New Mitsubishi mini-split ducted systems throughout.
- Electrical**
18. New electrical service to be underground to meter and disconnect where indicated on plan.
 19. Restore all historic exterior light fixtures including new wiring and restored finishes.



O'Connell
ARCHITECTURE

3908 Avenue B, Suite 309
Austin, Texas 78751
512/751-1374



MILLER-LONG HOUSE
RESTORATION

813 PARK BOULEVARD, AUSTIN, TEXAS 78751

ISSUE DATE

PRINT: 5/6/22

SHEET NAME

SOUTH
ELEVATION

SHEET NUMBER


A-213



1 WEST ELEVATION
Scale: 1/4" = 1'-0"


RESTORATION SCOPE

- Concrete**
1. Repair/replace concrete foundation skirt over original buff-brick perimeter beam to match historic character, texture, and finish.
- Stucco**
2. Throughout second floor and first floor entry area, remove stucco finish and replace with new 3-coat stucco over wire lath. Insulate wall and install vapor barrier per details. Finish texture to match original "Lace and Skip" trowel finish – see supplemental information provided by Architect.
 3. Window heads and sills at second and third floor are currently formed stucco – verify original detailing with Architect through selective demolition and investigations.
- Masonry**
4. Repoint all broken and deteriorated mortar joints with new mortar to match original in color, composition, texture, and tooling. Take particular note of mortar aggregate which must be matched.
 5. Remove existing brick sills, clean bricks, install new sill flashing and relay with proper pitch to exterior. Refer to detail herein. Mortar to match original in color, composition, texture, and tooling. Take particular note of mortar aggregate which must be matched. Brick salvaged from the south elevation of the garage may be used in these repairs.
 6. Repair and repoint brickwork at chimneys, reset chimney pots.
 7. Clean all masonry to remove algae staining using gentlest means possible. Pressurized water not to exceed 400psi. Cleaning program including all products and processes to be approved by Architect and mocked-up prior to use.
- Wood**
8. Replace rotted wood at eaves and rake boards, finials, moldings, door and window trim with new to match original detailing. Wood species to be approved by Architect through submittal samples. Acceptable wood species include selected types of mahogany, smooth-finished cedar, or other rot-, warp-, and check-resistant wood. Paint finish to match historic or approved equal.
 9. Restore exterior doors by removing finishes and using epoxy consolidation repair techniques in lieu of replacement to the maximum extent possible. Review condition of all doors and verify Restoration Program with Architect prior to start of work. Allow Architect access for evaluation of original finishes. Replace all door thresholds with solid oak tapered thresholds.
- Hardware**
10. Restore all original door hardware, or replace in kind if damage is beyond repair. Provide and install new deadbolts at exterior doors and as scheduled.
 11. Replace broken hardware at casement windows to match original character. Weatherstrip all operable windows.
- Steel Casement Windows**
12. Remove, restore, and reinstall steel casement windows. Replace irreparable stock to match original character. Match original exterior finish: Black paint.
 13. New steel casement window at attic level to match original character, refer to window
- Roof**
14. 10. Remove existing composition shingle roof and flashings and install new felt, flashings and architectural composition shingle roof. Product:
 15. Replace all roof vents and appurtenances at roof, and paint finish to match roof. Locate all on the south (rear) face of the building.
 16. Provide and install new skylights as indicated in Roof Plan.
- Mechanical**
17. New Mitsubishi mini-split ducted systems throughout.
- Electrical**
18. New electrical service to be underground to meter and disconnect where indicated on plan.
 19. Restore all historic exterior light fixtures including new wiring and restored finishes.



O'Connell
ARCHITECTURE

3908 Avenue B, Suite 309
Austin, Texas 78751
512/751-1374



MILLER-LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751

ISSUE DATE


PRINT: 5/6/22

SHEET NAME


WEST
ELEVATION

SHEET NUMBER


A-214




6 WALL FLASHING DETAIL
Scale: Half Actual Size




4 WINDOW HEAD DETAIL
Scale: Half Actual Size




2 STUCCO WINDOW HEAD
Scale: Half Actual Size



5 TYPICAL WINDOW JAMB
Scale: 3" = 1'-0"




3 TYPICAL BRICK SILL DETAIL
Scale: Half Actual Size




1 STUCCO SILL DETAIL
Scale: Half Actual Size


WINDOW SCHEDULE		CONTRACTOR TO FIELD VERIFY ALL DIMENSIONS						
Mark	Room	Type	Dimensions			Material	Lites	Notes
FIRST FLOOR			Width	Height	Head Ht			
1	Sun Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
2	Sun Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
3	Living Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
4	Living Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
5	Half Bath #1	B	1'-7"±	4'-1"±	6'-6"±	Steel	2x4 lights	
6	Entry		2'2" DIA			Wood		
7	Closet	B	1'-7"±	4'-1"±	6'-6"±	Steel	2x4 lights	
8	Guest Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	Interior wooden screens
9	Guest Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	Interior wooden screens
10	Guest Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	Interior wooden screens
11	Guest Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	Interior wooden screens
12	Bath Guest Rm. #1	B	3'-1"±	4'-1"±	8'-0"	Steel	2x4 lights	
13	Bath Guest Rm. #1	C	1'-7"±	4'-1"±	8'-0"	Steel	4x4 lights	Missing Center Bar
14	Half Bath #2	C	1'-7"±	4'-1"±	8'-0"	Steel	4x4 lights	
15	Dining Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
16	Dining Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
17	Dining Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
18	Dining Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
19	Living Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	Remove and Salvage for Parts
20	Living Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	Remove and Salvage for Parts
21	Sun Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
21	Sun Room	A	3'-1"±	4'-1"±	8'-0"	Steel	4x4 lights	
22	Sun Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
23	Sun Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
24	Sun Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
25	Sun Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
26	Sun Room	A	3'-1"±	5'-1"±	7'-4 ½"	Steel	4x5 lights	
SECOND FLOOR								
27	Sitting Room	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	Interior wooden screens
28	Sitting Room	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	Interior wooden screens
29	Bedroom 4	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	Interior wooden screens
30	Bedroom 4	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	Interior wooden screens
31	Bedroom 2	E	4'-7"±	5'-1"±	7'-2"	Steel	6x5 lights	Sprung L/H Sash
32	Bedroom 2	E	4'-7"±	5'-1"±	7'-2"	Steel	6x5 lights	Missing right-hand sash
33	Bath 1	D	1'-7"±	3'-1"±	7'-7"	Steel	2x3 lights	
34	Bath 1	B	1'-7"±	4'-1"±	7'-7"	Steel	2x4 lights	Interior wooden screens
35	Bath 3	E	4'-7"±	5'-1"±	7'-2"	Steel	6x5 lights	Interior wooden screens, mismatched handle
36	Bedroom 3	E	4'-7"±	5'-1"±	7'-2"	Steel	6x5 lights	
37	Bedroom 3	E	4'-7"±	5'-1"±	7'-2"	Steel	6x5 lights	
38	Bedroom 3	B sim	3'-1"±	4'-1"±	7'-6"	Steel	4x4 lights	No transom
39	Media Room	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	Replace missing center bar to match original
40	Media Room	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	
41	Sitting Room	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	
42	Sitting Room	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	
43	Sitting Room	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	
44	Sitting Room	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	
45	Sitting Room	A	3'-1"±	5'-1"±	7'-2"	Steel	4x5 lights	
THIRD FLOOR								
46	Attic - North Side	F	1'-7"±	6'-2"	9'-0"	Steel	2x6 light-arch	
47	Attic	G	3'-1"±	6'-3"±	9'-2"	Steel	4x6 lights	New window sim to type A, but with add'l transom row
48	Attic - East Side	F Sim	1'-7"±	6'-2"	9'-0"	Steel	2x5 light-arch	3-lite tall operable sash
49	Attic	Velux venting skylight or approved equal						
BASEMENT								
50	Basement	H	2'-9"	2'-2"		Steel	3x2 lights	New window to replace missing original
51	Basement	H	2'-9"	2'-2"		Steel	3x2 lights	New window to replace missing original




3 WINDOW TYPES
Scale: 3/8" = 1'-0"




A Fixed Sash Head & Jamb
Scale: Half Actual Size




B Fixed Transom over Csmt.
Scale: Half Actual Size



C French Csmt. Meeting Stile
Scale: Half Actual Size



D Csmt. Jamb Detail
Scale: Half Actual Size




E Csmt. Sill Detail
Scale: Half Actual Size

Basis of Window Design: Torrance Steel Window Co, 2600 Series


All Dimensions on details shown at the exterior of window

Installation shall conform to details on Sheet A-501




F Hopper Head Detail
Scale: Half Actual Size


G Hopper Jamb Detail
Scale: Half Actual Size



H Hopper Sill Detail
Scale: Half Actual Size



1 WINDOW 47 (New)
Scale: 1" = 1'-0"



2 NEW BSMT. WINDOWS
Scale: 1" = 1'-0"

O'Connell
ARCHITECTURE
3908 Avenue B, Suite 309
Austin, Texas 78751
512/751-1374



MILLER-LONG HOUSE
RESTORATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751

ISSUE DATE


PRINT: 5/6/22

SHEET NAME


DOORS &
WINDOWS

SHEET NUMBER


A-610





D Meeting Stile Detail
Scale: Half Actual Size



C Jamb Detail
Scale: Half Actual Size




B Door Head Detail
Scale: Half Actual Size




A Door Bottom Rail
Scale: Half Actual Size

5 NEW FRENCH DOOR #122
Scale: 1" = 1'-0"


Basis of design: Torrance Steel Window
Co. 1900 Series French Door




4 NEW LEAVES FOR DOOR 104
Scale: 3/4" = 1'-0"



3 CASING PROFILE FOR NEW DOORS
Scale: Half Actual Size




2 TYPICAL EXISTING DOOR CASING
Scale: Half Actual Size



1 DOOR TYPES
Scale: 1/4" = 1'-0"

DOOR SCHEDULE		CONTRACTOR TO FIELD VERIFY ALL DIMENSIONS					
Mark	Room	Type	Dimensions		Material	Lites	Notes
			Width	Height			
101	Front Door	F	3'-4"	7'-0"	Wood		Refinish historic Front Door
102	Entry Closet	A	2'-0"	6'-8"	Wood		Sand & refinish
103	Entry Half Bath	A	2'-0"	6'-8"	Wood		Sand & refinish
104	Bed Room #1	C	(2x) 2'-0"		Wood		planked @ inner, consult with architect
105	Closet- Bed Room #1	A	2'-8"	6'-8"	Wood		Reverse Swing, sand & refinish
106	Bath- Bed Room #1	A	3'-0"	6'-8"	Wood		New Door
107	Living Room	C	(2x) 2'-0"	7'-2"	Wood		planked @ inner, sand & refinish
108	Living Room	D	(2x) 2'-8"	7'-2"	Wood	15 each	Pair of historic French doors, sand & refinish
109	Living Room	D	(2x) 2'- 8"	7'-2"	Wood	15 each	Pair of historic French doors, sand & refinish
110	Sun Room	E	2'-10"	7'-9"	Wood	8 lights	Refinish door and hardware
111	Dining Room	B	2'-8"	7'-2"	-		Salvage
112	Opening-close up		2'-8"	6'-8"	-		no door
113	Closet	A	2'-8"	6'-8"	-		Salvage for reuse
114	Kitchen	A	2'-8"	6'-8"	-		Salvage for reuse
115	Back Stair	A	2'-7"	6'-7"	Wood		Salvage for reuse
116	Rear Door from kitchen	G	2'-10"	6'-8"	Wood		Historic Door in Garage fits in existing frame
117	Kitchen back stair	A	2'-6"	6'-8"	Wood		New Door
118	Cellar Stair	A	2'-0"	6'-8"	Wood		New Door
119	Kitchen Half Bath	A	2'-6"	6'-8"	Wood		New Door
120	Dining Room	cased opn'g	2'-8"	6'-8"	-		
121	Dining Room	cased opn'g	5'-4"	7'-2"	-		
122	Living Room	NEW			Steel		New French doors
201	Bed Room #2	A	2'-8"	6'-7"	Wood		Reverse swing, sand & refinish
202	Bath- Bed Room #2	A	2'-8"	6'-8"	Wood		salvage door for use at #215
203	Closet- Bed Room #2	A	2'-0"	6'-7 ½"	Wood		Salvage door to owner
204	Hall to Bath	A	2'-8"	6'-7"	Wood		salvage door for use at #222
205	Closet	A	2'-0"	6'-7 ½"	Wood		salvage door for use at #216
206	Bedroom #3	A	2'-8"	6'-7 ½"	Wood		Reverse swing, sand & refinish
207	Bathroom #3	A	2'-8"	6'-7"	Wood		salvage door for use at #219
208	Closet- Bedroom #3	A	2'-8"	6'-7"	Wood		Salvage door to owner
209	Closet	A	2'-0"		Wood		Salvage door to owner
210	Bed Room #4	A	2'-8"	6'-7 ½"	Wood		Sand & refinish
211	Bath-Bed Room #4	A	2'-8"		Wood		Salvage door for use at #217
212	Sitting Room	A	2'-8"		Wood		Reverse swing, sand & refinish
213	Media Room	A	2'-8"		Wood		Sand & refinish
214	Sitting Room	A	2'-8"		Wood		Sand & refinish
215	Bath- Bed Room #2	A	2'-8"	6'-8"	Wood		Relocate door & frame 202, sand & refinish
216	Closet- Bed Room #2	A	2'-0"	6'-8"	Wood		Relocate door & frame 205, sand & refinish
217	Laundry Closet	A	2'-8"	6'-8"	Wood		Relocate door & frame 211, sand & refinish
218	Closet Bed Room #3	A	(2x) 1'-8"	6'-8"	Wood		New Door
219	Bath Bed Room #3	A	2'-8"	6'-8"	Wood		Relocate door & frame 207, sand & refinish
220	Closet Bed Room #4	A	2'-6"	6'-8"	Wood		New Door
221	Bath Bed Room #4	A	2'-6"	6'-8"	Wood		New Door
222	Attic Stair	A	2'-8"	6'-8"	Wood		Relocate door & frame 204, sand & refinish
223	Closet Media Room	A	2'-6"	6'-8"	Wood		New Door
301	Attic	A	2'-6"	6'-8"	Wood		New Door
302	Bath	A	2'-8"	6'-8"	Wood		New Sliding Barn Door
303	Linen Closet	A	2'-0"	6'-8"	Wood		New Door

SYMBOL LEGEND

 FFE

0"

FFE OR GRADE ELEVATION AS NOTED

112

DOOR NUMBER

116

WINDOW NUMBER

A

WALL TYPE (PLAN VIEW)

NEW WALL (PLAN VIEW)

℄

CENTERLINE

EQUAL DIMENSIONS IN LINE

1

A-211

ELEVATION (LARGE SCALE)

W

E

N

S

ELEVATION (SMALL SCALE)

1

A-211


SECTION DETAIL


1


A-211


PLAN/ ELEVATION DETAIL


MATERIALS LEGEND


 BRICK MASONRY


 CONCRETE (Detail Scale)


 EARTH


 STEEL (Detail Scale)


 FRAMING WOOD (Detail Scale)


 BLOCKING - NON-CONTINUOUS (Detail Scale)


 FINISHED WOOD

 PLYWOOD

 BATT INSULATION

 RIGID INSULATION

 PLASTER OR CONCRETE AS NOTED (Detail Scale)

 NEW PARTITION WALL (see plan legend)

GENERAL NOTES

1. All work shall be performed in a professional matter, and in accordance with the International Residential Code, 2012, related trade codes, and applicable local codes, ordinances and laws.
2. Base drawings used in these documents were prepared by others, and may contain dimensional discrepancies. Contractor shall verity critical dimensions before beginning work. Do not scale drawings. Ask Architect for needed dimensions if not provided.
3. Historic designation of this building requires the Contractor and his subcontractors to exercise special caution in executing the work to prevent unnecessary damage to historic features, conditions, or materials. Contractor shall inform all subcontractors and workmen of these requirements.
4. The Contractor shall thoroughly example and familiarize himself with the requirements of the Contract Documents. Any conflicts shall be brought to the Architect's attention for resolution prior to the work being installed.
5. Perform all work in a safe and conscientious manner to prevent injuries and damage to the building and workers. Contractor shall maintain OSHA Standards for job safety and worker protection, and comply with applicable state and local government requirements.
6. Building permitting will be coordinated by the Owner and Architect prior to construction. Contractor is responsible for all trade permits, inspections, and compliance requirements.
7. Maintain the building and site in a clean and orderly condition.
8. The Contractor shall visit the site of the proposed work and full acquaint himself with the existing conditions regarding site access, staging, parking limitations, security, and other aspects of constructibility.
9. The Contractor shall coordinate work between all trades in this contract to ensure a smooth and timely workflow.
10. All work to be warranted for one year from the date of Substantial Completion unless otherwise noted.

ABBREVIATIONS

&	And	CONC	Concrete	FAR	Floor-Area Ratio	I.E.	Id Est (That Is)	MTL	Metal	R	Radius/Refrigerator	STL	Steel
#	Pound	CONT	Continuous	FF(E)	Finished Floor (Elevation)	IG	Insulated Glass	N	North	RCP	Reflected Ceiling Plan	STRUCT	Structural
@	At	COORD	Coordinate, Coordination	FIN	Finish(ed)	IN	Inches	NA	Not Applicable	RE/REF	Reference	T&G	Tongue & Groove
A/C	Air Conditioning	CR2	Critical Root Zone	FAKT	Fixture	INAC	Inaccessible	NIC	Not in Contract	REINF	Reinforced	TEMP	Temporary, Tempered
ACOUST	Acoustical	CVR	Cover	FLR	Floor	INCL	Including	NO	Number	REQ'D	Required	THK	Thick
ADD'L	Additional	CW	Cold Water	FT	Feet, Foot	INFO	Information	NSF	Net Square Feet	REQMT'S	Requirements	TOT	Total
ADJ	Adjacent	D	Deep, Depth, Dryer	FTG	Footing	INSUL	Insulation	NTS	Not to Scale	REV	Revision	TOW	Top of Wall
AFF	Above Finish Floor	DBL	Double	FV	Field Verify	INT	Interior	OC	On Center	RFG	Roofing	TRTD	Treated
AHJ	Authority Having Jurisdiction	DEMO	Demolish, Demolition	FV HT	Field Verify-Height	JNT	Joint	OCEW	On Center Each Way	RM	Room	TYP	Typical
AHU	Air Handling Unit	D-H	Double Hung	GA	Gauge	JST	Joist	OP'G	Opening	RO	Rough Opening	UC	Under Counter
APPROX	Approximately	DIA	Diameter	GALV	Galvanized	L	Length	OVHD	Overhead	ROW	Right of Way	UNFIN	Unfinished
ARCH	Architect	DIAG	Diagonal, Diagonally	GFCI	Ground Fault Circuit Interrupt	LB(S)	Pound(s)	OZ	Ounce	S	South	UNO	Unless Noted Otherwise
ASTM	American Society for Testing & Materials	DN	Down	GL	Glass	LF	Linear Foot	P&I	Provide & Install	SALV	Salvage	VERT	Vertical
BRD	Board	DS	Downspout	GPM	Gallons Per Minute	LP	Light Pole or Lightning Protection	PC	Photo Cell	SAU	Self-Adhering Underlayment	W	Wide, Width, West,
BLDG	Building	DW	Dishwasher	GR	Grade	LT	Light	PG	Page	SCH'D	Scheduled	W/O	Without
BRM	Bedroom	DWG	Drawing	GR	Gross Square Feet	LVR	Louver	PL	Plate or Platlaine	SCH'D	Scheduled	W/D	Washing Machine
BTWN	Between	DWR	Drawer	GSF	Gypsum Wall Board	SHT	Sheet	PR	Pair	SHT	Sheet	WD	Wood
CAB	Cabinet	E	East	HB	Hose Blb	MAX	Maximum	PSF	Pounds Per Square Foot	SHV	Shedding	WVW	Window
CL	Centerline	EA	Each	HDR	Header	MECH	Mechanical	PSI	Pounds Per Square Inch	SHTG	Sheathing	WH	Water Heater
CLC	Ceiling	EJ	Expansion Joint	HDWR	Hardware	M/E	Mechanical/Electrical	PT	Pressure Treated	SMACNA	Sheet Metal & Air Conditioning	WM	Water Meter
CLO	Closet	EM	Electric Meter	HR	Hour	MEP	Mechanical, Electrical, & Plumbing	PTD	Painted	SPEC'S	National Association, Inc.	WP	Waterproofing
CLR	Clear	EQUIP	Equipment	HT	Height	MIN	Minimum	PVMT	Polyvinyl Chloride	SPEC'D	Specified		
COL	Column	EXT'G	Existing	HVAC	Heat/Ventilation/	MISC	Miscellaneous	PWD	Plywood	SQ	Square		
COMP	Composite	EXT	Exterior		Air Conditioning	MTD	Mounted	QTR	Quarter	SS	Stainless Steel		


DESIGN TEAM

ARCHITECTURE

O'CONNELL ARCHITECTURE, LLC
TERESA O'CONNELL, AIA
3908 AVENUE B, SUITE 309
AUSTIN, TEXAS 78751
512.751.1374

STRUCTURAL ENGINEERING

TSEN ENGINEERING
210 BARTON SPRINGS RD., SUITE 250
AUSTIN, TEXAS 78704
512.474.4001



NORTH ELEVATION - FACING PARK BLVD

HISTORY

The Miller-Long House and Garage located at the corner of Park Blvd and Red River were constructed in the Tudor Revival style for Tom Miller and his wife Nellie in 1929. Tom Miller was an influential community leader who served as Mayor from 1933-1949 and 1955-1961, 22 years in all. The Tom Miller Dam is named in his honor.

Emma and Stuart Long purchased the property in 1950. Emma Long was the first female council member in Austin and later served as Mayor Pro Tem, another first for a woman. Long was a strong advocate for desegregation of public buildings, fair housing, and lower utility rates, as well as fair pay for firefighters, and police. Emma Long Park (formerly "City Park") is named in her honor.

Tom Miller and Emma Long are arguably two of Austin's most influential, effective, and dynamic leaders at a pivotal time in the city's history and development. A classic example of the Tudor Revival style of the early 20th century, the house has many distinctive features and finishes and remains closely associated with Miller and Long. Applications to the National Register of Historic Places and Austin Landmark designation are in process.

PROJECT INFORMATION

LEGAL DESCRIPTION: LOT 33 AND 34 BLK 23 OLT 14 DIV C PERRY ESTATE

ZONING: SF-3

APPLICABLE CODE: 2021 IRC

OCCUPANCY: Secondary Dwelling

YEAR CONSTRUCTED: 1929

HISTORIC: Officially determined eligible for individual listing on the National Register of Historic Places

SHEET LIST

- Architectural Drawings
- A-000

Cover Sheet
- A-900

Site Plan
- A-901

Demolition Plans & Floor Plans
- A-902

North and West Elevations
- A-903

South and East Elevations
- A-904

Sections & Wall Details
- A-905

Details
- A-906

Garage Door Details
- A-907

Schedules & Lighting Plans

- Structural Drawings
- S-801

Structural Notes
- S-802

Structural Notes
- S-803

Structural Notes
- S-901

Garage Foundation and Floor Framing Plan
- S-902

Ceiling and Roof Framing Plan
- S-1001

Typical Details
- S-1101


Foundation Details
- S-1201

Framing Details
- S-1202


Framing Details

AREA CALCULATIONS

811 Park - Lot 33		8662
813 Park - Lot 34		14427
	Total Lot Area per UDA	23089
Gross Floor Area		
Main House - Existing to Remain	First Floor	1637
	Second Floor	1637
	Attic over 6 ft. hgt.	709
	Area - House	3983
Secondary Dwelling (This Permit)		
	Ground Floor (conversion from garage)	575
	Second Floor	575
	Area - ADU	1150
Floor/Area Ratio		22.2%
Impervious Cover		
House - Existing (NIC)		1637
Stair and Site Wall - Existing		34
Garage/Apartment - Existing		575
Concrete Driveway		1554
Easement Access Drive		1289
Concrete Walks		350
Transformer Pads (NIC)		145
New stone wall		
Terrace, ramp, and stairs		
New path to Perry gate		
Brick Walk - New		117
AC Pad - New		4
Total Impervious Cover		5705
% Impervious Cover		24.7%



SITE LOCATION MAP



3908 Avenue B, Rm 309
Austin, Texas 78751
512/751-1374



MILLER-LONG HOUSE
GARAGE APARTMENT RENOVATION
813 PARK BOULEVARD, AUSTIN, TEXAS 78751

ISSUE DATE


PRINT: 5/6/22

SHEET NAME


COVER
SITE PLAN
NOTES

SHEET NUMBER


A-000




4 NORTH ELEVATION - Demolition
Scale: 1/4" = 1'-0"




2 NORTH ELEVATION
Scale: 1/4" = 1'-0"









3 WEST ELEVATION - Demolition
Scale: 1/4" = 1'-0"




1 WEST ELEVATION
Scale: 1/4" = 1'-0"









A SECTION A-A at STAIR
Scale: 1/4" = 1'-0"




B SECTION B-B
Scale: 1/4" = 1'-0"




6 ROOF DETAIL
Scale: 1 1/2" = 1'-0"




5 TYPICAL WALL—Second Floor
Scale: 3" = 1'-0"




4 SIDE WALL FLASHING
Scale: 3" = 1'-0"




3 EAVE DETAIL
Scale: 1 1/2" = 1'-0"




2 DETAIL at SECOND FLOOR
Scale: 1 1/2" = 1'-0"




1 SILL DETAIL — REAR WALL
Scale: 1 1/2" = 1'-0"




6 SPLAY at STAIR OPENING
Scale: 1 1/2" = 1'-0"




5 EAVE SECTION
Scale: 3" = 1'-0"




4 SHED ROOF @ GARAGE DOORS
Scale: 3" = 1'-0"




3 EAVE DETAIL - GARAGE SHED
Scale: 3" = 1'-0"




2 BRACKETS for SHED ROOF
Scale: 3" = 1'-0"




1 SHED ROOF over GARAGE DOORS
Scale: 1" = 1'-0"




6 GARAGE DOOR — DETAIL
Scale: 3" = 1'-0"




4 JAMB DETAIL — GARAGE DOOR
Scale: 3" = 1'-0"




5 GARAGE DOOR — HEAD DETAIL
Scale: 3" = 1'-0"



3 GARAGE DOOR — SILL DETAIL
Scale: 3" = 1'-0"



2 PARTIAL ELEVATION FIXED GARAGE DOORS
Scale: 1 1/2" = 1'-0"



1 PLAN DETAIL — GARAGE DOOR
Scale: 1 1/2" = 1'-0"