# HISTORIC LANDMARK COMMISSION

# APPLICATION FOR A CERTIFICATE OF APPROPRIATENESS AUGUST 2, 2023

# HR-2023-087189, C14H-2002-0015 MOORE-WILLIAMS HOUSE 1312 NEWING AVENUE

#### **PROPOSAL**

Construct a ground-floor screened porch and two second-floor additions, connect the belvedere and the attic via new dormer, and repair deteriorated elements.

# **PROJECT SPECIFICATIONS**

- 1) Repair deteriorated wood shingle siding, lap siding, balustrades, columns, stairs and trim using epoxy repair methods. Limit replacement to severely deteriorated pieces.
- 2) Repair and repoint chimney.
- 3) Replace roof with matching composition shingles.
- 4) Clip roof gable at 2004 addition. Add a new dormer to rear.
- 5) Add a 2nd-floor playroom with hipped roof, removing an existing balcony. The proposed addition is clad in fiber cement siding
- 6) Connect original house to second floor over ca. 2006 garage in place of non-original balcony. The proposed addition has a low-slope membrane roof and south-facing double-hung windows of metal-clad wood.
- 7) Construct a new screened porch at rear-side.
- 8) Convert one non-original window to a new back door at rear addition.
- 9) Enlarge one non-original window on rear of house and relocate one non-original window on south elevation. Create dormer at rear of belvedere, retaining existing columns at belvedere. Create new roof cricket for water diversion at front elevation.
- 10) Add new dormer with clipped gable at west (rear) elevation, second floor, above garage.

#### ARCHITECTURE

The 2002 historic zoning staff report describes the building as a two-story c. 1890 wood-frame front-gabled house originally with Victorian details, a full width projecting front porch, prominent front tower, wood frame windows including some with stained glass, prominent brick chimney and projecting bay on south façade.<sup>1</sup>

#### **DESIGN STANDARDS**

The City of Austin's <u>Historic Design Standards</u> (March 2021) are based on the Secretary of the Interior's Standards for Rehabilitation and are used to evaluate projects at historic landmarks. The following standards apply to the proposed project:

# Repair and alterations

# 1. General standards

The proposed project removes minimal historic fabric and repairs, rather than replaces, deteriorated elements wherever possible. Elements deteriorated beyond repair will be replaced in-kind. Revision of non-historic features does not appear to damage historic material.

#### 3. Roofs

The proposed project replaces the shingle roof in-kind. Roof connections to additions do not appear to remove a significant amount of historic fabric. The proposed rear dormer changes the existing roofline, but appears minimally visible from the primary street; existing belvedere elements will not be removed for dormer installation.

# 4. Exterior walls and trim

The proposed project repairs deteriorated elements or replaces in-kind where deteriorated beyond repair.

# 5. Windows, doors, and screens

Proposed window modifications appear limited to non-original rear or side windows and openings.

<sup>&</sup>lt;sup>1</sup> Sadowsky, Steve. Zoning Change Review Sheet, C14H-2002-0015.

# Residential additions

#### 1. Location

The proposed additions' locations are mostly compatible, though upper-floor additions may be visible from oblique views of the primary streetscape. The rear and ground-floor additions impact mostly non-original material. While the belvedere addition is appropriately sited for its proposed function, removal of non-historic fabric may cause damage to historic material should it be removed in the future.

# 2. Scale, massing, and height

The proposed additions appear subordinate to the main house.

#### 3. Design and style

The proposed additions appear appropriate in style and design.

#### 4. Roofs

Proposed roofs are either not visible or match the existing shingle roof in slope, materials, and style.

#### 5. Exterior walls

Proposed exterior walls appear appropriately differentiated and compatible.

# 6. Windows, screens, and doors

Proposed windows, doors, and screens appear compatible.

#### 7. Porches and decks

The proposed first-floor screened porch appears compatible.

#### **Summary**

The project meets most of the applicable standards.

# PROPERTY EVALUATION

The property contributes to the Travis Heights-Fairview Park National Register district.

# STAFF RECOMMENDATION

Approve the application as-is, but suggest retaining existing separation of belvedere and attic, rather than adding a rear dormer.



