
Mexic-Arte Museum Project (25,696 GSF)


Meeting objective: to understand how the project is conforming with Design Guidelines


- Existing building located at 419 Congress Avenue
- Congress Avenue Historic District, however, the building is not historic
- Congress Avenue Façade will be rehabilitated, the remainder of the building will be demolished
- American Alliance of Museums Accreditation
- Requires new floor to floor heights of 18'-6"
- Requires new structure and foundations to meet loading requirements appropriate for museum occupancy
- LEED Silver Certification | AEGB 2 Stars
- Great Streets Program
- Program Requirements:
 - Museum Store
 - Galleries
 - Loading/Unloading
 - Administrative Offices
 - Support Spaces
 - AIPP (Art in Public Places) Mural
 - Rotating Mural Program
 - AD Space




Site Plan









Level 1 Plan




Level 2 Plan




Level 3 Plan




Roof Level Plan






North Elevation – 5th Street











MEXIC-ARTE MUSEUM
5TH STREET & CONGRESS AVE.