
Barton Springs Pool Bypass Culvert and Dam Repairs & Inlet/Outlet Grate Projects

PARKS & RECREATION BOARD & ENVIRONMENTAL BOARD

JOINT COMMITTEE

Update



JULY 31, 2012



Inlet/Outlet Repairs Update

- Work on site will begin in August
- 90 calendar days to complete
- Work on downstream gate may coincide with Bypass Repairs

Bypass/Dam Repairs Update

- Work on site will begin in October
- 159 calendar days to complete
- Pool will remain open during 1st Phase, approximately mid-November

Communication During Construction

- Weekly Updates
- Posted:
 - ■On-site
 - ■PARD Website
 - Other possible locations
- Other Information

- Why do we need to resurface the deck?
 - Protect the reinforcing steel from corrosion
 - Provide an uniform finish
- What happens if we don't seal the surface?
 - Shorten the lifespan of the repairs, possibly 10-15 years
 - Minor aesthetics issues
 - Possibly jeopardize the placing of tiles
- Are there any options?
 - Possible clear sealants for the deck, which would need to be reapplied on a regular basis
 - Try to match the finish of the existing deck













Tunnel Deck Resurfacing Next Steps

- Sample surfacing to placed for viewing
- Continue to look for options
- Decision before construction starts