

HISTORIC LANDMARK COMMISSION
APRIL 22, 2019
PERMIT IN NATIONAL REGISTER HISTORIC DISTRICT
NRD-2019-0023
2105 NEWFIELD LANE
OLD WEST AUSTIN HISTORIC DISTRICT

PROPOSAL

Demolish a ca. 1940 contributing house and replace with new construction.

ARCHITECTURE

The existing house is a one-story Minimal Traditional-style building clad in horizontal wood siding, with a cross-gabled composition shingle roof and gabled entryway. Its windows are 6:6 with wooden screens. It is set back approximately 25', in line with the other houses on the street. A contributing wood-frame accessory structure is located to the rear of the house.

PROJECT SPECIFICATIONS

The proposed primary building is two stories, with a standing-seam metal roof of varying heights and pitches. It is clad with horizontal fiber-cement siding at the first floor and vertical standing-seam metal at the second. It has fixed-pane windows of varying dimensions and irregular placement throughout, as well as a screened porch to the rear and stone fireplace at the south elevation. The building is set back 55' from the curb.

The proposed accessory structure is composed of garage space at the first floor and living space above. It has a gabled roof with two shed dormers at the north and south elevations and a spiral staircase leading to the second-floor entrance at the rear. It has horizontal siding and a standing-seam metal roof to match the main building. The accessory building is located in front of the house's primary elevation and set back 25' from the curb.

RESEARCH

The house at 2105 Newfield Lane was built around 1940 by real estate speculator Nat Franzetti. Its first owners were Lindsay B. and Carlotta Newsum. Lindsay Newsum worked as an engineer for the State Board of Insurance Commissioners, while Carlotta Newsum owned and operated Carlinda Antiques on Georgetown Road. By 1941, they had sold the property to J.D. and Gale Lemmon. Lemmon was in the Army, and sold the house shortly after purchase to Charles and Dorothy Kirstein, who owned the house less than two years. Kirstein, also a veteran, was trained as an expert furrier and worked at Snyder's department store for a number of years, along with his wife. After the home's few initial owners, it was a rental property with relatively rapid occupant turnover. Many renters were affiliated with the University of Texas, either as students or staff members.

STANDARDS FOR REVIEW

The Secretary of the Interior's Standards for Rehabilitation are used to evaluate projects on contributing buildings in National Register historic districts; general design principles state that additions should be secondary to the principal structure in terms of size, scale, and materials, and that they should be located at the rear of the house whenever possible. The addition should have materials, scale, and fenestration patterns compatible with the existing house. Applicable standards from the Secretary of the Interior's Standards for Rehabilitation include:

9. New additions, exterior alterations, or related new construction shall not destroy historic materials that characterize the property. The new work shall be differentiated from the old and shall be compatible with the massing, size, scale, and architectural features to protect the historic integrity of the property and its environment.

The proposed new construction will require demolition of a contributing structure. It is differentiated from historic properties in the district by its modern cladding, fenestration, and two-story form. The proposed front-yard placement of the auxiliary garage structure and deep setback of the main house are not compatible with the lot placement of historic-age structures on the streetscape, nor are the proposed architectural features (metal siding, compound roof form, and irregular fenestration) compatible with the historic structures in the district.

10. New additions and adjacent or related new construction shall be undertaken in such a manner that if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.

If the proposed building were to be removed, the form and integrity of the historic district would be unimpaired; however, the proposed new construction requires removal of a contributing structure, thus impacting the overall integrity of the district.

Designation Criteria—Historic Landmark

- 1) The building is over 50 years old.
- 2) The building appears to retain integrity.
- 3) Properties must meet two historic designation criteria for landmark designation.
 - a. **Architecture.** The building does not appear to be architecturally significant.
 - b. **Historical association.** There do not appear to be significant historical associations.
 - c. **Archaeology.** The property has not been evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
 - d. **Community value.** The property does not appear to possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the community, city, or state.
 - e. **Landscape feature.** The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

COMMITTEE RECOMMENDATION


Consider retention and adaptive reuse of the existing house. For the proposed new construction, move the detached garage to the rear of the main house. Consider adding a porch to create a better transition between the two-story structure and the predominantly one-story streetscape.

STAFF RECOMMENDATION

Postpone the public hearing to June 24, 2019 to encourage rehabilitation and adaptive re-use of the existing building, and consider a demolition delay, as the building is contributing to the historic district. Encourage relocation over demolition. If the demolition permit is released, then staff recommends completion of a City of Austin Documentation Package, consisting of photographs of all elevations, a dimensioned sketch plan, and a narrative history, for archiving at the Austin History Center.

Staff supports all Committee recommendations for the new design and also recommends eliminating the metal siding from the new design, adding regular fenestration patterns and divided-light windows, and simplifying the roof form throughout to avoid visual competition with the smaller-scale Minimal Traditional buildings on the street.

LOCATION MAP



PROPERTY INFORMATION

Photos



Primary (west) façade of 2105 Newfield Lane.



Google street view of Newfield Ln showing adjacent structures

Occupancy History

Completed by Historic Preservation Office staff
April 2019

- 1939 Address not listed in directory
- 1941 Lindsay B. and Carlotta Newsum, owners
Assistant engineer, State Board of Insurance Commissioners
Proprietor, Carlinda Antiques, 5224 Georgetown Rd.
- 1944 J. D. and Gale Lemmon, owners
U.S. Army
- 1947 Charles and Dorothy L. Kirstein, owners
Furrier, Snyder's Smart Shop
Saleswoman, Snyder's
- Harry and Janice Dunlap, renters
Office manager, KTBC
- 1949 Arthur W. and Jane Wilson, owners
Department manager, Hutchins Brothers
- 1952 Shirley and Gertrude Gardner, renters
Accountant
- Mrs. Hildegaard S. Gardner, renter
Assistant actuary, Western Reserve Life Insurance
- 1955 Edward S. and Hildegaard Gardner, renters
Auditor
Department head, Western Republic Life Insurance
- 1959 Edward S. and Hildegaard Gardner, renters
Accountant
Assistant actuary Western Republic & Plymouth Life Insurance, 702 Colorado
- 1962 Hillared Norman, renter
Clerk
- 1965 Edward S. Gardner, renter
student
- 1968 H.P. Ethleved and Anastasia Hammerloch, renters
Animal tester approval
- H.P. III and Emma Y. Ethleved, renters
Animal tester
- Gremillion T. Ethleved, renter
Animal sampler

Terry L. Weldon, renter
Student

1973 Susan Martin, renter
Technologist, County Health Department
Note: The directory listing indicates that Susan Martin is a new resident.

1977 Randall A. Puckett, renter
Student

1981 John Dennison, renter
No occupation listed
Note: The directory listing indicates that John Dennison is a new resident.

1986 Grover S. Campbell, renter
Assistant professor, U of T

1992 Helen L. Lettunich, renter
Programs travel coordinator, U of T
Note: The directory listing indicates that Helen L. Lettunich is a new resident.

Building Permits

	Nat. Franzetti		2105 Newfield La.	
148	-	-	33	-
	Esfield G			
	Frame Res. & Box Garage			
	18911 - 2-23-40			
	5			

Building permit issued to Nat Franzetti, 2/23/1940.

WATER SERVICE PERMIT No 17189

Austin, Texas *20148*

Received of Nat Franzetti Date Feb 26, 1940

Address 2105 Newfield Lane

Amount Two And 50/100 - - - - - \$ 2.50

Plumber Smoot Size of Tap 1/2"

Date of Connection 2-28-40

Size of Tap Made 1/2"

Size Service Made 1/2"

Size Main Tapped 6"

From Front Prop. Line to Curb Cock 5'6"

From S. Prop. Line to Curb Cock 21'

Location of Meter P. W. B.

Type of Box 2014

Depth of Main in St. _____

Depth of Service Line _____

From Curb Cock to Tap on Main _____

Checked by Engr. Dept. 3-18-40 LE

No. Fittings	Size	Curb Cock	Elbow	St. Elbow	Bushing	Reducer	Pipe	Lead Comp.	Nipples	Union	Plug	Tap	Stop	Box	Lid	Valves	Job No.	Req. No.
1											1							
1											1							

See 7470

INDR 111

Water service permit issued to Nat Franzetti, 2/26/1940.

Connection Charge \$ 2.00 No 165888

APPLICATION FOR SEWER CONNECTION.

Austin, Texas, 2-23 1940

To the Superintendent of Sewer and Public Improvements,
City of Austin, Texas

Sir:—

I hereby make application for sewer connection and instructions on premises owned by Nat Franzetti at 2105 Newfield Lane Street, further described as lot 33, block _____, outlet _____, subdivision Emhill 27, division _____, plat 140, which is to be used as a Res.

In this place there are to be installed _____ fixtures.

I agree to pay the City Sewer Department the regular ordinance charge.

Respectfully, J. G. Thompson
J. G. Thompson

Stub Out AT - PL

Connected 4-5 19 40 Permit Pd 3-9-40

Size of Main 4" H.C. inches. 4-3-40

Size of Service 4 inches. 01

2 Feet Deep at curb

Feet from Property Line _____

Feet from Curb Line _____

Inspected by Boothright

Connection made by Conington 4-1381

13146 Sewer in Newfield Lane
at location of Stub. L. H. B.

Sewer connection permit issued to Nat Franzetti, 2/23/1940.