# HISTORIC LANDMARK COMMISSION JUNE 22, 2020 DEMOLITION AND RELOCATION PERMITS HDP-2020-0205 1615 HOLLY STREET

#### PROPOSAL

Demolish a ca. 1942 house.

#### ARCHITECTURE

The house at 1615 Holly Street is a one-story rectangular-plan cottage with a side-gabled composition shingle roof. Box columns support its shed-roofed entryway. It is clad in vertical wood siding, with 2:2 aluminum replacement windows and metal handrails flanking a poured concrete stoop.

#### RESEARCH

The house was constructed in 1942 by Martin Herman, who sold it to Ernest J. and Ethel Kunkel in 1944. Kunkel was a taxi driver. He and his wife lived at 1615 Holly until around 1946, when they sold the home to Mary Gonzales Cordova and her husband Vicente, who worked as an upholsterer. The Cordovas leased the home until after 1952. By 1955, Lorenzo and Mary Corpus had purchased it. Lorenzo Corpus worked for the City's Water and Sewer Department as a pipe layer. The Corpus family lived at 1615 Holly until at least 1972, when they remodeled the home.

#### STAFF COMMENTS


1615 Holly Street was recommended in the 2016 East Austin Historic Resource Survey as a contributing structure to potential National Register and local historic districts.

Designation Criteria—Historic Landmark

- 1) The building is under 50 years old.
- 2) The building appears to retain moderate to high integrity.
- 3) Properties must meet two criteria for landmark designation (LDC §25-2-352). The property does not appear to demonstrate significance according to City Code:
  - a) Architecture. The building does not appear to convey architectural significance.
  - b) Historical association. There do not appear to be significant historical associations.
  - c) *Archaeology*. The house was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
  - d) *Community value*. The house does not possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the city, the neighborhood, or a particular demographic group.
  - e) *Landscape feature*. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

#### STAFF RECOMMENDATION

Encourage rehabilitation and adaptive re-use, then relocation. Release the permit upon completion of a City of Austin documentation package.





CASE#: HDP-2020-0205 LOCATION: 1615 Holly Street

This product is for informational purposes and may not have been prepared for or be suitable for legal, engineering, or surveying purposes. It does not represent an on-the-ground survey and represents only the approximate relative segation of properly boundaries.




This product has been produced by CTM for the sole purpose of geographic reference. No elements is made by the City of Austin regarding specific accuracy or completeness.



#### PROPERTY INFORMATION







Zillow.com and Google Street View, 2009-19

Occupancy History

City Directory Research, May 2020

Historic Preservation Office

Note: Scope of research limited by library closure.

1959 Lorenzo P., Sr. and Mary S. Corpus, owners

1955 Lorenzo Perez and Mary Schafer Corpus, owners

Pipe layer, City Sewer & Water Department

1952 D. L. and Vallie Hibbs, renters

Mechanic

1949 Martin Howard and Frances Augusta Toliver, renters

Bricklayer

Waitress, Austin State School

1947 Vincente and Mary Cordova, owners

Upholsterer, Gregory Furniture

Ernest J. and Ethel Kunkel, owners 1944-45

Taxi driver

Biographical Information

# 3 Men Hold Up Taxi Driver

Ernest Kunkle, 1615 Holly, taxicab driver, reported to police Friday a holdup by three men Thursday might near Lake, Austin on Pecos street.

He said he picked up the three men at Seventh and Congress about 11 p. m. to take them to Lake Ausun. As they approached Hopi trail on Enfield road, he was told to turn right. He did so, he said, and then figuring something was wrong, he attempted to get back on the main road by Pecos when he was told to stop and hand over his money,

When he refused, he was struck by the man in the front seat, grabbed from behind by the other two men and knocked out. He said he regained consciousness about 7 a.m.

regained consciousness about 7 a.m. and found his wallet containing about \$12 was missing.

He described one of the men as being about 5 feet 9 inches tall, weighing about 155 pounds, with dark hair and dressed in khaki trousers and a white sport shirt.

The Austin Statesman: Jul 21, 1944



Lorenzo P. and Mary S. Corpus, 1940s. Source: https://www.findagrave.com/memorial/26209952/mary-corpus and https://www.findagrave.com/memorial/26202412/lorenzo-perez-corpus

#### **Building Permits**

## Martin Herman

1615 Holly St

58

52'3150' 08 4

#### Frame Res

### 23234- 1-19-42

Building permit, 1-19-42

"E. J. Kunkel

1615 Holly St.

58

 $2 50 \times 150$ 

one room addn. to res.

25748 5-25-44 \$183**,00** 

#### owner

Building permit for addition, 5-25-44

OWNER	Loranzo	Corpus	s ,		ADD	RESS	1615	Hol1	y St.
PLAT	16	LOT	50	x 1		of			BLK
SUBDIV	ISION Un	platte	ď						
OCCUPAL	NCY Re	sidenc	e -	27900000			3		
BLD PE	1.0	0255	DATE	6 – 2	6-7	2	OWNER ESTIM		\$3340.00
CONTRAC	CTOR OWN	er	_				NO, O	F FIXT	URES
WATER 7	TAP REC #				SEW	ER 7	CAP REC	#	
	Remode1	exist	<b>s</b> esi	iden	ce				
	APPLICATION TO the Sirit of here against the subdivise which is agreement to the subdivise which is ag	described a dion sto be used is place there ee to pay the store of the	SEWER  Teles ent of Sent of Sity  population by  // s lot  as a  re are to	CONNI CONNI of A n for s	prid I	SN	Non 1	18335 Lents, 1 instruct	reet,
	AT Stub On Connect Size of Size of	Pl it d 2 Main 3/ Service Y Feet Deep	٥٥	inches		St	18-42	-	
	Inspector Connec	tion made h	Curb L	ghi.	f gto	5 5 5 5 7 7 7 8 7 8	R- S-42	10 v 1 PL 1 <b>4 CL</b> 8 BB	