HISTORIC LANDMARK COMMISSION PERMITS IN NATIONAL REGISTER DISTRICTS APRIL 26, 2021 HR-2021-044308 OLD WEST AUSTIN NATIONAL REGISTER DISTRICT 2314 WOODLAWN BLVD.

PROPOSAL

Partially demolish ca. 1939 contributing house and construct additions to the side and rear, replace all windows, paint brick, reconfigure ca. 1941 garage, and construct landscape improvements.

PROJECT SPECIFICATIONS

- 1) Construction of a two-story addition to the back (west) and north sides of the home. The addition will be clad in brick on the first floor and horizontal wood siding on the upper floor.
- 2) Replacement of all windows with 2:2 light single-hung or fixed wood windows.
- 3) Painting previously unpainted brick at the house and garage.
- 4) Replacement of three single-car garage doors on the detached garage with two doors.
- 5) Construction of a perimeter enclosure, at the front of the property consisting of a 1' to 2' tall masonry wall with metal pickets between masonry piers, for an overall height of 8', and a solid masonry wall at the side and rear.
- 6) Construction of trellises, a pool, and sundeck in the back yard.

ARCHITECTURE

Two-story side-gabled Colonial Revival house clad in red brick, with central pedimented entry and 6:6 light windows with shutters. Side-gabled brick garage with three one-car overhead doors.

RESEARCH

The house at 2314 Woodlawn Blvd. was built for Dr. Samuel N. and May R. Key in 1939. Dr. Key was listed in city directories as a physician with offices in the Norwood Tower. His death certificate indicates he was a retired surgeon. His son, Dr. Samuel N. Key, Jr., also entered the medical profession.

STANDARDS FOR REVIEW

The City of Austin's Historic Design Standards (March 2021) are based on the Secretary of the Interior's Standards for Rehabilitation and are used to evaluate projects in National Register Historic Districts. The following standards apply to the proposed project:

Repair and alterations

- 5.1 Repair, rather than replace, historic windows, doors, and screens; and their trim, surrounds, sidelights, transoms, and shutters, unless they are deteriorated beyond the point of stabilization or restoration. Retain windows if 50% or more of the wood or metal sash members are intact.
- 5.3 If historic windows must be replaced, match the size and details of the existing window, including configuration, profile, and finish. Take into account elements such as frames, sashes, muntins, sills, heads, moldings, surrounds, hardware, and shutters.

The project entails significant modifications to the front door and decorative surround, including demolition of the walls adjacent to the door to create a larger door opening within a wider recess and without a step. The elevation drawing shows a simple pedimented surround in place of the scrolled pediment and Corinthian pilasters of the historic door surround. The new front door is glass.

The project also involves installation of all new windows that do not match the historic in their design, replacing 6:6 with 2:2 light single-hung or fixed windows. The front elevation has wood panels below the ground-floor windows. The project would remove the panels to fit taller windows within the existing openings.

Residential additions

- 1.1 Locate additions to the rear and sides of historic buildings to minimize visual impact.
- 1.2 Step back side additions from the front wall a distance that preserves the shape of the historic building from the primary

street.

The project includes an addition that wraps the side and rear of the property. At the side, the addition is set back only slightly, at 2'-7" from the front of the house, and disrupts the symmetry of the historic façade.

1.5 Minimize the loss of historic fabric by connecting additions to the existing building through the least possible invasive location and means.

The project entails extensive demolition of the side and rear of the house to accommodate the addition, including removal of the chimney and most of the side (north) elevation.

- 2.1 Design an addition to complement the scale and massing of the historic building, including height. The addition must appear subordinate to the historic building.
- 2.2 Minimize the appearance of the addition from the street faced by the historic building's front wall.
- 2.2 b. The historic building's overall shape as viewed from the street must appear relatively unaltered.

The addition is of a similar height and narrower width than the historic house. However, as previously noted, the addition introduces an asymmetrical element that alters the overall shape as viewed from the street.

- 4.1 If an addition will be visible from a street on the front or side, design its roof form and slope to complement the roof on the historic building.
- 4.2 Use roof materials that match or have similar color, texture, and other visual qualities as the roof on the historic building.

The ridgeline of the side-gabled roof on the addition is set slightly lower and behind that of the historic house, and the roof form, pitch, and shingles match the house. The project meets these standards.

- 3.1 Design additions to be compatible with and differentiated from the historic building, if they are visible from the street.
- 5.2 Differentiate the exterior wall materials of the addition from those of the historic building. This could be accomplished by using different materials, using the same materials with different dimensions, or changing trim type or dimensions.

The use of horizontal siding for the upper floor serves to differentiate the addition from the historic house. The project meets these standards.

Sites and Streetscapes

- 2.4 If constructing a new street-side fence or site wall, design it so that the materials, style, and scale are compatible with and differentiated from the architectural style and period of the building and are in keeping with historic fence styles and heights in the historic district.
- 2.4 a New front fences must be no more than 4' high and have a high degree of transparency.

The fence will be 8' tall but have a high degree of transparency.

The project does not meet many of the applicable standards and would render the house noncontributing to the National Register district.

STAFF COMMENTS

The house is contributing to the Old West Austin National Register District.

Designation Criteria—Historic Landmark

- 1) The building is more than 50 years old.
- 2) The building appears to retain high integrity.
- 3) Properties must meet two criteria for landmark designation (LDC §25-2-352). Staff has evaluated the property and determined that it does not meet two criteria:
 - a. *Architecture*. The building is a good example of the Colonial Revival-style architecture prevalent in the Old West Austin National Register district.
 - b. *Historical association*. While the house was owned for a considerable time by Dr. Samuel Key, a physician, limited information was found regarding his contributions to the medical field. As such, the property does not appear to have significant historical associations.
 - c. *Archaeology*. The property was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
 - d. *Community value*. The property does not possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the city, the neighborhood, or a particular demographic group.

e. Landscape feature. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

COMMITTEE FEEDBACK

Not reviewed.

STAFF RECOMMENDATION


Encourage design modifications to preserve the view of the property from the street through retention of the original windows and pedimented door surround, keeping the brick unpainted, and setting the side addition further back, but comment on and release the permit upon completion of a City of Austin Documentation Package.





NOTIFICATIONS

CASE#: HR 21-044308 LOCATION: ²³¹⁴ WOODLAWN BLVD



1"=195'

This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.



PROPERTY INFORMATION

Photos







Source: Realtor.com, 2021

Occupancy History City Directory Research, April 2021

1939	Not listed. Samuel N. and Mary R. Key listed at 1406 Windsor Rd.
1940	Samuel N. and Mary R. Key Samuel: physician, 505 Norwood Building
1941	Samuel N. and Mary R. Key Samuel: physician, 505-06 Norwood Building
1942	Samuel N. and May R. Key, owners Samuel: physician, 505-06 Norwood Building
1944	Samuel N. and May R. Key, owners Samuel: physician, 505-06 Capital National Bank Building
1947	Samuel N. and May R. Key, owners Samuel: physician, 503-06 Capital National Bank Building
1949	Samuel N. and May R. Key, owners Samuel: physician, 505 Capital National Bank Building
1952	Samuel N. and May Key, owners

	Samuel: physician, 505 Capital National Bank Building
1953	Samuel N. and May Key, owners Samuel: physician, 505 Capital National Bank Building
1954	Samuel N. and May Key, owners Samuel: physician, 505 Capital National Bank Building
1955	Samuel N. and May Key, owners No occupations listed
1957	May Key (widow Sam N. Key), owner No occupation listed
1959	May Key, owner

Biographical Information

MEDICAL SOCIETY MEETS.

Travis County Doctors Discuss Meningitis Thoroughly.

Meningitis was the general subject of discussion by members of the Travis County Medical Society last night, gathered in regular monthly session in the office of Dr. Harper, Scarbrough building. Dr. Z. T. Scott. secretary of the organization, read the statement made recently by the City Board of Health concerning the meningitis scars and what precautions the public should take. The society unanimously indersed the statement, and will adopt it as their attitude toward the disease, as far as a statement from them to the public is due.

public is due.
Dr. Z. T. Hundy, recently elected as president of the society, delivered his inaugural address. One main point upon which he dwell was the importance of education of the laity upon hodly health and how to provent and fight disease. His address was well taken.

Dr. Italph Steiner led the discussion on meningitis, assisted by Dr. Samuel Nov. The disease was discussed from every standpoint, and many helpful hints were let fail during the short talks. None expressed a fear that Austin might have an opidemic of this fatal disease.

It was decided to make the bulletin of the society, a number of which was recently issued, a permanent thing, to be published at regular intervals.

Among the prominent out-of-town doctors who were present and participated in the discussions were: Dr. C. C. Black of efforgetown, president of the Seventh District Medical Society; Dr. J. A. Holtoway of Round Rock; Dr. Carrington of Pflugerville and Dr. Hudson of Elgin.

2	1. PLACE OF DEA		LAAS	CERTIE		2 USUAL RES	AND DESCRIPTION OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN COLUMN	e FILE NO.		residence before
U		Travis				A. STATE	Texas	its. write REPAL	Trovid	3
w	b. CITY (II outside OR TOWN	Austin	pr	ecinet no.) STAY	yrs.	OR TOWN	Austin		and give prec	A CONTRACTOR
. 0	d. FULL NAME OF (HOSPITAL OR INSTITUTION	of not in hospital of Seton Hos	nital	street address or locati	oe)	d. STREET ADDRESS	2314 Wood	lawn Blvd	le o	
	3. NAME OF DECEASED	a. (First)		b. (Middle)		c. (Last)	4 DATE		-	
SIDE	(Type or Print)	Samuel 6. COLOR OR RA	CE 12 H	Newton		Key Sr.	DEATI	Septembe	r 3, 19	956 5 F UNDER 24 H
	Male	White	V. WI	ARRIED, NEVER MAI DOWED, DIVORCED Married	(Specity)	eptember 3	The second second	69	11 3	Hours Mis
REVERSE	Retired works	ON (Give kind of work and life, even if recired) 10b. KIND OF BUSINESS OR INDUSTRY Surgeon								
2	12. FATHER'S NAME			BIRTHPL		13. MOTHER'S MAI			400	THPLACE
I	William Merce 14. WAS DECEASED EVE		FORCES? LIS	Texas		Rhoda Izor		-	Texa	B
	(Yes. no. or unknown) (If	yes, give war or date	e at service)	SOCIAL SECONTI	00	no Az	m n.	Key s	2	
	17. CAUSE OF DEATH	I DISEASE OR	CONDITION		L CERTI	FICATION		0	1 18	TERVAL BETWEEN
FOR	Enter only one cause per line for (a), (b), and (c)	I. DISEASE OR DIRECTLY LEA	DING TO DEAT	H+(a) _ CON	book	Elkrou	Mosi	9	2	was
-	*This does not mean	ANTECEDENT								A control
LLED	the mode of dying, such as heart failure, aschenia, etc. It means the disease injury, or complica-									
S										
	# which arrived death II OTHER SIGNIFICANT CONDITIONS									1
INFORMATION	18a. DATE OF OPERATI			NGS OF OPERATION					19.	AUTOPSY?
*	ma ACCIDENT	(Hpedity)	20h PLACEO	FINJURY (a.g., in or at	sout I	20c.(CITY, TOWN.	00 000 men	VO CO A DESARRA		res No Z
£	20 a. ACCIDENT SUICIDE HOMICIDE	(abeaus)	bome, farm, fac	tory street, office bldg.,	ste.)	20c.(C117, 10mm,	TENNO	DEPARTMEN		EIN
99	20d. TIME (Mosth)	(Day) (Year)	(Hour)			20 f. HOW DID INJU		AU OF VITAL		re
품	INJURY			WORK LAT			-		A SECURIOR OF THE PARTY OF	LA COMPANIE
0TE	21. I hereby certify t	hat I attended	the deceased	d from 8			9/3 , 19	56, that I lass	t saw the d	rceased
9	alive on 7.	C. M. Day	rnall. M	at death occurred	22 b. AD	DRESS	causes and or	the date stated		TE SIGNED
	22. SIGNATURE (C. M. Darnall, M.D. Perres or title) 22. ADDRESS Capt. Natl. Bank Bldg., Austin, Tex. 22. DATE SIGNED									
	23a. BURIAL, CREMA	TION, REMOVAL			1	Z3c. NAME OF CEN	ETERY OR CRE	MATORY	-	
	Burial		Sep	tember 4,	1956	Austin M	emorial P	ark	10	
	Austin, Travi	The second second	(State)			y Funeral		lly F. Pe	al #372	3
- 1	25a. REGISTRAR'S FILE	s county	, Texas	BY LOCAL REGISTR		REGISTRARS		my r. re	6T 47/2)

Death certificate, Samuel Newton Key, Sr., 9/3/1956

Permits				
Connection Charge \$# /343 N. 15904				
APPLICATION FOR SEWER CONNECTION.				,
Austin, Texas, 7-15 19.39		,	•	,
To the Superintendent of Sewer and Public Improvements, City of Austin, Texas			•	
I hereby make application for sewer connection and instructions on premises owned by Dr. Si Wey				
at 2314 Woodlawn Street,			<i>y</i> ,.	
further described as lot 22, block, outlot,	<i>:</i>		-37	•
subdivision Sunset Hill, division, plat 148.	o de la companya del companya de la companya del companya de la co	.	n 71.	
which is to be used as a				
In this place there are to be installed fixtures.				
I agree to pay the City Sewer Department the regular ordinance charge. Respectfully,			÷1	
AT PL 8-22-39 Stub Out 8-22-39	115	-f		
Connected 19 Permit Pd.		V2/170	ر من کورنسخ	,
Size of Main inches.	Q A	1 Jr	100	•
Size of Service inches.	52	3/2/	-10/7, 13	7
Feet from Property Line Stule and	THE	10 griff	Thorp :	
Inspected by Colonial States				**************************************
Connection made by Months 18-12-25	. 8			
11781 Server at Southeast corner of late L.H. B.w		. \$		

Sewer tap permit, 1939

WATER SEE ICE PERMIT Austin, Texas N_0 13845/ Dr. Sam Key Date July 14, 1939 Received of 2314 Woodlawn Address. Ten and no/100 -10.00 Amount Spiller-Miller 1 " Plumber Size of Tap Date of Connection Size of Tap Made Size Service Made____ Size Main Tapped____ From Front Prop. Line to Curb Cock 12 Prop. Line to Curb Cock 5 2 Location of Meter Care Curb Cock St. Elbow Type of Box... Bushing Nipples Elbow No. Fittings Depth of Main in St. Depth of Service Line____ From Curb Cock to Tap on Main. Checked by Engr. Dept. 8-15-39 LE XXX 4700C MINDSOR

Water tap permit, 1939