1104 Charlotte St

Kindra Welch and family



720 sqft

Structural Board-Batten Siding,

Original front porch,

original front door,

3 out of 8 original windows











minor structural issues with original Juniper piers

1. Eastern front corner sits directly on the ground enabling deterioration of wood structure and a near constant termite invasion



2. Driveway slopes towards the house



3. The house is the focal point of 12th street traffic, including restaurant and retail traffic from commercial area 1 block away. New Years Eve '03-'04 a driver crashed his truck through the front wall and into the living room.






- 1. One corner sits directly in contact with the ground.
- 2. Driveway slopes towards the house
- 3. The house is the focal point of 12th street traffic.


LONG TERM SOLUTION:

Significantly Raise the House


(And hopefully maintain Historic Contributing Status)




EXISTING SITEPLAN




DEMO BACK PORCH




PUSH HOUSE AWAY FROM THE STREET APPROX. 4'-4" AND RAISE UP 6'-7'



PROPOSED SITE PLAN



Existing Survey And Proposed Siteplan






VIEW FROM THE EAST "NORTH DRIVE"



VIEW FROM THE SOUTHEAST "NORTH DRIVE"



VIEW FROM THE SOUTH "NORTH DRIVE"











Neighborhood context