HISTORIC LANDMARK COMMISSION

DEMOLITION AND RELOCATION PERMITS
JANUARY 24, 2022
GF-2022-000303
608 E. 41ST STREET

PROPOSAL

Replace all windows, open enclosed front porch and replace screens, remove chimney, replace roof with standing-seam metal, add dormer to main façade, remove decorative brackets, and construct a two-story addition immediately above the ridgeline of a ca. 1930 one-story house.

PROJECT SPECIFICATIONS

- 1) Window replacement: replace most existing windows, except porch windows. Window at main façade will be removed and replaced with new window of similar configuration. Windows at secondary elevations appear to be vinyl.
- 2) Open enclosed front porch, removing existing screens and knee wall, and replace screens with undivided retractable screen.
- 3) Remove existing brick chimney.
- 4) Replace roof with standing-seam metal roof to match proposed addition.
- 5) Add dormer to main façade. The proposed dormer is gabled, with a single arched window.
- 6) Remove decorative brackets at entryway and gable ends.
- 7) Demolish existing addition and carport and construct a two-story addition to the rear of the house, immediately above the existing roof ridge. The proposed addition is clad in painted brick and horizontal fiber- cement siding. Its irregular compound roof is clad in standing-seam metal and features shed, side-gable, and gabled profiles. Windows are a combination of fixed and 1:1 casement, with full-height 2:2 fixed windows with decorative half-timbered trim at the east elevation and an ornamental fountain beneath. Decorative exposed purlins are proposed for eave overhangs at east and rear elevations.

ARCHITECTURE

One-story cross-gabled house with partial-width inset screened porch, steep gable with deep eaves and triangular knee braces, arched front entryway with decorative brackets and exposed rafter tails at gabled portico, original lattice window at main façade, and horizontal wood siding.

RESEARCH

The main house at 608 E. 41st Street was constructed around 1930 by W. D. Nealand. Frances and W. Bryan Stoermer were its first and longest-term owners. W. B. Stoermer owned and operated a welding and machinist shop with his brother Clarence. The shop was located on E. 5th Street, though the address changed from the 100 block to the 300 block. The Stoermers constructed a rear dwelling unit in 1936, and it became a steady rental property even after their departure in the early 1940s.

DESIGN STANDARDS

The City of Austin's <u>Historic Design Standards</u> (March 2021) are based on the Secretary of the Interior's Standards for Rehabilitation and are used to evaluate projects at potential historic landmarks. The following standards apply to the proposed project:

Repair and alterations

1. General standards

The proposed project removes some historic-age material at visible elevations, including character-defining decorative details.

3. Roofs

The proposed metal replacement roof is not compatible with the historic building's style but is considered an acceptable modification within historic districts per the design standards.

5. Windows, doors, and screens

The demolition plan indicates that a lattice window at the main elevation will be replaced; however, the replacement appears

to match the existing.

6. Porches

The proposed modifications restore the porch's open design and replace stationary screening with retractable screens that will not permanently obscure the front of the house.

7. Chimneys

The proposed project modifies the original brick chimney to accommodate the addition.

Residential additions

1. Location

The proposed addition is located immediately above the existing roof ridgeline. The proposed dormer is situated in front of the existing ridgeline, immediately atop the porch. The citywide design standards specify that additions should be located behind the ridgeline of the existing building; neither the dormer nor the second-story addition meet this standard.

2. Scale, massing, and height

The proposed addition does not appear subordinate to the main house due to its scale, height, compound roofline, and placement. The dormer alters the massing of the historic portion of the house to remain.

3. Design and style

The proposed addition is adequately differentiated from the existing house; however, its window-to-wall area ratios, floor-fenestration patterns, and bay divisions at secondary elevations are minimally compatible, particularly at the east elevation, which will be partially visible from Peck Avenue. Adding incompatible decorative details to the new portion of the house (exposed purlins, half-timbered trim, and water features) while removing brackets and exposed rafter tails from the historic portion of the home detracts from the overall compatibility of the project.

4. Roofs

The proposed addition's roofline is complex and visible above the single-story portion of the house. Its standing-seam metal material is less compatible than shingle roofing.

5. Exterior walls

The proposed addition's primary and secondary materials appear mostly compatible, with the exception of elaborate trim at the east elevation.

6. Windows, screens, and doors

The proposed addition's fenestration is mostly hidden from the street view; however, the full-height window at the east elevation would be visible from the secondary street. The arched window at proposed dormer is somewhat compatible; though its shape may be difficult to differentiate from existing arched details, it appears on a clearly added element.

7. Porches and decks

The addition's proposed porches and balconies do not appear to be visible from the street, except for the east elevation's second-floor balcony, which is not compatible with the style of the existing house.

Summary

The project meets few applicable standards.

PROPERTY EVALUATION

The draft North Loop-Hancock-Boggy Creek survey lists the property as a medium priority.

Designation Criteria—Historic Landmark


- 1) The building is more than 50 years old.
- 2) The building appears to retain high to moderate integrity.
- 3) Properties must meet two criteria for landmark designation (LDC §25-2-352). Staff has evaluated the property and determined that it does not meet two criteria:
 - a. Architecture. The building is constructed in the Tudor Revival style.
 - b. Historical association. The property does not appear to have significant historical associations.
 - c. Archaeology. The property was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
 - d. Community value. The property does not possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the city, the neighborhood, or a particular demographic group.

e. Landscape feature. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

STAFF RECOMMENDATION

Approve the application upon completion of a City of Austin Documentation Package, encouraging the applicant to simplify the addition's roofline, push the addition back further from the existing roof ridge, omit the dormer at the main elevation, retain original decorative details and fenestration where it exists at the historic portion of the house, and simplify the east elevation to appear more understated from Peck Avenue.





NOTIFICATIONS

CASE#: GF 22-000303 LOCATION: 608 E 41ST STREET

This product is for informational purposes and may not have been prepared for or be suitable for legal, engineering, or surveying purposes, it does not represent an on-the-ground survey and represents only the approximate relative location of property boundaries.

1"=250'


This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.



Photos







Partial demolition application, 2022

Occupancy History

City Directory Research, January 2022

1959 O. H. Hoffmeyer, renter

1957

Wilford C. Wilde, owner Research engineer, University of Texas

1955 Daird A. and Mirien Senter, renters

Student

1952	William J. and Lila Brooks, owners Cotton buyer Country Club of Austin
1949	William J. and Lila Brooks, owners Cotton buyer
	Mary V. Brooks, renter Clerk, Texas Employment Commission
1947	William F. and Maxine Winters, owners Student, University of Texas
	Vacant
1944	David H. and Frances Swope, renters USA
	J. Harold and Elizabeth Wade, renters USA
	Gilbert L. and Mary J. Koehler, renters USA
1941	W. Bryan and Frances Stoermer, owners Stoermer Bros.
	Louis M. and Mary E. Koch, renters Draftsman, State Highway Department
1939	William B. and Frances Stoermer, owners Stoermer Bros.
	Lester B. and Marjorie Hobbs, renters Salesman, Standard Brands Inc.
1937	William Bryan and Frances Stoermer, owners Stoermer Bros.
1935	William Bryan and Frances Stoermer, owners Stoermer Bros.
1932	William Bryan and Frances Stoermer, owners Stoermer Bros.
1929	Address not listed
Permits	
	Unless the Plumbing is done in strict accordance with City Ordinances, do not turn on the water. No.A
	PERMIT FÖR WATER SERVICE Austin Jaxas



Water service permit, 1930

Unless the Plumbing is done in strict accordance w		370 1010	
PERMIT FOR WATER	SERVICE	AUSTIN, TEXAS IN . 1494682	
M W B Stoermer	Address	608 641 (Real)	
Plumber Gissell	Size of Tap	Date / 2-14+3	
		W d	
Date of Connection 12-19-36	Foreman's Report	1118	
	ter service permit	t, 1936	
	RY SEWER SERVICE PE		
JIBI ZI	Austin, Texas	10025/	
Page dans d. of		Date 12/14/193	6
Received of Gissell Address 608 E. 41st	rear	Date	
		\$_12.00	_
Amount twelve dollars Builder or Owner W. B. Stoermer		Plumber	_
Lot _6 Block 6	Subdivision	Ideal_placePlat No. 82	
			7
Date of Connection 12/17/1936	s l		
Sew	ver service permit	t, 1936	
Wilford C. Wilde		608 E 41st St	
82 So 98.451	of 6	6 · ·	
	Ideal P	lace	
fra	ne gar		
5 6 6 45	4-13-54	600.00	
	owner		
•	A If Id has	Zoning Bd 4-12-54	-
_	_		
Е	Building permit, 1	, , , , , , , , , , , , , , , , , , , ,	•
A. F. Baker		608 East 41st. St	•
82 So 98.45 of	6-	6	
Ideal Place			
Frame add'n to	residence.		
77689 1	0-6-60	276.00	
owner		no	ne

CARPORT Variation BD of Adj.9-26-60 No setback from Peck Avenue.

Building permit, 1960

HEAVY RAIN BIG AIN TO TRAVIS FARMERS

"The heavy rain this week should mean a lot to the farmers of Travis county and I am sure that it will mean quite a bit of welding and farm implement repairing for us in the near future," says C. A. Stoermer of Stoermer Bros.

"Welding is a wonderful thing. It used to be that people with broken machinery went out and bought new parts, but modern welding processes make that unnecessary. Rapid strides have been made since we first started in the machine repair business. We now have a portable welding machine, which makes it very convenient for our customers."

Here Since 1922.

Stoermer Brothers opened their machine shop at 102 East Fifth street Sept. 15, 1922, and have been there ever since. Although most of the work has been confined to repairs in Austin, the firm has of late een doing much work in rural comnunitles of the county.

Probably the biggest rush in the firm's history was during the sub-freezing weather around the first of the year. At that time, hundreds of houses in Austin, particularly in the neighborhood of the university, suffered bursted pipes, and for a while it seemed that they would

Shop Practically Complete.

Thoy make all pumps, steal drums, and anything Their in the shop. Another large source of business is car frames and fenders.

The firm is now doing some light boller work for the Steck building on Congress avenue.

STOERMER BROS. MAKE GENERAL

One of Austin's best known machine shops is that of Stoermer Brothers, located at 102 East Fifth street, which has been in business here for more than six years.

Stoermer Brothers handle practically any type of repair work in metal. Repair or welding work on automobiles, tractors, gin machinery or any other automotive equipment is handled regularly by this concern. The firm rebores cylinders with the motor in chassis, fits pistons and pins, trues up crank and main bearing journals, faces valves and makes bushings of all types.

Broken steel frames of all types are repaired and work done on steam pumps, babbit boxes and bearings where welding is needed. Steel tanks, reservoirs and other similar equipment are handled by Stoermer Brothers.

The firm also has carbide and welding materials for sale at the shop and a full stock of cold drawn brass rede,s cold rolled steel and iron.

Machinists Save **Broken Auto Parts**

Stoermer Brothers, general machinists and welders at 102 East and repairing, stated Mr. Stoermer, Fifth street, consisting of C. A. and Fifth street, consisting of C. A. and W. B. Stoormer, have been operating a first class shop for the past Steady additions for facilitating four years and have built up a wonderful business. kinds of automotive parts and are tically complete, and most of this specialists in machinery repairing, machinery has been built right there pipe fitting and welding. motto is "save the pieces" and they will make them as good as new again.

MISS YOUNGER ANNOUNCES PLANS

The marriage of Miss Frances Younger, daughter of Mr. and Mrs. L. H. Younger of Austin, and Bryan Stoermer will take place at 9:30 o'clock Sunday morning, Oct. 6, in the parlors of the First Methodist church with the Rev. W. F. Bryan, pastor of the church, officiating. Only members of the two families and a few close friends will attend.

Miss Alice Younger, sister of the bride, will serve as maid of honor and Miss Maxine Fincher will be bridesmaid. W. H. Barrett will be at the organ and J. P. Barkley will sing the bridal solo.



The Austin Statesman (1921-1973), Oct 2, 1929; The Austin American (1914-1973), Mar 26, 1939