Feb 2022 Boil Water Notice

Austin City Council | February 15, 2022



Opening Comments

Greg Meszaros

Austin Water Director



Operations Overview

Rick Coronado, PE

Assistant Director, Operations



WHAT HAPPENED

- Crews were filling a basin with water to begin treatment
 - A mixture of water and processed solids was added to "seed" the basin
 - This is a high turbidity mixture that is typically stopped after a few hours
- "Seeding" was not stopped and continued for most of the night
- Alarms and sample tests indicating high turbidity were recorded



WHAT HAPPENED

- High turbidity water moved into water filters
- Filters removed particles and produced water that met regulatory standards until they clogged
- Multiple filters exceeded turbidity standards and entered the clearwells (underground storage tanks)



WHAT HAPPENED

- Supervisory staff were notified to assess situation
- Plant was shut down
- Production was ramped up at Davis and Handcox to keep water flowing to customers
- Water pressure and disinfection parameters remained consistent and within regulatory standards during this time



INITIAL ACTIONS UNDERWAY

- Meetings have been held with plant staff at each water treatment plant (Ullrich, Davis, Handcox)
- Examining process control protocols
- Examining training protocols
- Reviewing alarm, testing & notification procedures for improvements



Questions

