

KEYNOTES


- 1 Patch and repair existing standing seam roof
- 2 New standing seam metal roof to match existing, as required to remove skylights
- 3 Existing roof structure over porch
- 4 Existing awning, below
- 5 Existing chimney
- 6 Existing vent

ROOF PLAN NOTES

- 1. X

SHEET REFERENCES

- 1. Refer to G2.01 for wall types and partition types.
- 2. Refer to G2.50 for door and frame types and schedules.
- 3. Refer to G2.60 for window types and schedule.
- 4. Refer to G3.01 for finish schedule, appliance schedule, plumbing fixture schedule, bath accessory schedule.
- 5. Refer to A2.01 for lighting fixture legend and lighting dimensions.



SANDERS ARCHITECTURE

PROGRESS PRINT

NOT FOR REGULATORY
APPROVAL, PERMIT, OR
CONSTRUCTION

Copyright:
These drawings are property of the
architect and may not be reproduced,
distributed, published, or used in any way
without written consent of the architect.

Sooch Residence

706 Oakland Ave.,
Austin, Tx 78703

Historic Review

October 14, 2022

Drawn by: CG,MC,EK

Checked by: CS

Revisions:

Roof Plan.

A1.30