SUPPLEMENTAL INSTRUCTIONS **ENGINEER'S**

Distribution to:

ARCHITECT CONTRACTOR OWNER FIELD



TO (Architect): OWNER: (name, address) PROJECT: Colina West Austin, Texas 78701 200 E 6th ST Wall ENGINEER'S SUPPLEMENTAL INSTRUCTION NO: 2 DATE OF ISSUANCE: 8/13/16

ENGINEER: Engineering 360, Inc.

ENGINEER'S PROJECT NO: 15036

CONTRACT FOR: General Construction

The Work shall be carried out in accordance with the following supplemental instructions issued in accordance with the Contract Documents without change in Contract Sum or Contract Time. Prior to proceeding in accordance with these instructions, indicate your acceptance of these instructions for minor change to the Work as consistent with the Contract Documents and return a copy to the Engineer.

Description:

Demolish west exterior masonry wall at third and rebuild with CMU wall and reclaimed brick veneer.

- Shore third floor joists
- 8705480 Reinforce lower section wall between second floor level and third floor level
 - Reattach third floor joists to wall reinforcing
- Shore roof trusses
 - Demo existing masonry wall in sections
 - Install rebar dowels at top of existing masonry wall
 - Pressure inject upper 24" of existing masonry wall
- Construct minimum 12: deep tie beam at top of existing masonry wall, leaving sufficient reinforcing exposed to provide 40 diameter lap to next section of wall.
- 9 Construct 8" CMU wall for section
- 10) Attach roof trusses to new wall 11) Weatherproof section of wall


- 12) Repeat for each section of wall13) Waterproof and insulate CMU wall
- 14) Install windows15) Construct brick veneer

ATTACHMENTS: Sketches

BY: Engineer ISSUED: Contractor ACCEPTED:

POSTERED. 50110 ER AL FISHER

Page 1 of 1



TO INC.

BY:	SHEET NO:	JOB NO: 15030	PROJECT: 200
DATE: 8/13/16	OF:	6	EGEST WAY





BY:	SHEET NO:	JOB NO: 150	PROJECT: W
DATE: 8/3/16	OF:	6	EGT ST WALL

JOINT 12814 #4 VERTO 16"O,C. 8/13/16

"Bringing Structure to the World"

May 1, 2016

David Kahn Colina West Limited 804 Congress Avenue, Suite 300 Austin, Texas 78701

Re: Hannig Row Lease Spaces Vacated for Masonry Repairs 200 East 6th Street, Austin, Texas

Dear David,


As we discussed earlier today, it is our professional engineering opinion that several lease spaces will need to be vacated in the Hannig Row building to allow your Contractor, Blue & Associates, access to properly and safely install bracing and shoring and to perform necessary masonry wall repair work. After reviewing several variations of bracing and shoring, and reviewing several versions of sequencing the construction work, we have come to the conclusion that this work can only be performed with portions of lease spaces vacated. I've identified areas on plan sketches that your Contractor may need complete access to, and we will leave it with them to identify which of these areas they will need access to, and the schedule for that access.


Feel free to contact me with any questions.

MJ Structures, PLLC Richard A. Martin, PE


Principal

SOUNT MANUAL BURNESS OF THE SOUNT OF THE SOU





HANNIG ROW ROOF DECKS



OWNER

ARCHITECT

OLA 103 East Fifth Street. Ste 205 Austin, TX 78701 Contact: Megan Slattery 512.786.1101

Colina West 804 Congress Ave., Ste 300 Austin, TX 78701 Contact: Sean O'Brien 512.565.4477

HANNIG ROW CORE

PRELIMINARY REVIEW

SHEET INDEX

001.5 ROOF PLAN 002.5 WEST ELEVATION - BRAZOS STREET 003.5 EAST ELEVATION

5 VIEWS FROM BRAZOS STREET
5 VIEWS FROM 6TH STREET
5 AXONOMETRIC - WEST DECK
5 AXONOMETRIC - EAST DECK
5 SITE PHOTOS


005.5 007.5 009.5


APPROVED BY

HISTORIC LANDWARK COMMISSION 1:56 pm, Sep 24, 2014 for HLC Chair Layousk

Project numb
Date
Drawn by
Checked by number 09.18.14 14-007C scale COVER

9/18/2014 5:37:05 PM





1) OPTION 5 - VIEW 1 - FROM BRAZOS ST.

HANNIG ROW CORE

OLA 103 East Fifth Street. Ste 205 Austin, TX 78701 Contact: Megan Slattery 512.786.1101

Colina West 804 Congress Ave., Ste 300 Austin, TX 78701 Contact: Sean O'Brien 512.565.4477

ARCHITECT

OWNER

Project number
Date
Drawn by
Checked by **OPTION 5 - VIEWS FROM BRAZOS STREET** 14-007C 09.18.14 scale 005.5

PRELIMINARY REVIEW

2 OPTION 5 - VIEW 2 - FROM BRAZOS ST.

(1)

HISTORIC LANDWARK COMMISSION for HLC Chair

ARGA

OT

WRLL

3

RE. BUILT

9/18/2014 5:26:12 PM

1) OPTION 5 - VIEW 3 - CORNER

HANNIG ROW CORE

OLA 103 East Fifth Street. Ste 205 Austin, TX 78701 Contact: Megan Slattery 512.786.1101

Colina West 804 Congress Ave., Ste 300 Austin, TX 78701 Contact: Sean O'Brien 512.565.4477


ARCHITECT

OWNER

PRELIMINARY REVIEW

Drawn by Checked by Project i Date number VIEWS FROM 6TH STREET - OPTION 5 14-007C 09.18.14 scale 006.5

(2) VIEWS FROM 6TH STREET - OPTION 5



APPROVED BY
HISTORIC LANDMARK COMMISSION

1:56 pm, Sep 24, 2014

Ladousky

9/18/2014 5:26:25 PM

