

1194 E.M. Franklin Avenue
ca. 1955



OCCUPANCY HISTORY
1194 E.M. Franklin Avenue

City Directory Research, Austin History Center
By City Historic Preservation Office
January, 2017

1992

NOTE: The address is listed as 1194 Redwood Avenue, the former name for E.M. Franklin Avenue.

1985-86

Doris D. White, owner
Employed by the State of Texas
NOTE: The address is listed as 1194 Redwood Avenue, the former name for E.M. Franklin Avenue.

1981

Doris D. White, owner
Employed by AISD
NOTE: The address is listed as 1194 Redwood Avenue, the former name for E.M. Franklin Avenue.

1977

NOTE: The address is listed as 1194 Redwood Avenue, the former name for E.M. Franklin Avenue.

1973

Doris M. White, owner
Wrapper, Handy Andy Supermarket (multiple locations)
NOTE: The address is listed as 1194 Redwood Avenue, the former name for E.M. Franklin Avenue.

1968

Doris White, renter
Maid, Handy Andy Supermarket (multiple locations)
Also listed is Samuel W. White, Jr., a cook.
NOTE: The address is listed as 1194 Redwood Avenue, the former name for E.M. Franklin Avenue.

1965

Samuel and Doris M. White, owners
Samuel: Driver, Jack McKay Lumber Company, 1645 E. 6th Street.
Doris: Maid, Fashion Shop (multiple locations)
NOTE: The address is listed as 1194 Redwood Avenue, the former name for E.M. Franklin Avenue.

1963

Samuel and Doris M. White, owners
Driver, Jack McKay Lumber Company, 1645 E. 6th Street.
NOTE: The address is listed as 1194 Redwood Avenue, the former name for E.M. Franklin Avenue.

1962

Samuel and Doris White, owners
Laborer



WATER SERVICE PERMIT

Austin, Texas

E No. ³³⁷ 3792
INDEXED

Received of CLARENCE FLOURNOY Date 5-5-11
 Address: 1194 ~~REDACTED~~ AVE. E.M. Franklin Ave.
 Amount TWENTY & NO/100 20
 Plumber L.H. MEISKE Size of Tap 3/4"

Date of Connection	<u>7-6-55</u>	
Size of Tap Made	<u>3/4"</u>	
Size Service Made	<u>3/4"</u>	
Size Main Tapped	<u>6" CE</u>	
From Front Prop. Line to Curb Cock	<u>2.5'</u>	
From <u>NO</u> Prop. Line to Curb Cock	<u>8'</u>	
Location of Meter	<u>CEPB</u>	
Type of Box	<u>LAWN</u>	
Depth of Main in St.	<u>3'</u>	
Depth of Service Line	<u>2.5'</u>	
From Curb Cock to Tap on Main	<u>14'</u>	
Checked by Engr. Dept.	<u>8-19-55 HBR</u>	

No. Fittings	Size
	Curb Cock
	Elbow
	St. Elbow
	Bushing
	Reducer
<u>16</u>	Pipe <u>3/4" COP</u>
	Lead Comp.
<u>1</u>	Nipples <u>1" COP</u>
<u>1</u>	Union <u>1" COP</u>
	Plug
<u>1</u>	Fee <u>3/4" COP</u>
<u>1</u>	Stop <u>3/4" ANGLE</u>
<u>1</u>	Box <u>COP</u>
<u>1</u>	Lid
	Valves
	Job No. <u>W. 723-502</u>
	Req. No. <u>2088</u>

INDEXED

A laundry room was added in 2010.