HISTORIC LANDMARK COMMISSION MAY 21, 2018 PERMITS IN NATIONAL REGISTER HISTORIC DISTRICTS NRD-2018-0036

1629 PALMA PLAZA OLD WEST AUSTIN HISTORIC DISTRICT

PROPOSAL

Raise the ridgeline height and increase the pitch of a portion of the roof in a ca. 1935 house. The house is a contributing property in the Old West Austin Historic District.

PROJECT SPECIFICATIONS

The existing building is a cross-gabled, C-plan house with two front-facing gables. The house is 1½ and 2 stories high. The roof is covered in composition shingles. The building is clad in stucco, with wood-sash fixed and steel-sash casement windows.

The proposed project includes converting the attic in the central portion of the house to livable space by raising the roof ridgeline approximately half a story. Two skylights will be added behind the chimney. Submitted plans note that roofing material for the entire house may be asphalt shingles or standing-seam metal.

STANDARDS FOR REVIEW

The Secretary of the Interior's Standards for Rehabilitation are used to evaluate projects on contributing buildings in National Register historic districts. Applicable standards include:

- 2. The historic character of a property will be retained and preserved. The removal of distinctive materials or alteration of features, spaces, and spatial relationships that characterize a property will be avoided.
 Replacing the existing asphalt shingle roofing with standing-seam metal roofing would dramatically alter the historic character of the property and is not appropriate.
- 9. New additions, exterior alterations, or related new construction will not destroy historic materials, features, and spatial relationships that characterize the property. The new work will be differentiated from the old and will be compatible with the historic materials, features, size, scale and proportion, and massing to protect the integrity of the property and its environment.
 The proposed project alters the historic character of the property by changing the proportions of the central roof to the floor-to-ceiling height, modifying the massing of the house, and altering the relationship between the roof and the chimney. It will be somewhat differentiated from the historic-age design by the skylights located behind the chimney. The house's historic character will otherwise be retained and preserved.
- 10. New additions and adjacent or related new construction will be undertaken in such a manner that, if removed in the future, the essential form and integrity of the historic property and its environment would be unimpaired.


 While it would be difficult to reverse the proposed change, the roof could be rebuilt at its original height and slope.

The proposed project somewhat complies with the standards. The project does change the character of the property, but less obtrusively than a full second-story addition might.

STAFF RECOMMENDATION


Release the plans, contingent on use of asphalt shingles as roofing material (to match existing).





NOTIFICATIONS

CASE#: NRD-2018-0037 LOCATION: 1629 PALMA PLACE



This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.



1 " = 333 '

PROPERTY INFORMATION

Photos



North (primary) façade of 1629 Palma Plaza.



East elevation.

PERMIT I	FOR WA	ATER SERVICE AUSTIN, TEXAS $^{ m N}{}^{ m o}$ $^{7831}{}_{ m o}$
M		Address 1929 Palm Plaza ST
		Size of Tap 34 Date 5 /= 3
		Foreman's Report
Date of Connection.	5-1-	34
Size of Tap Made	3/4	<u> </u>
Size Service Made	3/	
Sise Main Tapped		3
From Front Prop. Li		
From Prop. Li	ine to Curb Cock	
From Prop. La Location of Meter.	north S	ida
Type of Box La	PA Bol	\$ 3 \ \frac{1}{2} \ \frac{1}{2
Depth of Main in St.	3.	Tutings Curb Cock Elboro St. Elboro Bushing Reducer Pipe X Valves Lad Stop Box
Depth of Service Lin		Fittings Curb C Elbow Elbow St. Elb Bushim Reduce Pipe Lead C Nipple Union Plug Tee Stop
From Curb Cock to 1		
Checked by Engr. De		
one and of this		
INDEXED	W.A.K	1/12/20
INDEXED ter service perm	W.L.L. it, 5/1/1934.	onen -
		nen
ter service perm		1000 polimo Plaga
ter service perm	it, 5/1/1934.	1000 polimo Plaga
ter service perm. G	it, 5/1/1934.	icker 1629 Palma Plaza
ter service perm. G	it, 5/1/1934.	icker 1629 Palma Plaza - 14-15 -
ter service perm. G	it, 5/1/1934.	icker 1629 Palma Plaza - 17-15 - Enfield E
ter service perm G 90c	it, 5/1/1934.	icker 1629 Palma Plaza - 14-15 Enfield E cco Addin. to side of res., 2nd. story
ter service perm G 90c	stuc	icker 1629 Palma Plaza - 15 - Enfield E cco Add'n. to side of res., 2nd. story 20565 - 10/8/40
ter service perm. 90c ilding permit for	stuc	icker 1629 Palma Plaza - 15 - Enfield E cco Add'n. to side of res., 2nd. story 20565 - 10/8/40 cco addition, 10/8/1940.


Frame servant quarters

32962 2-24-47


\$900.00

Building permit for "servant quarters," 2/24/1947.

Day labor



Primary façade of detached garage apartment, 2011.



1935 map, showing original house footprint. 1961 map, showing ca. 1940 addition to the east.