HISTORIC LANDMARK COMMISSION DECEMBER 17, 2018 DEMOLITION AND RELOCATION PERMITS HDP-2018-0645 5515 JIM HOGG AVENUE

PROPOSAL

Demolish a ca. 1945 house.

ARCHITECTURE

One-story, rectangular-plan, side-gabled, stone house with a central, partial-width, front-gabled independent porch on ornamental metal supports; single 1:1 fenestration; wood siding in the tympanum of the side gables.

RESEARCH

The house appears to have been built in 1945, according to building permits and water utility records, but the address does not appear in city directories until the edition of 1952. The first and longest-term owner and occupant was Orville R. Heryford, a native of Missouri who worked as a driver and equipment operator for the Austin Parks and Recreation Department for many years. After his wife Susie died in 1969, Orville continued to live in this house; he married his second wife in 1977; they lived here until around 1985.

STAFF COMMENTS

The house is beyond the bounds of any City survey to date.


Staff has evaluated this house for designation as a historic landmark and has determined that the house does not meet the criteria for landmark designation as set forth in City Code:

- a. **Architecture.** The house is a stone house, a rapidly-vanishing residential style in Austin. The house does not exhibit any architectural distinction apart from its stone exterior, but these houses are becoming more and more rare in the city's inventory of mid-20th century residential building types.
- b. **Historical association**. The house was owned by a man who was an equipment operator for the City Parks and Recreation Department for almost the entire time he lived in this house; there do not appear to be significant historical associations.
- c. **Archaeology**. The house was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
- d. **Community value**. The house does not possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the city, the neighborhood, or a particular demographic group.
- e. **Landscape feature**. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

STAFF RECOMMENDATION

Encourage rehabilitation and adaptive re-use, then relocation over demolition, but release the permit upon completion of a City of Austin Documentation Package, consisting of photographs of all elevations, a dimensioned sketch plan, and a narrative history, for archiving at the Austin History Center. The house does not meet the criteria for individual designation as a historic landmark.





NOTIFICATIONS

CASE#: HDP-2018-0645 5515 JIM HOGG AVENUE

This product is for informational purposes and may not have been prepared for or be suitable for legal, engineering, or surveying purposes. It does not represent an on-the-ground survey and represents only the approximate relative location of property boundaries.

1"=167'

This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.



5515 Jim Hogg Avenue ca. 1945





OCCUPANCY HISTORY 5515 Jim Hogg Avenue

City Directory Research, Austin History Center By City Historic Preservation Office December, 2018

1992	Betty K. Rutherford, renter No occupation listed NOTE: The directory indicates that Betty K. Rutherford was a new resident at this address.
1985-86	Vacant
1981	Orville R. and Rita Heryford, owners Retired
1977	Orville R. and Rita Heryford, owners Retired
1973	Orville R. Heryford, owner Equipment operator, City Parks and Recreation Department
1968	Orville R. and Susie B. Heryford, owners Driver, City Parks Department
1965	Orville R. and Susie B. Heryford, owners Driver, City Parks Department
1961	Orville R. and Susie B. Heryford, owners Driver, City Parks Department
1959	Orville R. and Susie B. Heryford, owners Driver, City Parks Division
1955	Orville R. and Susie B. Heryford, owners Custodian, City Parks Division
1952	Orville R. and Susie B. Heryford, owners Laborer
1949	The address is not listed in the directory. NOTE: Orville R. Heryford is listed as a repairman at the Texas School for the Deaf. He lived on the school campus.

BIOGRAPHICAL NOTES:

Orville R. and Susie B. Heryford/then Rita Heryford (ca. 1950 - ca. 1985)

Orville Heryford appears in the 1940 U.S. Census as a lodger in the home of June Kramer of Churdan, Greene County, Iowa. Orville Heryford was 30, had been born in Missouri, and was a farm laborer. He lived in Sheldon, Vernon County, Missouri in 1935. He was single.

The 1930 U.S. Census shows Orville Heryford as the 19-year old son of Thomas and Alice G. Heryford, who owned their home in Dover Township, Vernon County, Missouri. Thomas Heryford

was a 57-year old Missouri-born farmer. Alice G. Heryford, 49, had been born in Missouri, and had no occupation listed. Orville was the only child listed; he had no occupation shown.

Susie B. Heryford died in 1969. Orville Ray Heryford married Rita Uriegas in Williamson County, Texas in January, 1977.

MRS. SUSIE B. HERYFORD Mrs. Susie Belle Heryford, 73, of 5515 Jim Hogg, died in a local hospital Tuesday afternoon, She was a Baptist and had been a resident of Austin for 18 years Survivors include her husband. Orville Heryford Austin: one son Thomas R Summer Austin Of daughters, Mrs. Ormie Driver. and Mrs. Pearl Stephens, both of Minden, La.: two brothers. Gil Miller and Rube Miller, both of Minden, La.; grandchildren. Funeral will be at Sunday at Hyltin-Manor Funeral Home with Rev. Mildred Wicks officiating. Burial will Capital Memorial Gardens.

> Obituary of Susie Heryford Austin American, October 1, 1969

HERYFORD, Orville Ray, 78, of Austin died Thursday. Services 3 p.m. today at Angel Funeral Home.

Death notice for Orville Heryford Austin <u>American-Statesman</u>, April 14, 1989

- Howard	W.	Holland	•	5515	Jim	Hogg	Avenue
198			9	N.561 o.	8		

Broad Acres

Rock residence

27335 - 7/11/45

\$800,00

Owner

5

Building permit for the construction of this house (1945)

**	WATER SERVICE I	PERM	ΠT	e Periodological Periodological	No .	21097	Sec. z.
`	Received of HOWARD W. HOL		.,		Da	E74/2	-les
. 2	Address 5515 TINI HO	66	A	VE	·		
9	Amount TWO + 50/100		·			\$2	50
& EWE	Plumber BURLESON	1 	· <u>···</u> ···		Size of	Tap 1/2"	************
COPPERON COPPERON	Date of Connection 1-16-08 Size of Tap Made 3/4 Size Service Made 3/4 Size Main Tapped 2 C. I From Front Prop. Line to Curb Cock 30 From So Prop. Line to Curb Cock 388 Location of Meter 24/5/1/2 P. L.	F Size		Coppet Kabing	W.Y.S. Conc.	20027 20027 2 K	3.23-502
CHANGED TO	Type of Box Depth of Main in St. 20" Depth of Service Line 20 From Curb Cock to Tap on Main 22.8" Checked by Engr. Dept. 22.2.4.5	- Fift	Elbow St. Elbow	Bushing / Reduces /	Lead Comp	Sep 7	Job No. K Rea. No.

Water service permit for this address (1945)

			A CONTRACT
Rept No./695	Application	for Sewer Connection No	23435
€£.	Kust	Austin, Texas,	14-51
To the Superintend	ent of Sanitary Sewer 1	Division, City of Austin, Texas.	•
Sir:— I berebrimake an	pliostionator sewer com	ection and instructions on premises own	ed by
$(\wedge \otimes \omega)$	nagues	5.38 J. 8 . 6 ()	Street,
further described as	1	Block Outlot Div	ition
subdivision (1800)	and a	Play 98, which is to be used as a	3 6/2
In this place there are I agree to pay the <i>Cit</i> i	to be installed fixty of Austin, the regular of	ures. Plumbing Permit No.	
7	1_	6 almans	
Depth at Prop. Line)	Respectfully, Try	
Stab-Out: Connected	-Sol Nec	Hunes	
Date 5	(Location)	62	
. D	111		150
By <u> </u>	awish !	1+ +6	1-08.
NOTE: Connection In	struction (mm M	Anten
mum 1	aft das	dur //	A- 2000
	- //	0	e de la companya della companya della companya de la companya della companya dell
5	Sewer connection app	plication for this address (1951)	
OWNER Orvi	lle Herford	ADDRESS 5515 Jim Hogg	Avenue
PLAT 198	LOT	8	BLK 9
CUDDING CION	Broadacres		
SUBDIVISION	Diososcies		
OCCUPANCY	Kitchen		
		OWNERS	
BLD PERMIT #	97695 DATE 1	1-3-65 ESTIMATE 958.	00
•			
CONTRACTOR	House Clinic	NO. OF FIXTURE	<u>s 1 </u>
WATER TAP REC	#	SEWER TAP REC #	•
MAJER TAI REC		DENER THE REC #	
	Frame Addit	ion To Residence (Kitchen	.)
		ነበበ ቁለ የተ	
Building permit	to Orville Heryford fo	i00 sq.ft. or the construction of a kitchen add	dition (1965)