HISTORIC LANDMARK COMMISSION

PERMITS IN NATIONAL REGISTER HISTORIC DISTRICTS OCTOBER 25, 2021 HR-2021-126308

TRAVIS HEIGHTS-FAIRVIEW PARK NATIONAL REGISTER HISTORIC DISTRICT 1505 TRAVIS HEIGHTS BOULEVARD

PROPOSAL

Partially demolish contributing residence to replace all siding, windows, railings, and roof. Convert attic into second floor and crawlspace into basement.

PROJECT SPECIFICATIONS

- 1) Convert attic to second floor: modify roofline, increasing pitch and replacing existing material with metal roof. Add shed-roofed stucco dormers to secondary elevations to create habitable attic space. Add rear balcony with metal guardrails, creating a flat-roofed rear porch below.
- 2) Partially demolish and remodel front porch: replace original wood handrails at porch with metal safety railings. Replace original box columns and masonry piers with painted metal posts. Remove original porch gable and replace with metal shed roof. Add built-in steel planters in front of porch.
- 3) Remove and replace original horizontal wood siding with fiber cement board-and-batten siding.
- 4) Remove and replace original 1:1 wood windows and screens with undivided fixed and casement windows.
- 5) Remove original wood front door and replace with fully glazed double doors.
- 6) Convert crawlspace into basement: construct rear deck and access stairs. Construct basement-level patio. The proposed basement walk-out is stucco, with sliding glass doors and horizontal metal handrails at stairs.

ARCHITECTURE

One-story Craftsman bungalow with gabled roof, horizontal wood siding, mulled 1:1 wood windows, and a full-width porch supported by boxed columns on brick piers. Intact decorative details include deep eaves with exposed rafter tails and triangular knee braces at gable ends.

RESEARCH

The house at 1505 Travis Heights Boulevard was built for Fred and Julia C. Penick before 1924. Fred Penick was a bank teller, cashier, and clerk at the American National Bank for most of his career. Julia Penick, active in various community-building and youth enrichment programs, ran a summer camp with her older children. Penick had previously been employed as a camp employee at Yosemite National Park.

DESIGN STANDARDS

The City of Austin's <u>Historic Design Standards</u> (March 2021) are based on the Secretary of the Interior's Standards for Rehabilitation and are used to evaluate projects in National Register districts. The following standards apply to the proposed project:

Repair and alterations

1. General standards

The proposed project removes intact historic material from the building's exterior without attempting repair of deteriorated elements. Replacement elements do not look the same and are not made of the same materials as the original elements.

2. Foundations

The original building skirt, steps, and masonry cheek walls appear to have been removed without Historic Preservation Office review in 2020 during express-permitted foundation repair work. Instead of rebuilding these elements from photographic elements, per design standards, the proposed project obscures the foundation at the main façade with incompatible steel planters.

3. Roofs

While a shingle roof is the most appropriate option for replacement material, the proposed project's metal roof is allowed by the design standards. However, the proposed project alters roof configuration and pitch and removes historic decorative detailing. The shed-roofed dormers appear out of proportion with the main façade.

4. Exterior walls and trim

The proposed project removes all historic-age horizontal wood siding and trim, replacing historic elements with vertical board-and-batten fiber cement siding and minimal trim of different profiles, without considering repair.

5. Windows, doors, and screens

The proposed project removes all historic-age windows, doors, screens, and trim, without consideration of repair. The proposed replacement windows do not match the historic windows in configuration, size, profile, material, details, or finish. The proposed front door replacement enlarges the existing opening and removes the current door in favor of fully-glazed double doors.

6. Porches

The proposed project replaces historic-age porch piers, columns, railings, skirting, and trim with elements that are not compatible in style or materials. Additionally, it removes the original gable roof—including character-defining decorative details—replaces it with an incompatible shed roof, altering the porch's original dimensions and height.

Summary

The project does not meet the applicable standards.

PROPERTY EVALUATION

The property contributes to the Travis Heights-Fairview Park National Register Historic District.

Designation Criteria—Historic Landmark


- 1) The building is more than 50 years old.
- 2) The building appears to retain high integrity.
- 3) Properties must meet two criteria for landmark designation (LDC §25-2-352). Staff has evaluated the property and determined that it does not meet two criteria:
 - a. Architecture. The building is a good example of the Craftsman style.
 - b. Historical association. The property does not appear to have significant historical associations.
 - c. Archaeology. The property was not evaluated for its potential to yield significant data concerning the human history or prehistory of the region.
 - d. Community value. The property does not possess a unique location, physical characteristic, or significant feature that contributes to the character, image, or cultural identity of the city, the neighborhood, or a particular demographic group.
 - e. Landscape feature. The property is not a significant natural or designed landscape with artistic, aesthetic, cultural, or historical value to the city.

COMMITTEE FEEDBACK

Retain as many character-defining features as possible, including siding, gable vents, wood windows, piers, columns, and railings. Consider alternatives to raised roof ridge. Push back addition as much as possible from front of house.

STAFF RECOMMENDATION

Release the demolition permit upon completion of a City of Austin Documentation Package. Comment on and release the plans, encouraging the applicant to implement Committee feedback to the greatest extent possible.



1"=292'

This product has been produced by CTM for the sole purpose of geographic reference. No warranty is made by the City of Austin regarding specific accuracy or completeness.

Photos



Google Street View, 2020







Application, 2021





Zillow.com, undated

	ncy History ectory Research, August 2021	
1959	Fred M. and Julia Penick, owners Assistant cashier, American National Bank	
1957	Fred M. and Julia Penick, owners Assistant cashier, American National Bank	
1955	Fred M. and Julia Penick, owners Assistant cashier, American National Bank	
1952	Fred M. and Julia Penick, owners Assistant cashier, The American National Bank Examiner, State Highway Department	
1949	Fred M. and Julia Penick, owners Assistant cashier, The American National Bank Examiner, State Highway Department	
1947	7 Fred M. and Julia Penick, owners Assistant cashier, American National Bank Saleswoman, Mathis Flower Shop	
1944	Philip H. Sharnquist, renter Fred M. and Julia Penick, owners Assistant cashier, American National Bank	
1941	Fred M. and Julia Penick, owners Teller, American National Bank	
1939	Fred M. and Julia C. Penick, owners Teller, American National Bank Joyce Penick, renter Student, University of Texas	
1937	Fred M. and Julia C. Penick, owners Teller, American National Bank Manager, cafeteria, Fulmore School	
1935	Fred M. and Julia C. Penick, owners Teller, American National Bank Manager, cafeteria, Fulmore School	
1932	Fred M. and Julia C. Penick, owners Teller, American National Bank Manager cafeteria Fulmore School	
1929	Fred M. and Julia Penick, owners Teller, American National Bank	

Fred M. and Julia Penick, owners Teller, American National Bank

Fred M. and Julia Penick, owners Clerk, American National Bank

Address not listed

1927

1924

1922

PENICK CAMP WILL OPEN JUNE 7

Camp Open House

Open house will be observed Sunday at Camp Ah Wahnee, camp exclusively for younger girls, near Dripping Springs. Mrs. Fred Penick and Miss Annie Jen Felder are co-directors of the camp, Mrs. Penick, who has had six years experience with Twin Fire camp in Yosemite National park, will have charge of all crafts work. Mrs. Chester Koock will direct the camp, Mrs. Pensetra Stubbs, who will fire programs assisted by Miss Jean Hildreth of Dallas.

Miss Berta Stubbs, who will leach horseback riding and nature, is an interesting member of the staff, since she was reared in the staff of toustanding counselors. Also stubbs will be incharge of training the children in charge of training the children in charge of training and Mrs. M. Hol

Camp Ah-Wah-Nee, exclusive camp for children at Dripping Springs, will open its second season

at the camp.

Mrs. Penick and Miss Felder will be assisted in hostess duties at the camp on Sunday by the following girls:

Jo Anne. Francis, Nancy Francis, Francis Evelyn Schneider, Ann Boyd, Virginia Davis, Martha Ann Kelly, Patsy and Kathryn Hughes, life.

The Austin Statesman (1921-1973); Jan 13, 1943 and The Austin American (1914-1973); Jun 11, 1939

Bank Re-elects Its Officials

Officials of the American National bank were re-elected at the meeting of stockholders held Tuesday afternoon.

meeting of stockholders neid Tucsday, afternoon.

Two new assistant cashiers were named, Miss Margaret Macken and Fred M. Penick.

Directors are A. C. Bull, W. S. Drake, Jr., J. E. Harrison, Theo P. Meyer, Tom Miller, J. R. Nichols, V. P. Patterson, Ben. H. Powell, A. B. Spires, E. R. L. Wroe and H. A. Wroe.

Officers are as follows: H. A. Wroe, chairman of the board; E. R. L. Wroe, president; V. P. Patterson, vice-president; V. P. Patterson, vice-president and trust officer; A. C. Bull, vice-president; L. D. Williams, cashier; W. W. Shropshire, W. R. Long, Jr., Ben M. Brigham, J. H. Meyers, Jr., Miss Margaret Macken and Fred M. Penick, assistant cashier; and E. C. Duke, assistant trust officer.

PENICK, Fred M., 83, of Austin, died Thursday. Services 4 p.m. Saturday at Wilke-Clay Funeral Home. Survivors: wife, Julia C. Penick of Austin; daughters, Mrs. Chester (Joyce) Wheless of Corpus Christi, Mrs. Frank (Jean) Spiller of Austin; son, Fred M. Penick Jr. of Lockhart; brothers, Tinsley Penick, Tom Penick, Harvey Penick, all of Austin; seven grandchildren; four greatgrandchildren.

Permits

Connecting Charge \$ 12 00	Unless the Plumbing is done in strict accordance with City of PERMIT FOR WATER SE	NO OOCO
Application for Sewer Connection.	м	Address 1505 Travis Hights Blud 1. Size of Tap 3/4" Date 5/12/3/
Austin, Texas, 193	Foren	man's Report
City of Austin, Texas. Sir:- 1 hereby make application for sewer connection and instructions on premises.	Date of Connection 5/12/3/ Size of Tap Made. 3/4." Size Service Made. 3/4."	
owned to Lid Sinich at 1505 Lagina Blod Street	Sise Main Tapped 2	
which place is to be used as a Pus	Location of Meter II Ins. ide. C. 41.6. Type of Box. La. k.	Cock
In this place there are to be installed fixtures. I agree to pay the City Sewer Department the regular ordinance charge.	Depth of Main in St. Depth of Service Line. From Curb Cock to Tap on Main. R.A. ma.in.	Curb Elboar St. El St. El Bushi Pipe Unipol Plugo Plugo Box Lid
Respectfully, Mud Shuuf	5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Foreman's Signature A.L. Jacobson

Sewer Connection Permit and Water Service Permit, 1931

Fred M. Penick

1505 Travis Blvd

31

10

T ravis Hts.

Re-roof Res.

21347 - 2-28-41

Building Permit, 1941