



**PHOTOGRAPH 1**

**Direction:**  
Facing North

**Description:**  
View of the storm drain outfall construction/Shoal Creek stabilization site at the intersection of 34<sup>th</sup> Street and Shoal Creek Boulevard. The yellow arrows indicate the approximate location where the contractor will use the park for temporary access during construction. The sidewalk will be replaced upon project completion.



**PHOTOGRAPH 2**

**Direction:**  
Facing west

**Description:**  
View of 34<sup>th</sup> Street at the Shoal Creek Boulevard intersection. For reference, the yellow arrow points to the same large boulder shown in the background of Photograph 1.



**PHOTOGRAPH 3**

**Direction:**  
Facing north

**Description:**  
View of the damaged wing-wall and eroded bank within the Watershed Protection Department drainage easement at the corner of Shoal Creek Boulevard and 34<sup>th</sup> Street.



**PHOTOGRAPH 4**

**Direction:**  
Facing south

**Description:**  
Reverse view of the wing-wall and eroded bank shown in Photograph 3. The Shoal Creek Trail is shown in the background.