Existing Creek Erosion

The bed and banks of Shoal Creek are actively eroding due to lack of vegetation, urbanized stream flow, and pedestrian traffic.

Legend

See Creek Restoration Map



8 Photograph Location



Photo Simulation Location

shoal creek restoration 15th © 28th streets



