


AUPPERTLE COMPANY
Engineering, Planning & Development Services
10088 Creekside Drive, Austin, Texas 78734 512.329.8241

INSTRUMENT: BSA
APPROVED:
SCALE: NTS
7101 Greenbush Dr.
DATE: May 15, 2014
SHEET: 3 of 4



- [illegible]

The drawing shows a rectangular plate with diagonal hatching. On the left side, there is a rectangular area with a cross-hatched pattern. This area is connected to a larger rectangular section on the left by a horizontal strip. A dashed line runs vertically through the center of the plate, indicating a fold or cut line. There are eight circular holes: two on the left side (one in the cross-hatched area, one in the horizontal strip), and six on the right side (two in the top section, two in the bottom section, and two in the middle section).

[illegible]ELEVATION FROM UPSTREAM