HISTORIC LANDMARK COMMISSION PERMITS IN NATIONAL REGISTER HISTORIC DISTRICTS NOVEMBER 16, 2015 NRD-2015-0119 Clarksville National Register District

1810 W 10th Street

PROPOSAL

Demolish the building

ARCHITECTURE

The house is a circa 1932 one story frame vernacular residential structure with craftsman detailing. The building has horizontal hap wood siding double hung wood windows, a standing seam metal roof and a front porch with stick detailing in the gable work.

PROJECT SPECIFICATIONS


Demolish the contributing building the Clarksville National Register Historic District.

HISTORY

The 1932 vernacular craftsman home was built for and lived in by John Johnson and his wife Lillie for almost 30 years. John was a laborer who worked with the City Street and Bridge Division. Once the Johnsons moved out of the house, a series of renters who often did not have an occupation listed lived in the house.

STAFF RECOMMENDATION

While the building is a nice example of a vernacular style residential structure commonly found in Clarksville and it retains much of its architectural integrity, the occupational history researched on this property did not turn up any historical or cultural associations with this property. While Staff encourages the applicant to reuse the structure or consider relocation, we cannot recommend imitating historic zoning on this property as it does not meant the criteria for Historic Landmark designation. Staff does recommend a postponement to the December 14, 2015 meeting to allow the neighborhood and staff time to discuss alternatives to demolition.



$1806 \; W \; 10^{th} \; Street$

Circa 1932



OCCUPANCY HISTORY

City Directory Research, Austin History Center By City Historic Preservation Office November, 2015

1992	Vacant
1985-86	Terry Floyd, renter No occupation
1981	Vacant
1977	Mike Bonilla, renter No occupation
1973	Mitchel Valery, renter Employer at W.O Harper Plumbing
1968	Mrs. Ola M. Robinson, renter No occupation
1962	Rayond Rodriquez, renter Roofer at Capital Roofing

1959	John and Mable Johnson, owner No Occupation
1955	John and Mable Johnson, owner No Occupation
1952	John and Mable Johnson, owner No Occupation
1949	John and Mable Johnson, owner No Occupation
1947	John and Lillie Johnson, owner No Occupation
1944-45	John and Lillie Johnson, owner Laborer
1941	John and Lillie Johnson, owner Laborer with City Street and Bridge Division
1939	John and Lillie Johnson, owner Laborer
1937	John and Lillie Johnson, owner Laborer
1935	John and Lillie Johnson, owner Laborer
1932-33	John and Lillie Johnson, owner Laborer

Unless-the Plumbing is done in strict accordance	with City Ordinances, do not	turn on the water.	Sev. 9I
PERMIT FOR WATE	R SERVICE	AUSTIN, TEXAS N	? 1114 97
M. Rosil Johnson	Address./.a	906W/0	th
Plumber	Size of Tap		ite 4-7-32
Ÿ	^		
11/11/2	Foreman's Report	1 1 1	,
Date of Connection.	7711	27 , 76	
Size of Tap Made Size Service Made		3 0 5	7,1
Size Main Tapped	Sign In You	3 3	
From Front Prop. Line to Curb Cock.	1 / 2	12 6	
From Prop. Line to Curb Cock.	4 11 11 11 11	1 1 100 1	
Type of Box.	3041	1876 Par 14	N
Death of Main in St	Fittings Curb Cock Elbow St. Elbow Bushing		No.
Depth of Service Line.	Fittings Curb C Elbow St. Elbow Bushing	Pipe Irela Nipp Unios Tree	Box Lid Values Values Req.iN
From Curb Cock to Tap on Main. 20	S 01	N M - (-)	
Checked by Engr. Dept. 5-7-33 30	7. Coreman's Signature	13	
INDEXED		Bury	and the same of th
78			1
			•
1 '		,	
			4
-			
			
`. •	.561	>	. :
		. //	•
79 0	1 150M		
			
		27	
4	1,4,81	081	
fy	'	- /	
//			
V		J	