


# Austin Community College - Rio Grand Campus

Application for Certificate of Appropriateness  
for a City Landmark or Local Historic District



ACC Rio Grande Campus

## Color Photographs



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING | NOVEMBER 9TH 2016  
E1 | EXTERIOR: WEST ELEVATION




AUSTIN COMMUNITY COLLEGE, MAIN BUILDING | NOVEMBER 9TH 2016  
E2 | EXTERIOR: EAST ELEVATION



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING | NOVEMBER 9TH 2016  
E3 | EXTERIOR: SOUTH ELEVATION



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING |  
NOVEMBER 9TH 2016  
E4 | EXTERIOR: NORTH ELEVATION



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING |  
NOVEMBER 9TH 2016  
E5 | EXTERIOR: TYPICAL BASEMENT WINDOW



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING |  
NOVEMBER 9TH 2016  
E6 | EXTERIOR: TYPICAL MASONRY REPAIR



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING | NOVEMBER 9TH 2016  
E7 | EXTERIOR: SOUTHEAST CORNER



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING | NOVEMBER 9TH 2016  
E8 | EXTERIOR: EAST ENTRANCE



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING | NOVEMBER 9TH 2016  
E9 | EXTERIOR: EAST ENTRANCE



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING | NOVEMBER 9TH 2016  
E10 | EXTERIOR: 1925 THIRD FLOOR GABLE




AUSTIN COMMUNITY COLLEGE, MAIN BUILDING | NOVEMBER 9TH 2016  
E11 | EXTERIOR: WEST ENTRANCE



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING | NOVEMBER 9TH 2016  
E12 | EXTERIOR: TYPICAL GROUND FLOOR WINDOWS



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING |  
NOVEMBER 9TH 2016  
E13 | EXTERIOR: SOUTH COURTYARD



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING |  
NOVEMBER 9TH 2016  
E14 | EXTERIOR: SOUTH COURTYARD



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING |  
NOVEMBER 9TH 2016  
E15 | EXTERIOR: NORTH COURTYARD



AUSTIN COMMUNITY COLLEGE, MAIN BUILDING |  
NOVEMBER 9TH 2016  
E16 | EXTERIOR: NORTH COURTYARD