



1/2" AESTHETIC PERIMETER





HOUSE IS ON BLOCKS AND TREE POST





UNDER HOUSE/ NOT BUILT PROPERLY






SEPARATION





SEPARATION




FOUNDATION IS UNSTABLE/ CRACKS IN WALLS





SIDING IS POPPING OUT





OLD WINDOWS/ CRACKS IN WALL





ROTTEN ROOF/ LEAKS





ROTTEN WOOD/ NO INSULATION





POSSIBLE WATER DAMAGE





OLD SHED / NOT STABLE





OLD ROOFING W/ LEAKS





OLD SHED/ ROTTEN ROOF





BEAMS/ ROOF NOT STURDY