

4409 Avenue C Austin, TX 78751

Homeowner: Erika Bsumek

Scope of Work: There are a total of 11 windows being replaced, with the room is three sided wall; the south wall will have 1 picture window and 3 hung windows. The north wall will have 1 picture window and 3 hung windows. The east wall will have 1 picture window and two hung windows. Please see attached illustrated pics. The current windows are made of aluminum metal. They were installed years ago when the back was closed and roomed up. The new replacement windows will only alter this back room that is not visible to the front of the home. There are no grids being installed. The colors are white interior and white exterior. We are installing 3 picture windows in the corners, and installing 8 single hung windows. They will be vinyl windows, double pane glass. These updates will only alter the look of this back room of the house facing the backyard. There is no visibility to the front of the house.



South wall

Single
Hung
Window

Single
Hung
Window

Single
Hung
Window

Picture
Window







North wall

Picture
Window

Single
Hung
Window

Single
Hung
Window



Metal windows
Being replaced