



Figure 1 – Cracks in Plaster



Figure 2 – Cracks in Plaster



Figure 3 – Tilted Cabinets



Figure 4 – Cracks in Floor





Figure 5 – Cracks in Tile



Figure 6 – Balcony/Porch



Figure 7 – Interior Wall



Figure 8 – Garage Walls





Figure 9 – Fireplace with Deteriorating Brick Liner and Heavy Creosote



Figure 10 – Antiquated Plumbing Causing Water Pressure and Clog Issues