


CLAYTON KORTE



SIDING IS DECAYED, WATER-DAMAGED, AND LOOSE (PARTICULARLY ON THE NORTH AND EAST SIDES).





FOUNDATION IS CRACKED ON A FOUR WAY AXIS. HOMEOWNERS HAVE NEVER PARKED A CAR ON IT SINCE PURCHASING THE HOUSE IN 2009.



CLAYTON EXISTING GARAGE - FOUNDATION CRACKS



SUPPLEMENTAL PHOTOS FOR HISTORIC REVIEW | FOWLER RESIDENCE - 2109 KENWOOD AVENUE



BROKEN ROTTEN DOORS - INOPERABLE DUE TO SHIFTED FOUNDATION AND DISREPAIR. RIGHT HAND (SOUTH DOOR) HAS NEVER BEEN OPENED SINCE THE HOME WAS PURCHASED IN 2009.



THE GARAGE IS OUT OF PLUMB ON THE NORTH-SOUTH AXIS, ESPECIALLY THE CURBING ALONG THE SOUTH SIDE. THIS IS APPARENT IN THE BROKEN FASCIA AND CLADDING AROUND THE GARAGE DOORS AND IN THE FACT THAT THE GARAGE DOORS CANNOT BE OPENED.



VINES ARE GROWING THROUGH THE ROOF AND WALLS AND THE ROOF LEAKS.



CLAYTON KORTE

EXISTING GARAGE - DOOR AND VINES