HLC DESIGN REVIEW



PARQUE ZARAGOZA NEIGHBORHOOD PARK PARQUE ZARAGOZA NEIGHBORHOOD PARK


REHABILITATION PROJECT

June 14, 2022





HLC DESIGN REVIEW | June 14, 2022 |




HLC DESIGN REVIEW | June 14, 2022 2




- 1931 Zaragosa Park (now Zaragoza Park) established, with baseball field and picnic and celebration areas
- 1933 Swimming pool constructed at the park, used for summer swim season
- 1941 Shelter house, with dressing and toilet facilities for pool users, built by the NYA
- I971 Planning for renovation of the bathhouse was begun
- 1975 Bid awarded for renovation of the bathhouse, including installation of air conditioning
- 1996 New Parque Zaragoza Recreation Center building dedicated at the park
- 2022 Parque Zaragoza listed on National Register, with bathhouse as a contributing building



HLC DESIGN REVIEW | June 14, 2022 3









Scope Summary

- Rehabilitation of building
- Programmatic priority for swimming bathhouse use
- Provide code compliant restroom and shower facilities
- Provide limited air conditioning, at lifeguard/first aid office

Retain existing accessible parking

Provide accessible route from parking to entrance

Enhance connection to the park

Limited civil and landscape work

Replace electrical systems, improve lighting

Window and door repairs, roof replacement, masonry cleaning

LEED Silver sustainable building certification

HLC DESIGN REVIEW | June 14, 2022 8














DEMOLITION GENERAL NOTES

- Building has asbestos-containing materials. Contractor to refer to included asbestos abatement specifications prior to conducting any work. Coordinate all demolition with specifications and report. Follow all local, state and federal regulations when removing any asbestos-containing materials.
- Architect has no knowledge of other asbestos or other hazardous materials on jobsite. Contractor shall immediately isolate the affected area if other asbestos or other hazardous materials are discovered during construction. Notify Owner for further instruction before proceeding with other work.
- Demolition plans are provided to give a general indication of the scope of the work. Confirm exact extent of the demolition on site.
- 4. Items to be removed, relocated or salvaged are shown with dashed line and are as listed in the keyed demolition notes. All other items are intended to remain in place. Do not damage items, surfaces, finishes and building elements to remain.
- 5. Remove only non-load bearing construction and partitions. Contractor to verify, prior to removal, that no structural components, i.e. bearing walls, bears, headers, etc. supporting floor, roof or ceiling joists are designated for removal. Contact the Architect prior to removal of any construction in question or deviating from the design intent.
- All service locations to be confirmed prior to the commencement of work. Maintain existing utilities to remain in service and protect against damage during demolition operations.
 Protect all existing finishes shown to remain during demolition to
- Protect all existing finishes shown to remain during demolition to prevent damage. Any damage sustained during demolition shall be repaired or replaced by Contractor to match existing conditions.
- Protect all finishes uncovered beneath demolished wall coverings, or other removed elements. Do not damange finishes uncovered in the demolition work.
 All demolition activities shall be performed so as to produce minimal
- 9. All demolition activities shall be performed so as to produce minimal disturbance to existing facility and occupants. Maintain separation between areas undergoing demolition work and surrounding occupied areas by providing temporary barriers to prevent dust mioration. Minimize excessive and protoneed noise levels and dust.
- Comply with local jurisdiction requirements for demolition work.
 Where Contractor is designated to make removals, disposition of materials is the sole responsibility of the Contractor.
- materials is the sole responsibility of the Contractor.12. Upon completion of demolition activities, clean the entire area of demolition to a tidy, uniform condition, removing all debris, dust
- partitions and associated materials used during the demolition. Clear all areas impacted by the demolition, including but not limited to, adjacent occupied areas and areas not within the scope of work.

DEMOLITION KEYED NOTES

1. Remove existing concrete flatwork as shown

- 2. Remove existing concrete planter borders.
- 5. 6.

7.



12/17/2015

Parque Zaragoza Neighborhood Park: ADA Transition Plan Items

This property is listed in or eligible for listing in the National Register of Historic Places.

AUSTIN PARKS RECREATION

Legend

Assembly Areas Door/Gate

Drinking Fountain

Parking Lot ADA Marker

Other Features

Parking Lots

Picnic Tables

Playgrounds **Protruding Objects**

Restrooms

Baseball

Basketball

Volleyball

Swimming Pools O Trail ADA Routes City of Austin Parks

This product is for informational purposes and may not have been propared for or be unitable for legal, engineering, or univeying purposes. It does not represent an on-the-ground survey and represents only the approximate relative location of property boundaries. This product has been produced by the Parks and Recreation Department for the sole survey of the survey his deformed

for the sole purpose of geographic reference. No warranty is made by the City of Austin ing specific accuracy or completen

100

50

Feet

O

.

6 P

A

œ,

•

A

€

R

(I)


Parque Zaragoza Neighborhood Park

2608 Gonzales St. Austin, Texas 78702

Inspection Date:


*Item Number includes photo


ITEM NO.	GIS ID	BARRIER	CODE HEADING	VIOLATION	RECOMMENDED ACTION	QUANTITY	BUDGETED	PRIORITY LEVEL
			2012 Texas Accessibility				COST	
			Standards					
16*	Other Features: 175	Door	307.2 Protruding Objects	There are 4 cased openings that are	Reconstruct the doorway.	4	\$ 10,000	1
				protruding objects.				
19	Door Gate: 1066	Door	404.2.7 Door & Gate	The door does not have compliant	Replace with compliant hardware.	1	\$ 300	1
			Hardware	hardware.				
27*	Protruding Object:	Mounted Object	307.2 Protruding Objects	The frame within the doorway is a	Relocate out of circulation path, install	1	\$ 300	1
	236			protruding object.	where the lowest edge is at 27"			
					maximum, or add cane detection.			






HLC DESIGN REVIEW | June 14, 2022 10









NOVEMBER 4, 2021 PARQUE ZARAGOZA





HLC DESIGN REVIEW | June 14, 2022 13








EXAMPLES OF DECORATIVE SCREEN INFILI

Parque Zaragoza Restroom Rehabilitation



HLC DESIGN REVIEW | June 14, 2022 16

Thank You



